
Agilent 86030A Lightwave Component
Analyzer System



Agilent Technologies

© Copyright Agilent Technologies, Inc. 2000, 2002 All Rights Reserved. Reproduction, adaptation, or translation without prior written permission is prohibited, except as allowed under copyright laws.

Agilent Technologies Part No. 86030-90023
Printed in USA
March 2002

Agilent Technologies, Inc.
Lightwave Division
3910 Brickway Boulevard
Santa Rosa, CA 95403, USA

Notice.

The information contained in this document is subject to change without notice. Companies, names, and data used in examples herein are fictitious unless otherwise noted. Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Restricted Rights Legend.

Use, duplication, or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

Warranty.

This Agilent Technologies instrument product is warranted against defects in material and workmanship for a period of one year from date of shipment. During the warranty period, Agilent Technologies Company will, at its option, either repair or replace products which prove to be defective. For warranty service or repair, this product must be returned to a service facility designated by Agilent Technologies. Buyer shall prepay shipping charges to Agilent Technologies and Agilent Technologies shall pay shipping charges to return the product to Buyer. However, Buyer shall pay all shipping charges, duties, and taxes for products returned to Agilent Technologies from another country.

Agilent Technologies warrants that its software and firmware designated by Agilent Technologies for use with an instrument will execute its programming instructions when properly installed on that instrument. Agilent Technologies does not warrant that the operation of the instrument, or software, or firmware will be uninterrupted or error-free.

Limitation of Warranty.

The foregoing warranty shall not apply to defects resulting from improper or inadequate maintenance by Buyer, Buyer-supplied software or interfacing, unauthorized modification or misuse, operation outside of the environmental specifications for the product, or improper site preparation or maintenance.

No other warranty is expressed or implied. Agilent Technologies specifically disclaims the implied warranties of merchantability and fitness for a particular purpose.

Exclusive Remedies.

The remedies provided herein are buyer's sole and exclusive remedies. Agilent Technologies shall not be liable for any direct, indirect, special, incidental, or consequential damages, whether based on contract, tort, or any other legal theory.

Safety Symbols.

CAUTION

The *caution* sign denotes a hazard. It calls attention to a procedure which, if not correctly performed or adhered to, could result in damage to or destruction of the product. Do not proceed beyond a caution sign until the indicated conditions are fully understood and met.

WARNING

The *warning* sign denotes a hazard. It calls attention to a procedure which, if not correctly performed or adhered to, could result in injury or loss of life. Do not proceed beyond a warning sign until the indicated conditions are fully understood and met.



The instruction manual symbol. The product is marked with this warning symbol when it is necessary for the user to refer to the instructions in the manual.



The laser radiation symbol. This warning symbol is marked on products which have a laser output.



The AC symbol is used to indicate the required nature of the line module input power.



The ON symbols are used to mark the positions of the instrument power line switch.



The OFF symbols are used to mark the positions of the instrument power line switch.



The CE mark is a registered trademark of the European Community.



The CSA mark is a registered trademark of the Canadian Standards Association.



The C-Tick mark is a registered trademark of the Australian Spectrum Management Agency.

ISM1-A

This text denotes the instrument is an Industrial Scientific and Medical Group 1 Class A product.

Software License

The following License Terms govern your use of the accompanying Software unless you have a separate signed agreement with Agilent.

License Grant. Agilent grants you a license to Use one copy of the Software. “Use” means storing, loading, installing, executing or displaying the Software. You may not modify the Software or disable any licensing or control features of the Software. If the Software is licensed for “concurrent use,” you may not allow more than the maximum number of authorized users to Use the Software concurrently.

Ownership. The Software is owned and copyrighted by Agilent or its third party suppliers. Your license confers no title to, or ownership in, the Software and is not a sale of any rights in the Software. Agilent’s third party suppliers may protect their rights in the event of any violation of these License Terms.

Copies and Adaptations. You may only make copies or adaptations of the Software for archival purposes or when copying or adaptation is an essential step in the authorized Use of the Software. You must reproduce all copyright notices in the original Software on all copies or adaptations. You may not copy the Software onto any public network.

No Disassembly or Decryption. You may not disassemble or decompile the Software unless Agilent’s prior written consent is obtained. In some jurisdictions, Agilent’s consent may not be required for limited disassembly or decompilation.

Upon request, you will provide Agilent with reasonably detailed information regarding any disassembly or decompilation. You may not decrypt the Software unless decryption is a necessary part of the operation of the Software.

Transfer. Your license will automatically terminate upon any transfer of the Software. Upon transfer, you must deliver the Software, including any copies and related documentation, to the transferee. The transferee must accept these License Terms as a condition of the transfer.

Termination. Agilent may terminate your license upon notice for failure to comply with any of these License Terms. Upon termination, you must immediately destroy the Software, together with all copies, adaptations and merged portions in any form.

Export Requirements. You may not export or re-export the Software or any copies or adaptation in violation of any applicable laws or regulations.

U.S. Government Restricted Rights. The Software and Documentation have been developed entirely at private expense. They are delivered and licensed as “commercial computer software” as defined in DFARS 252.227-7013 (Oct 1988), DFARS 252.211-7015 (May 1991) or DFARS 252.227-7014 (Jun 1995), as a “commercial item” as defined in FAR 2.101(a), or as “Restricted computer software” as defined in FAR 52.227-19 (Jun 1987) (or any equivalent agency regulation or contract clause), whichever is applicable. You have those

rights provided for such Software and Documentation by the applicable FAR or DFARS clause or the Agilent standard software agreement for the product involved.

Limited Software Warranty Software. Agilent Technologies warrants for a period of one year from the date of purchase that the software product will execute its programming instructions when properly installed on the instrument indicated on this package. Agilent Technologies does not warrant that the operation of the software will be uninterrupted or error free. In the event that this software product fails to execute its programming instructions during the warranty period, Customer’s remedy shall be to return the media to Agilent Technologies for replacement. Should Agilent Technologies be unable to replace the media within a reasonable amount of time, Customer’s alternate remedy shall be a refund of the purchase price upon return of the product and all copies.

Media. Agilent Technologies warrants the media upon which this product is recorded to be free from defects in materials and workmanship under normal use for a period of one year from the date of purchase. In the event any media prove to be defective during the warranty period, Customer’s remedy shall be to return the media to Agilent Technologies for replacement. Should Agilent Technologies be unable to replace the media within a reasonable amount of time, Customer’s alternate remedy shall be a

refund of the purchase price upon return of the product and all copies.

Notice of Warranty Claims. Customer must notify Agilent Technologies in writing of any warranty claim not later than thirty (30) days after the expiration of the warranty period.

Limitation of Warranty. Agilent Technologies makes no other express warranty, whether written or oral, with respect to this product. Any implied warranty of merchantability or fitness is limited to the one year duration of this written warranty.

This warranty gives specific legal rights, and Customer may also have other rights which vary from state to state, or province to province.

Exclusive Remedies. The remedies provided above are Customer’s sole and exclusive remedies. In no event shall Agilent Technologies be liable for any direct, indirect, special, incidental, or consequential damages (including lost profit) whether based on warranty, contract, tort, or any other legal theory.

Warranty Service. Warranty service may be obtained from the nearest Agilent Technologies sales office or other location indicated in the owner’s manual or service booklet.

General Safety Considerations

This product has been designed and tested in accordance with IEC Publication 1010, Safety Requirements for Electronic Measuring Apparatus, and has been supplied in a safe condition. The instruction documentation contains information and warnings which must be followed by the user to ensure safe operation and to maintain the product in a safe condition.

WARNING

If this product is not used as specified, the protection provided by the equipment could be impaired. This product must be used in a normal condition (in which all means for protection are intact) only.

WARNING

No operator serviceable parts inside. Refer servicing to qualified personnel. To prevent electrical shock, do not remove covers.

Contents

General Safety Considerations iv

1 Installation

Installation 1-2

Step 1. Prepare the Site 1-4

Step 2. Install the Monitor Mount Assembly 1-6

Step 3. Install the Keyboard/Mouse Transmitter and the Work Surface 1-8

Step 4. Confirm Front and Rear Panel Connections 1-9

Step 5. Turn the System On 1-11

Step 6. Configure for Remote Operation 1-12

2 Getting Started

Configuration Options 2-6

Front Panel Features 2-8

Rear Panel Features 2-11

Software Overview 2-12

File Menu 2-13

Options Menu 2-20

Tools Menu 2-27

Laser Safety Considerations 2-30

Accurate Measurements 2-33

Electrostatic Discharge Information 2-44

Quick Start 2-47

3 Measurement Techniques

The Calibrations 3-2

Saving and Reusing 86030A Calibration Sets 3-5

O/O Response and Isolation Bandwidth Calibration 3-8

O/E Response and Isolation Bandwidth Calibration 3-11

O/E Response and Match Bandwidth Calibration 3-14

E/O Response and Isolation Bandwidth Calibration 3-23

Agilent 86030A System Example Measurements 3-28

Electrical Mismatch Ripple and its Effects on Measurements 3-29

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver 3-41

O/E RF Overload Detection Measurement 3-51

Contents

4 Remote Operation

- 86030A Remote Operation Overview 4-3
- COM Fundamentals 4-5
- Getting a Handle to the Server Object 4-9
- Configuring for DCOM Programming 4-12
- COM Data Types 4-15
- Tutorial Using 86030A Remote Operation 4-18
- List of Available Commands 4-25
- System Properties 4-29
- System Methods 4-32
- Data Methods 4-34
- Network Analyzer Methods 4-39
- Calibration Methods 4-41
- 86032A Testset Methods 4-77
- Enumerated Values 4-80
- System Messages 4-82
- Optical Test Set Error and Action Messages
with Descriptions 4-84
- System Error and Action Messages
with Descriptions 4-86
- Network Analyzer Error and Action Messages with Descriptions 4-91
- Error Codes and Error Handling 4-94

5 Theory of Operation

- System Operation 5-2
- Lightwave Test Set Operation 5-3
- Measurement Calibration 5-6
- O/O Measurement Calibration 5-7
- O/E Measurement Calibration 5-9
- E/O Measurement Calibration 5-11
- Electrical Measurement Calibration 5-14
- O/E Display Scaling Calculations 5-16
- E/O Display Scaling Calculations 5-17
- O/O Display Scaling Calculations 5-18

6 System Verification

- Lightwave Verification 6-3

If the Lightwave Verification Test Fails 6-7

7 Maintenance

86032A Test Set Troubleshooting Diagnostics 7-7

Modulator Troubleshooting Tips 7-16

Agilent Technologies Support and Maintenance 7-17

Electrostatic Discharge Information 7-19

Returning the System for Service 7-22

Agilent Technologies Service Offices 7-25

After Repair 7-26

8 Specifications and Regulatory Information

General Specifications 8-3

Electrical Specifications 8-4

Optical to Optical (O/O) Specifications 8-6

Optical to Electrical (O/E) Specifications 8-7

Electrical to Optical (E/O) Specifications 8-12

Characteristics 8-16

Optical to Electrical (O/E) Characteristics 8-18

Electrical to Optical (E/O) Characteristics 8-21

Regulatory Information 8-24

Declaration of Conformity 8-25

- Step 1. Prepare the Site 1-4
- Step 2. Install the Monitor Mount Assembly 1-6
- Step 3. Install the Keyboard/Mouse Transmitter and the Work Surface 1-8
- Step 4. Confirm Front and Rear Panel Connections 1-9
- Step 5. Turn the System On 1-11
- Step 6. Configure for Remote Operation 1-12

Installation

Installation

The instructions in this chapter show you how to install the 86030A 50 GHz LCA. For overseas sales, the product is shipped *without* an ac power connector. You should have a local electrician provide and install an ac connector that meets the standards for the region. Also, be sure to set all instruments to use the local line voltage.

WARNING

This system is a Safety Class I Product (provided with a protective earthing ground incorporated in the power cord). The mains plug shall only be inserted in a socket outlet provided with a protective earth contact. Any interruption of the protective conductor inside or outside of the product is likely to make the product dangerous. Intentional interruption is prohibited.

WARNING

To prevent electric shock, disconnect the system from mains before cleaning. Use a dry cloth or one slightly dampened with water to clean the external case parts. Do not attempt to clean internally.

WARNING

HP/Agilent 86032A: No operator serviceable parts inside. Refer servicing to qualified personnel. To prevent electrical shock, do not remove covers.

WARNING

HP/Agilent 86032A: For continued protection against fire hazard, replace line fuse only with same type and ratings. Use a 6.3A 250V fuse. The use of other fuses or materials is prohibited.

WARNING

HP/Agilent 86032A and HP/Agilent 86030A: If the system and test set products are not used as specified, the protection provided by the equipment could be impaired. These products must be used in a normal condition (in which all means for protection are intact) only.

CAUTION

Do not load any software on the 86030A system computer.

CAUTION

HP/Agilent 86032A and HP/Agilent 86030A: This system and test set are designed for use in INSTALLATION CATEGORY II and POLLUTION DEGREE 2, per IEC 1010 and 664 respectively.

CAUTION

HP/Agilent 86030A: Ventilation Requirements. When installing the product in a cabinet, the convection into and out of the product must not be restricted. The ambient temperature (outside the cabinet) must be less than the maximum operating temperature of the product by 4°C for every 100 watts dissipated in the cabinet. If the total power dissipated in the cabinet is greater than 800 watts, then forced convection must be used.

CAUTION


The warranty and calibration will be voided on systems where the individual instruments, including fiber-optic cables, RF cables, or GPIB cables are removed by the customer. The system should only be disassembled by an Agilent Customer Engineer. Instruments should not be swapped or removed by non-Agilent personnel.

Step 1. Prepare the Site

Your site should accommodate the dimensions, weights, and power consumption limits shown in the following figure.

WARNING

This system weighs approximately 600 lbs (270 kg). To avoid injuries, use proper moving equipment and use extreme care when installing.



WARNING

Install the system so the power cords are readily identifiable and are easily reached by the operator. The power cords are the disconnecting device. They disconnect the mains circuits from the mains supply

before other parts of the system. Alternately, an externally installed switch or circuit breaker (which is readily identifiable and is easily reached by the operator) may be used as a disconnecting device.

CAUTION

HP/Agilent 86030A and HP/Agilent 86032A: Install the system and test set according to the enclosure protection provided. This system and test set do not protect against the ingress of water. The system and test set protects against finger access to hazardous parts within the enclosure.

CAUTION

Before switching on this system, make sure the line voltage selector switch on the HP/Agilent 86032A lightwave test set's rear panel is set to the voltage of the mains supply, that the correct fuse is installed, and that the supply voltage is in the specified range.

Step 2. Install the Monitor Mount Assembly

- 1 Remove the black end cap from the top of the extrusion.
- 2 Slide the star knob onto the lower part of the extrusion and tighten.
- 3 Loosen the two black levers on the friction plate and slide it onto the extrusion.
- 4 Move the friction plate to the desired height and tighten the two black levers.
- 5 Loosen the star knob and raise it until it stops below the friction plate, then tighten the knob securely to prevent the friction plate, arm, and monitor mount assembly from falling.

WARNING

If the star knob is not installed properly, the friction plate, arm, and monitor mount assembly may fall, causing injury to the user or damage to the monitor and mounting components.

- 6 Attach the keyboard tray to the monitor mount assembly using the six provided mounting screws. Tighten with a 1/8" Allen wrench.
- 7 Attach the LCD monitor to the monitor mount assembly with the provided mounting screw. Tighten with a 7/32" Allen wrench. Make sure the monitor is properly oriented with the alignment pin, then tighten with a 7/32" Allen wrench.

CAUTION


Tighten all hardware on the arm and monitor mount assembly as necessary to prevent the monitor and keyboard from tipping unexpectedly.

CAUTION

Be careful when swinging the arm around in front of the system to avoid striking the 8510C and other system components.

- 8 Replace the black end cap on the extrusion.
- 9 Connect the monitor cables to the LCD monitor and secure the cables to the bottom of the arm using tie wraps.

Step 2. Install the Monitor Mount Assembly



Step 3. Install the Keyboard/Mouse Transmitter and the Work Surface

- 1** Slide the keyboard/mouse transmitter into the plastic holder on the bottom side of the work surface. Use the cable clamps on the bottom of the work surface to secure the cables.
- 2** Attach the work surface rails to the rack using a T-25 torx driver.
- 3** Slide the work surface over the rails and secure it using the hardware provided.
- 4** Route the transmitter cables through the rack and attach to the appropriate computer connectors using extension cables, if necessary.

The Connect button on the transmitter should be towards the plastic holder.

Step 4. Confirm Front and Rear Panel Connections

- 1 Connect the jumper between the LASER OUTPUT and LASER INPUT on the 86032A front panel. Refer to [Figure 1-1](#).

You must clean the connectors every time the jumper is connected. Refer to [“Cleaning Connectors”](#) on page 2-40.

- 2 Confirm the cabling of the Agilent/HP 86030A system. Refer to [Figure 1-2](#).




Figure 1-1. Location of the PMF Jumper

Installation
Step 4. Confirm Front and Rear Panel Connections




Figure 1-2. Agilent 86030A Cabling Configuration

Step 5. Turn the System On

- 1 Plug in the Power Distribution Units (PDU).
- 2 Turn on the system, and allow it to warm up for two hours.
- 3 When prompted for the password, enter Agilent.
- 4 Make certain that the laser key is in the ON position.
- 5 From the Windows **Start** menu on the 86030A computer, select **Programs, Agilent, 86030A Main** to open the software.

A splash screen will appear displaying the software title followed by the application screen shown in the following figure.

NOTE

Do NOT attempt to close the analyzer application until the 86030A system status window says “System Ready.”



- 6 Perform a system verification. Refer to “Lightwave Verification” on page 6-3.

Step 6. Configure for Remote Operation

This step provides instructions for configuring and installing the 86030A controller software on a client PC, which is external to the analyzer system. This step is only necessary if you will be operating the 86030A remotely. For information on available commands and remote operation, refer to [Chapter 4, “Remote Operation”](#).

Client PC Minimum Requirements

- Windows NT 4.0 Service Pack 6
- LAN Card

Configure the Client PC for a Private LAN Interface

These instructions assume that your computer already has a second network adapter (LAN card) and a TCP/IP protocol installed. The first LAN card must have a static IP to work on your public LAN in the presence of the second card.

- 1 On the client PC, click Start, Settings, Control Panel.
- 2 Double-click Network.
- 3 Select the Protocols tag and click Properties.
- 4 In the list displayed, select the type of LAN adapter card that you have installed in the client PC.
- 5 Click Adapter and select the second LAN card.
- 6 Click Specify, IP Address and enter the following settings.
 - For IP Address, enter 192.168.000.001
 - For Subnet Mask, enter 255.255.255.0
 - For Default Gateway: enter 192.168.000.001
- 7 Click Apply.


NOTE

If you get an error at least twice, indicating the adapter card has an empty primary window address, click Yes.

- 8 For the TCP/IP Properties window, click OK.
- 9 On the Network window, click Close.
- 10 Restart the PC.

Install the Controller Software

- 1 Insert the disk labeled “Agilent 86030A Controller Software” into the client computer CDROM drive.
- 2 Locate the file “86030A_Inst.exe” on the disk.
- 3 Double-click the file to start the installation process.
- 4 The window below will appear, indicating the setup process has begun.



- If a window appears stating that the Windows installer is an older version, click OK to allow the setup to upgrade the installer. It may take a few moments for the Welcome screen to appear.
 - Restart the computer after the installer is upgraded so the setup may continue.
- 5 When the InstallShield window appears, the installation process has begun. Click Next.
 - 6 Enter the User Name and Organization, then click Next.
 - 7 Select Complete setup, and click Next.
 - 8 Click Install. The installation may take a few minutes.
 - 9 Click Finish to complete the installation.

Installation

Step 6. Configure for Remote Operation

System Overview	2-2
Configuration Options	2-6
Front Panel Features	2-8
Rear Panel Features	2-11
Software Overview	2-12
File Menu	2-13
Options Menu	2-20
Tools Menu	2-27
Laser Safety Considerations	2-30
Accurate Measurements	2-33
Electrostatic Discharge Information	2-44
Quick Start	2-47

Getting Started

System Overview

The Agilent 86030A 50 GHz lightwave component analyzer provides accurate and repeatable characterization of electro-optical, optical, and electrical components.


You can characterize components such as O/E photodiode receivers, E/O photodiodes, lightwave modulators, and other optical and electrical components used in 40 Gb/s lightwave systems.

The Agilent 86030A system consists of the following items:

- 85107B vector network analyzer system
- 86032A 50 GHz lightwave test set
- system software
- personal computer, serving as the system controller
- controller software for a client computer

NOTE

You can control the 86030A directly using the system computer, or remotely using the controller software on a client computer.



Calibrated Measurements

One of the key benefits of the 50 GHz lightwave component analyzer is its ability to perform calibrated measurements of optical components. The system contains an O/E receiver that has been factory calibrated in magnitude, and characterized in phase. The ability to make calibrated measurements assures accuracy, reliability, and confidence in the components being measured. Additionally, the laser source, optical modulator, and calibrated O/E receiver are temperature stabilized which also improves the accuracy and repeatability of measurements.

Verification Device

A verification device is included with the N1012A Lightwave Verification Kit. The device is an O/E photodetector and includes associated amplitude and phase data. You can use this verification device at any time to verify the measurement integrity of your system. The 86030A system provides a guided verification routine that measures the verification device, and displays a graph of its response versus acceptable tolerances. The verification device allows you to periodically monitor system calibration, and detect when the optical test set needs to be recalibrated. You can also use the device to resolve uncertainty if unexpected results are obtained from a test device. This verification capability provides confidence in the measurement integrity of the system.

Measurement Software

Guided measurement software provides an easy-to-use operator interface. It provides pictorial diagrams of interconnections for configuration, calibration, and measurements. On-screen prompts also guide you through the entire measurement process, from the calibration to the measurement.

Data Management

Display, analysis, and archiving of data is easy and straightforward with the system. The measured data is displayed on the Agilent 8510C network analyzer. Full use of the analyzer's functions such as markers, data formats, and data scaling features are available. Data can be archived to disk in either ASCII text or Microsoft¹ Excel formats. The included Excel software allows data to be displayed and analyzed using standard Excel features and formats. Data connectivity to a local area network (LAN) is provided via a LAN card in the system's PC.

1. Microsoft and Excel are registered U.S. trademarks of Microsoft Corporation.

System Accessories

The accessories described below may be shipped with your system.

Table 2-1. System Accessories

Description	Agilent Model/Part Number
Verification Kit	N1012A
86030A User's Guide	86030-90023
2.4 mm 8510C Calibration Kit	85056A
2.4 mm Flexible Cables	85133F
Controller (Client) Software CDROM	86030-10004
86030A Operating System Software CDROM	86030-10002
86032A Calibration Coefficients Floppy Disk	Unique to 86032A Test Set
Bias Network 0.045 - 50 GHz (2.4 mm) ^a	11612B

a. The bias network is not part of the 86030A shipment, yet it may be helpful when measuring modulators.

Configuration Options

The standard Agilent/HP 86030A system is supplied with FC/PC optical connectors. If other optical connectors are desired, ordering one of the following connector options will replace the FC/PC connectors with the desired optical connectors.

Table 2-2. Available Options for the 86030A System

Option Number	Description	Part Number
011	Diamond HMS-10 connector interface	08154-61701
013	DIN 47256 connector interface	08154-61703
014	ST optical connector interface	08154-61704
017	SC optical connector interface	08154-61708
230	220-240 VAC operation	

WARNING

During measurements, laser light emits from the front-panel OPTICAL OUTPUT connector and the LASER OUTPUT connector. This light originates from the system's laser source. Always keep these connectors covered when not in use.

NOTE

If you would like to change the optical connectors to a different type, you can order a quantity of seven of the replacement part number, shown above.

CAUTION

The warranty and calibration will be voided on systems where the individual instruments are removed by the customer. The system should only be disassembled by a Agilent Technologies Customer Engineer. Instruments should not be replaced by non-Agilent Technologies personnel.

Measurement accuracy—it's up to you!

Fiber-optic connectors are easily damaged when connected to dirty or damaged cables and accessories. The 86030A's front-panel SOURCE OUTPUT and RECEIVER INPUT connectors, 86032A Laser Output and External Laser Input are no exception. When you use improper cleaning and handling techniques, you risk expensive instrument repairs, damaged cables, and compromised measurements. Before you connect any electrical cable to the 86030A, refer to ["Electrostatic Discharge Information"](#) on page 7-19.

Front Panel Features




Figure 2-3. 86032A Front Panel

1. LASER Key	Turns the laser on and off. Note that the laser is not operational until it is activated by the 86030A software program. You can turn on the laser manually from the Diagnostic software. From the Windows Start menu, select Programs, Agilent Technologies 50 GHz LCA, 50 GHz Diagnostics. From the Laser menu, click Laser ON. Make sure the laser key on the 86032A is in the on position.
--------------	--

WARNING

Do NOT, under any circumstances, look into the optical output or any fiber/device attached to the output while the laser is in operation. Refer to “Laser Safety Considerations” on page 2-30.

2. Laser LED	Indicates the state of the laser. When the LED is lit, the laser is on. Note that the laser is not operational until it is activated by the 86030A software program. You can turn on the laser manually from the Diagnostic software. From the Windows Start menu, select Programs, Agilent Technologies 50 GHz LCA, 50 GHz Diagnostics. From the Laser menu, click Laser ON.
3. E/O LED	When on, indicates the internal measurement path is selected for an E/O (electrical-to-optical) device.
4. E/E LED	When on, the internal measurement path is selected for an E/E (electrical-to-electrical) device. The test set is in a bypass mode for E/E device selection and the laser is shut down. The test set will need to be in the ON position for use in E/E mode.
5. O/E LED	When on, the internal measurement path is selected for an (optical-to-electrical) O/E device.
6. O/O LED	When on, the internal measurement path is selected for an (optical-to-optical) O/O device.
7. DIRECTIONAL COUPLER INPUT	Input for the optical direction coupler. This port is usually connected to the OPTICAL OUTPUT.
8. DIRECTIONAL COUPLER COUPLED	Port for the coupler output. This port is usually connected to the OPTICAL RECEIVER INPUT.
9. DIRECTIONAL COUPLER TEST PORT	Coupler output port (transmission) or test port (reflection).
10. Grounding Receptacle	Ground path that is provided to connect a static strap.
11. RF OUTPUT	RF output that provides RF drive power for E/O devices.
12. OPTICAL RECEIVER RF OUTPUT	Test set optical receiver output.


Front Panel Features

13. OPTICAL RECEIVER INPUT	Test set optical receiver input.
14. OPTICAL OUTPUT	Modulator output.
15. LASER INPUT	External laser input.
16. LASER OUTPUT	Output of internal laser.
17. POWER Switch	Turns the instrument power on.

CAUTION

Use care in handling optical connectors. Damage to an optical test port connector can require a costly repair and lost productivity for the system. Keep optical cables connected to the test ports to protect the connectors from damage. Also, make sure to clean the connectors before each use. [Refer to “Accurate Measurements” on page 2-33.](#)

Rear Panel Features



rearfeat


Figure 2-4. 86032A Rear Panel

1. Remote Programming Connector	Allows for remote control of the instrument's front panel via the 86030A software installed on the system PC.
2. Laser Remote Shutdown	Turns the laser on or off. When the BNC short is connected, the laser is enabled. When removed, the laser is disabled.
3. Line Module	This assembly houses the line cord connector.
4. RF REF OUTPUT	RF output of the test set that is used to route the 8517B electrical test set for phase locking.
5. EXT ALC	DC output from the leveling detector on the internal ALC circuit. This output is routed to the EXT ALC port of the network analyzer source.
6. RF INPUT	RF input port from the source output of the network analyzer.

Software Overview


The 86030A software sets up instrument states on the network analyzer and lightwave test set, and guides you through the measurement calibration and measurement procedures. The program combines the measurement calibration traces with the calibration data response of the lightwave receiver, and loads the result back into the network analyzer to provide calibrated lightwave measurements. You can save and view trace data using Microsoft Excel, and manually control the 86032A test set operation.

File Menu



The File menu is used to save data as either an ASCII text file or an Excel worksheet. Using Graph Excel Data allows you to automatically view saved data in an Excel worksheet as tabular data, or as graphical data in log magnitude, phase or delay formats. The File menu is also used to exit the application.


Save Data



Text File

Text File allows you to save data as an ASCII text file in four different formats:

- Raw Data
- Log Magnitude
- Phase
- Delay


File Menu

Raw Data saves trace data in a ASCII text format (.txt) known as a CITIFile (common instrumentation transfer and interchange file). The CITIFile format is useful when data will be exchanged with another network analyzer. The data file saves both real and imaginary pairs independent of the format of the active screen. However, any trace smoothing that was applied to the measurement will not be saved (that is, Smoothing On is activated from the 8510C Response menu).

Formatted Data, Log Mag, Phase, Delay saves trace data with any trace smoothing that was applied to the measurement (that is, Smoothing On is activated from the 8510C Response menu), but only retains the values of the format that was selected for saving (that is, Log Magnitude, Phase, or Delay).

Excel File

Excel File allows you to save the trace display as a Microsoft Excel workbook (.xls extension). The Excel format is useful when you want to view or edit the data in an Excel spreadsheet.



Raw Data saves both real and imaginary pairs independent of the format of the active screen. This data can later be viewed in either Log Magnitude or Phase format from the File, Graph Excel Data menu. Any trace smoothing that was applied to the measurement will not be saved (that is, if Smoothing On is activated from the 8510C Response menu).


Formatted Data saves trace data and any trace smoothing that was applied to the measurement, but only viewed using the format that the data was originally saved (that is, Log Magnitude, Phase, or Delay).

Log Mag saves the log magnitude format. This is the standard Cartesian format used to display magnitude-only measurements of insertion loss, return loss, or absolute power in dB versus frequency.

Phase saves the phase of data versus frequency in a Cartesian format.

Delay saves the group delay format, with marker values given in seconds. Group delay is the measurement of signal transmission time through a test device. It is defined as the derivative of the phase characteristic with respect to frequency. Since the derivative is basically the instantaneous slope (or rate of change of phase with frequency), a perfectly linear phase shift results in a constant slope, and therefore a constant group delay.

Graph Excel Data



Raw Data

Data allows you to view trace data in either Log Magnitude or Phase format. However, any trace smoothing that was applied to the measurement will not be captured. (that is, if Smoothing On was activated from the 8510C Response menu).

Log Magnitude displays the trace data in Cartesian format as logarithmic (dB) magnitude versus frequency.

Phase displays the trace data in Cartesian format as phase versus frequency.

Formatted Data,

Formatted Data allows you to view trace data in the format that it was saved (that is, Log Magnitude, Phase, or Delay) including any trace smoothing that was applied to the measurement

Log Mag displays the log magnitude format. This is the standard Cartesian format used to display magnitude-only measurements of insertion loss, return loss, or absolute power in dB versus frequency.

Phase displays the phase shift of data versus frequency in a Cartesian format.

Delay displays the group delay format, with marker values given in seconds. Group delay is the measurement of signal transmission time through a test device. It is defined as the derivative of the phase characteristic with respect to frequency. Since the derivative is basically the instantaneous slope (or rate of change of phase with frequency), a perfectly linear phase shift results in a constant slope, and therefore a constant group delay. See [Figure 2-5](#).




Figure 2-5.

Note, however, that the phase characteristic typically consists of both linear and higher order (deviations from linear) components. The linear component can be attributed to the electrical length of the test device, and represents the average signal transit time. The higher order components are interpreted as variations in transit time for different frequencies, and represent a source of signal distortion. See [Figure 2-6](#).




Figure 2-6.

$$\text{Group Delay} = \tau_g = \frac{-d\phi}{d\omega} \quad \begin{array}{l} \text{in Radians} \\ \text{in Radians} \end{array} = \frac{-1}{360^\circ} \cdot \frac{d\phi}{df} \quad \begin{array}{l} \phi \text{ in Degrees} \\ f \text{ in Hz } (\omega = 2\pi f) \end{array}$$

The analyzer computes group delay from the phase slope. Phase data is used to find the phase change, $\Delta\phi$, over a specified frequency aperture, Δf , to obtain an approximation for the rate of change of phase with frequency (Figure 2-7). This value, τ_g , represents the group delay in seconds assuming linear phase change over Δf . It is important that $\Delta\phi$ be $\leq 180^\circ$, or errors will result in the group delay data. These errors can be significant for long delay devices.




Figure 2-7.

When deviations from linear phase are present, changing the frequency step can result in different values for group delay. Note that in this case the computed slope varies as the aperture Δf is increased (Figure 2-8). A wider aperture results in loss of the fine grain variations in group delay. This loss of detail is the reason that in any comparison of group delay data it is important to know the aperture used to make the measurement.




Figure 2-8.

In determining the group delay aperture, there is a trade-off between resolution of fine detail and rapid variations in group delay, which can look like a noisy trace. These rapid variations can be reduced by increasing the aperture, but this will tend to smooth out the fine detail. More detail will become visible as the aperture is decreased, but the variations will also increase, possibly to the point of obscuring the detail. A good practice is to use a smaller aperture to assure that small variations are not missed, then increase the aperture to smooth the trace.

Exit

Exit closes the 86030A software application.

Options Menu



The Options menu allows you to set and monitor system functions.

Auto Bias

Auto Bias allows you to bias the modulator to operate at quadrature or at maximum optical power. Under typical circumstances the lightwave modulator is biased to operate at quadrature. Quadrature is the point where the slope of the optical power versus voltage is maximally positive. Refer to [Figure 2-9](#).

Modulator Auto-Biasing ...

Power at Quadrature (dBm)

Voltage at Quadrature (V)

Voltage at Maximum Optical Power (V)

Voltage at Minimum Optical Power (V)

Maximum Optical Power (dBm)

Minimum Optical Power (dBm)




Figure 2-9. Effect of Bias Voltage on Modulated Optical Power

Power at Quadrature (1)

The point midway between the maximum and minimum optical power points, on the positive slope of the bias curve. The quadrature point allows maximum optical power variations versus modulation voltage.

Voltage at Quadrature (2)

The voltage where the optical power is at the quadrature point. The auto-biasing routine selects this voltage to bias the internal optical modulator.

**Voltage at
Maximum Optical
Power (3)**

The voltage at which the maximum output power occurs (V_{\max}).

**Voltage at
Minimum Optical
Power (4)**

The voltage at which the minimum output power occurs (V_{\min}).

**Maximum Optical
Power (5)**

The maximum optical output power.

**Minimum Optical
Power (6)**

The minimum optical output power.

How to Determine if Auto Bias Values are Reasonable

The following formulas will help you to determine if the modulator auto bias settings are valid. Refer to [Figure 2-9 on page 2-21](#)

Voltage at Maximum Optical Power – Voltage at Minimum Optical Power should be between 3 and 6 volts.

Voltage at Quadrature should be approximately $\frac{V_{\max} + V_{\min}}{2}$


Maximum Optical Power should be > 3 dBm

Power at Quadrature should be > 0 dBm

Tip: You can set this value manually. From the Tools menu, click on Monitor Test Set. In the Modify Bias Voltage text box, enter the desired value and then click Set Modulator Bias Voltage to.


[Refer to “Modulator Troubleshooting Tips” on page 7-16](#) for more information.

Auto Bias At Cal



Auto Bias At Cal when selected, an auto bias is performed before each calibration. The auto bias is performed after you click either Resp Cal or Resp-Isol Cal.


Customize



Customize allows you to set and monitor certain parameters that affect the operation of the system.

Standard

The Standard Settings dialog box allows you to set and monitor certain parameters controlled by the network analyzer.



GPIB Address displays the current address setting for the analyzer. This value must correspond to the actual address on the 8510 GPIB address bus. Failure of these two numbers to match will prevent operation.

Average Factor is used to improve the sensitivity of the measurement. For the Step Mode of operation for each modulation frequency point, multiple data point samples (equal to the number of averages) are measured by the system, and averaged together to provide a single average value. Averaging multiple data points together reduces the effects of noise on the measurement. The improvement in sensitivity is equal to:

$$dB = 10\log_{10}(\text{number of averages})$$

Note the 8510C network analyzer only averages with powers of 2 (that is, 1, 2, 4, 8, 16, 32, 64, 128, 256, 512, 1024, and so on). Therefore, if an averaging factor of 500 is set on the analyzer, the analyzer will default to 256 averages.

Bias Interval, mins corresponds to the number of minutes before prompting you to perform another modulator auto bias.

Refl Standard% corresponds to the percent of reflection of the Reflection Standard used in the system. This is useful for O/O reflection modes.

Averaging when selected, the network analyzer will perform averaging at each data point.

Split Screen E/O when selected, the network analyzer displays both the bandwidth and reflection measurement on the display. *This function is only valid with an E/O Bandwidth and Reflection measurement.* Bandwidth is

displayed on channel 1 and Reflection is displayed on channel 2. When this function is cleared, use the network analyzer front panel channel buttons to select between the two measurements.

Time Date Stamp when selected, the time and date stamp is applied to the trace on the network analyzer.

Scale Excel Chart when selected, the trace data saved from the network analyzer will be auto-scaled to fit into an Excel chart.

Step Sweep/Ramp Sweep toggles between step sweep and ramp sweep modes.

Step Sweep is a digital sweep beginning at the start frequency and ending at the stop frequency with the source phase locked and the data measured at a frequency interval determined by the number of points selected on the network analyzer (STIMULUS MENU, STEP). An up arrow on the trace identifies the data point just measured. The step mode is recommended when you need the best modulation frequency accuracy and repeatability.

Dwell time prior to measurement at each frequency point is controlled by the sweep time setting. Measurement time at each point is determined by the averaging factor.


NOTE

System specifications are only warranted when using the Step Sweep mode of operation.

Ramp Sweep selects continuous linear analog sweeps beginning at the start frequency and ending at the stop frequency. The rate is determined by the sweep time, measuring data at frequency intervals set by the number of points. (8510 access, STIMULUS MENU, RAMP)

Advanced

The Advanced Settings dialog box allows changing of default power values.



External Leveling when checked, the system uses external leveling. When cleared, the system uses internal leveling. Normal system operation uses external leveling.

Src Pwr, E to X, dBV for E/O mode and E/ E mode, displays the 83651A external leveling source power.

Src Pwr, O to X, dBV for O/E mode and O/O mode, displays the 83651A external leveling source power.

Default Settings when selected, resets the source power to its factory default values.

Setting the Power at the RF Output Port The power at the 86030A RF output port is set at the factory for a nominal 0 dBm. You can change the RF output power level by following these steps:

- 1 Connect a power meter to the RF output port.
- 2 On the 8510, press **Span, 0, Hz, Center Frequency, 25, GHz**.
- 3 In the 86030A **Options** menu, click **Customize, Advanced**.
- 4 In the **Src Pwr, EtoO, dBV** box, enter the power value and click **OK**. Make the changes to the power level in small deviations from the default state.


CAUTION

Do not exceed -3 to +5 dBm at the 8510 RF output port. Due to variations in amplifier gain, error messages may appear on the analyzer screen. Reduce or increase the power setting to remove the error messages.

System Verification


A System Verification performs a measurement on the verification device over the entire frequency range. The verification device is the 83440D Option 050 lightwave detector supplied in the N1012A verification kit. Once the verification is completed, the results are displayed in an Excel worksheet along with the error bars that were computed from the factory measurement of the verification device. For the system to pass the verification test, the verification device trace must fit within the error bars. A pass or fail indicator is displayed at the bottom of the worksheet. Refer to “[Lightwave Verification](#)” on page 6-3 for more information.

Tools Menu



The Tools menu is used to monitor and modify 86032A test set parameters.

Modify Test Set



Current Laser Output Power (dBm) displays the value of the laser power coming from the LASER OUTPUT port of the test set.

Set Laser Output Power to:(dBm), when Modify Power is selected, the value will be updated to the value specified in this text box.

Modify Power sets the internal laser of the 86030A test set to the power specified in the Modify Power text box. This value will be used until you restart the 86030A software. Valid settings are from 0 dBm to 10 dBm.

Set Optical Output Pwr to Nominal Setting sets the laser to its factory default setting. When the software is started, the power always defaults back to the factory setting.

Current Modulator Bias Voltage (V) displays the value last applied to the internal modulator bias tee attached to the optical modulator.

Set Modulator Bias Voltage to: (V), when Modify Bias Voltage is selected, the bias voltage will be updated to the value specified in this text box. The range is -10 to +10 volts.

Modify Bias Voltage sets the bias voltage to the value entered in the Set Modulator Bias Voltage text box.

Turn Laser On turns on the laser inside the 86032A test set. This command does not change the power of the laser. This function is useful in E/O mode when you may want to use the internal high power laser as a stimulus for testing optical modulators. The optical power is normally off in the E/O mode.

Turn Laser Off turns off the laser inside the 86032A test set. This command does not change power of the laser. If the laser is turned off and then turned back on again, the original power of the laser will be used.

Set Mod. Bias to Quadrature when clicked, performs an auto bias on the modulator and sets the modulator bias voltage to the midpoint of the modulated optical power curve. Biasing at quadrature maximizes the modulation response and minimizes distortion of the modulated signal.

The power of the laser is assumed to have been previously set. If the laser power is too low or if the laser is turned off, the auto bias routine will fail and display a message indicating that a bias point could not be found. For this command to function properly, the laser power should be left at its default setting or set to a reasonable power value (between 3 and 12 dBm) prior to performing this function.


Set Mod Bias to Maximum when selected, performs an auto bias on the modulator and sets the modulator at maximum optical output power.

The power of the laser is assumed to have been previously set. If the laser power is too low or if the laser is turned off, the auto bias routine will fail and display a message indicating that a bias point could not be found. For this command to function properly, the laser power should be left to its default setting or set to a reasonable power value (between 3 and 12 dBm) prior to performing this function.

E/X when selected, puts the 86032A test set into electrical excitation mode. The RF signal coming into the optical test set will be routed out of the front panel connector marked “RF OUTPUT.” Therefore, the RF signal will not be routed to the optical modulator in the test set.

O/X when selected, puts the 86032A test set into optical excitation mode. The RF signal coming into the test set will be routed to the optical modulator, rather than out the front panel connector marked “RF OUTPUT.”

Monitor Test Set



The Monitor Test Set dialog box is used to monitor and update the power and voltage levels of the 86032A test set.

Optical Output Power (dBm) displays the current optical power coming from the 86032A OPTICAL OUTPUT port.

Optical Receiver Input (dBm) displays the current optical power coming into the 86032A OPTICAL RECEIVER INPUT port.

Current Modulator Bias Setting (V) displays the current value of the 86032A bias voltage on the modulator.

Laser Safety Considerations

Laser Safety

Laser radiation in the ultraviolet and far infrared parts of the spectrum can cause damage primarily to the cornea and lens of the eye. Laser radiation in the visible and near infrared regions of the spectrum can cause damage to the retina of the eye.

The CW laser sources use a laser from which the greatest dangers to exposure are:

- 1 To the eyes, where aqueous flare, cataract formation, and/or corneal burn are possible.
- 2 To the skin, where burning is possible.

WARNING

Do NOT, under any circumstances, look into the optical output or any fiber/device attached to the output while the laser is in operation.

This system should be serviced only by authorized personnel.

Do not enable the laser unless fiber or an equivalent device is attached to the optical output connector.

CAUTION

Use of controls or adjustments or performance of procedures other than those specified herein can result in hazardous radiation exposure.

Laser Classifications

United States-FDA Laser Class IIIb. The system is rated USFDA (United States Food and Drug Administration) Laser Class IIIb according to Part 1040, Performance Standards for Light Emitting Products, from the Center for Devices and Radiological Health.

International-IEC Laser Class 3B. The system is rated IEC (International Electrotechnical Commission) Laser Class 3B laser products according to Publication 825.

International-IEC 825. The system helps satisfy the International (IEC825) safety requirements with the use of a REMOTE SHUTDOWN and a KEY SWITCH.

Laser Warning Labels

The 86030A is shipped with the following warning labels. For systems used outside of the USA, both laser aperture and laser warning labels will be included with the shipment (The labels are located in the same box as this manual). Place these labels directly over the USA laser warning and aperture labels.




Figure 2-10. Laser safety label locations

Electrical Safety

The electrical safety considerations are documented in the section “[General Safety Considerations](#)” on page iv. Familiarize yourself with the safety markings and instructions before operating this system.

Service

Limited service may be performed on this system in accordance with information provided in [Chapter 7, “Maintenance”](#). For all other repairs the system must be returned to Agilent Technologies.

Maintenance

On a daily basis, practice the techniques for proper connector use and care. Refer to the *Lightwave Connection Techniques for Better Measurements* booklet. If you should ever need to clean the cabinet, use a damp cloth only.

CAUTION

Exposure to temperatures above 55°C may cause the front panel fiber to retract. In this case a matching compound can be used to temporarily improve return loss. However, the system should be returned to Agilent Technologies for repair.

CAUTION

This product is designed for use in INSTALLATION CATEGORY II and POLLUTION DEGREE 2, per IEC 1010 and 664 respectively.

Learn proper connector care

When you use improper cleaning and handling techniques, you risk expensive system repairs, damaged cables, and compromised measurements. Repair of damaged connectors due to improper use is not covered under warranty.

Clean all cables before applying to any connector. Refer to the *Lightwave Connections Techniques for Better Measurements* booklet.

Accurate Measurements

Today, advances in measurement capabilities make connectors and connection techniques more important than ever. Damage to the connectors on calibration and verification devices, test ports, cables, and other devices can degrade measurement accuracy and damage instruments. Replacing a damaged connector can cost thousands of dollars, not to mention lost time! This expense can be avoided by observing the simple precautions presented in this book. This book also contains a brief list of tips for caring for electrical connectors.

Choosing the Right Connector

A critical but often overlooked factor in making a good lightwave measurement is the selection of the fiber-optic connector. The differences in connector types are mainly in the mechanical assembly that holds the ferrule in position against another identical ferrule. Connectors also vary in the polish, curve, and concentricity of the core within the cladding. Mating one style of cable to another requires an adapter. Agilent Technologies offers adapters for most instruments to allow testing with many different cables. The [Figure 2-11 on page 2-34](#) shows the basic components of a typical connector.

The system tolerance for reflection and insertion loss must be known when selecting a connector from the wide variety of currently available connectors. Some items to consider when selecting a connector are:

- How much insertion loss can be allowed?
- Will the connector need to make multiple connections? Some connectors are better than others, and some are very poor for making repeated connections.
- What is the reflection tolerance? Can the system take reflection degradation?
- Is an instrument-grade connector with a precision core alignment required?
- Is repeatability tolerance for reflection and loss important? Do your specifica-

tions take repeatability uncertainty into account?

- Will a connector degrade the return loss too much, or will a fusion splice be required? For example, many DFB lasers cannot operate with reflections from connectors. Often as much as 90 dB isolation is needed.




Figure 2-11. Basic components of a connector.

Over the last few years, the FC/PC style connector has emerged as the most popular connector for fiber-optic applications. While not the highest performing connector, it represents a good compromise between performance, reliability, and cost. If properly maintained and cleaned, this connector can withstand many repeated connections.

However, many instrument specifications require tighter tolerances than most connectors, including the FC/PC style, can deliver. These instruments cannot tolerate connectors with the large non-concentricities of the fiber common with ceramic style ferrules. When tighter alignment is required, Agilent instruments typically use a connector such as the Diamond HMS-10, which has concentric tolerances within a few tenths of a micron. Agilent then uses a special universal adapter, which allows other cable types to mate with this precision connector. See [Figure 2-12 on page 2-35](#).



Figure 2-12. Universal adapters

The HMS-10 encases the fiber within a soft nickel silver (Cu/Ni/Zn) center which is surrounded by a tough tungsten carbide casing, as shown in [Figure 2-13](#).




Figure 2-13. Cross-section of the Diamond HMS-10 connector.

The nickel silver allows an active centering process that permits the glass fiber to be moved to the desired position. This process first stakes the soft nickel silver to fix the fiber in a near-center location, then uses a post-active staking to shift the fiber into the desired position within 0.2 μm. This process, plus the keyed axis, allows very precise core-to-core alignments. This connector is found on most Agilent lightwave instruments.

The soft core, while allowing precise centering, is also the chief liability of the connector. The soft material is easily damaged. Care must be taken to minimize excessive scratching and wear. While minor wear is not a problem if the glass face is not affected, scratches or grit can cause the glass fiber to move out of alignment. Also, if unkeyed connectors are used, the nickel silver can be pushed onto the glass surface. Scratches, fiber movement, or glass contamination will cause loss of signal and increased reflections, resulting in poor return loss.

Inspecting Connectors

Because fiber-optic connectors are susceptible to damage that is not immediately obvious to the naked eye, bad measurements can be made without the user even being aware of a connector problem. Although microscopic examination and return loss measurements are the best way to ensure good connections, they are not always practical. An awareness of potential problems, along with good cleaning practices, can ensure that optimum connector performance is maintained. With glass-to-glass interfaces, it is clear that any degradation of a ferrule or the end of the fiber, any stray particles, or finger oil can have a significant effect on connector performance.

[Figure 2-14](#) shows the end of a clean fiber-optic cable. The dark circle in the center of the micrograph is the fiber's 125 μm core and cladding which carries the light. The surrounding area is the soft nickel-silver ferrule. [Figure 2-15](#) shows a dirty fiber end from neglect or perhaps improper cleaning. Material is smeared and ground into the end of the fiber causing light scattering and poor reflection. Not only is the precision polish lost, but this action can grind off the glass face and destroy the connector.

[Figure 2-16](#) shows physical damage to the glass fiber end caused by either repeated connections made without removing loose particles or using improper cleaning tools. When severe, the damage on one connector end can be transferred to another good connector that comes in contact with it.

The cure for these problems is disciplined connector care as described in the following list and in [“Cleaning Connectors” on page 2-40](#).

Use the following guidelines to achieve the best possible performance when making measurements on a fiber-optic system:

- Never use metal or sharp objects to clean a connector and never scrape the connector.
- Avoid matching gel and oils.




Figure 2-14. Clean, problem-free fiber end and ferrule.




Figure 2-15. Dirty fiber end and ferrule from poor cleaning.




Figure 2-16. Damage from improper cleaning.

Accurate Measurements

While these often work well on first insertion, they are great dirt magnets. The oil or gel grabs and holds grit that is then ground into the end of the fiber. Also, some early gels were designed for use with the FC, non-contacting connectors, using small glass spheres. When used with contacting connectors, these glass balls can scratch and pit the fiber. If an index matching gel or oil must be used, apply it to a freshly cleaned connector, make the measurement, and then immediately clean it off. Never use a gel for longer-term connections and never use it to improve a damaged connector. The gel can mask the extent of damage and continued use of a damaged fiber can transfer damage to the instrument.

- When inserting a fiber-optic cable into a connector, gently insert it in as straight a line as possible. Tipping and inserting at an angle can scrape material off the inside of the connector or even break the inside sleeve of connectors made with ceramic material.
- When inserting a fiber-optic connector into a connector, make sure that the fiber end does not touch the outside of the mating connector or adapter.
- Avoid over tightening connections.

Unlike common electrical connections, tighter is *not* better. The purpose of the connector is to bring two fiber ends together. Once they touch, tightening only causes a greater force to be applied to the delicate fibers. With connectors that have a convex fiber end, the end can be pushed off-axis resulting in misalignment and excessive return loss. Many measurements are actually improved by backing off the connector pressure. Also, if a piece of grit does happen to get by the cleaning procedure, the tighter connection is more likely to damage the glass. Tighten the connectors just until the two fibers touch.

- Keep connectors covered when not in use.
- Use fusion splices on the more permanent critical nodes. Choose the best connector possible. Replace connecting cables regularly. Frequently measure the return loss of the connector to check for degradation, and clean every connector, every time.

All connectors should be treated like the high-quality lens of a good camera. The weak link in instrument and system reliability is often the inappropriate use and care of the connector. Because current connectors are so easy to use, there tends to be reduced vigilance in connector care and cleaning. It takes only one missed cleaning for a piece of grit to permanently damage the glass and ruin the connector.

Measuring insertion loss and return loss

Consistent measurements with your lightwave equipment are a good indication that you have good connections. Since return loss and insertion loss are key factors in determining optical connector performance they can be used to determine connector degradation. A smooth, polished fiber end should produce a good return-loss measurement. The quality of the polish establishes the difference between the “PC” (physical contact) and the “Super PC” connectors. Most connectors today are physical contact which make glass-to-glass connections, therefore it is critical that the area around the glass core be clean and free of scratches. Although the major area of a connector, excluding the glass, may show scratches and wear, if the glass has maintained its polished smoothness, the connector can still provide a good low level return loss connection.

If you test your cables and accessories for insertion loss and return loss upon receipt, and retain the measured data for comparison, you will be able to tell in the future if any degradation has occurred. Typical values are less than 0.5 dB of loss, and sometimes as little as 0.1 dB of loss with high performance connectors. Return loss is a measure of reflection: the less reflection the better (the larger the return loss, the smaller the reflection). The best physically contacting connectors have return losses better than 50 dB, although 30 to 40 dB is more common.

To Test Insertion Loss

Use an appropriate lightwave source and a compatible lightwave receiver to test insertion loss. Examples of test equipment configurations include the following equipment:

- 71450A or 71451A Optical Spectrum Analyzers with Option 002 built-in white light source.
- 8702 or 8703 Lightwave Component Analyzer system.
- 83420 Chromatic Dispersion Test Set with an 8510 Network Analyzer.
- 8153 Lightwave Multimeter with a source and power sensor module.

To Test Return Loss

Use an appropriate lightwave source, lightwave receiver, and lightwave coupler to test return loss. Examples of test equipment configurations include the following equipment:

- Agilent 8703 Lightwave Component Analyzer.
- Agilent 8702 Lightwave Component Analyzer with the appropriate source, receiver, and lightwave coupler.
- Agilent 8504 Precision Reflectometer.
- Agilent 8153 Lightwave Multimeter with a source and power sensor module in

conjunction with a lightwave coupler.

- Agilent 81554SM Dual Source and Agilent 81534A Return Loss Module.

Visual inspection of fiber ends

Visual inspection of fiber ends can be helpful. Contamination or imperfections on the cable end face can be detected as well as cracks or chips in the fiber itself. Use a microscope (100X to 200X magnification) to inspect the entire end face for contamination, raised metal, or dents in the metal as well as any other imperfections. Inspect the fiber for cracks and chips. Visible imperfections not touching the fiber core may not affect performance (unless the imperfections keep the fibers from contacting).

WARNING

Always remove both ends of fiber-optic cables from any instrument, system, or device before visually inspecting the fiber ends. Disable all optical sources before disconnecting fiber-optic cables. Failure to do so may result in permanent injury to your eyes.

Cleaning Connectors

The procedures in this section provide the proper steps for cleaning fiber-optic cables and Agilent universal adapters. The initial cleaning, using the alcohol as a solvent, gently removes any grit and oil. If a caked-on layer of material is still present, (this can happen if the beryllium-copper sides of the ferrule retainer get scraped and deposited on the end of the fiber during insertion of the cable), a second cleaning should be performed. It is not uncommon for a cable or connector to require more than one cleaning.

CAUTION

Agilent strongly recommends that index matching compounds *not* be applied to their instruments and accessories. Some compounds, such as gels, may be difficult to remove and can contain damaging particulates. If you think the use of such compounds is necessary, refer to the compound manufacturer for information on application and cleaning procedures.

Table 2-3. Cleaning Accessories

Item	Agilent Part Number
Pure isopropyl alcohol	—
Cotton swabs	8520-0023
Small foam swabs	9300-1223
Compressed dust remover (non-residue)	8500-5262

Table 2-4. Dust Caps Provided with Lightwave Instruments

Item	Agilent Part Number
Laser shutter cap	08145-64521
FC/PC dust cap	08154-44102
Biconic dust cap	08154-44105
DIN dust cap	5040-9364
HMS10/Agilent dust cap	5040-9361
ST dust cap	5040-9366

To clean a non-lensed connector

CAUTION

Do not use any type of foam swab to clean optical fiber ends. Foam swabs can leave filmy deposits on fiber ends that can degrade performance.

- 1** Apply pure isopropyl alcohol to a clean lint-free cotton swab or lens paper.
 Cotton swabs can be used as long as no cotton fibers remain on the fiber end after cleaning.
- 2** Clean the ferrules and other parts of the connector while avoiding the end of the fiber.
- 3** Apply isopropyl alcohol to a new clean lint-free cotton swab or lens paper.
- 4** Clean the fiber end with the swab or lens paper.

Accurate Measurements

Do *not* scrub during this initial cleaning because grit can be caught in the swab and become a gouging element.

- 5 Immediately dry the fiber end with a clean, dry, lint-free cotton swab or lens paper.
- 6 Blow across the connector end face from a distance of 6 to 8 inches using filtered, dry, compressed air. Aim the compressed air at a shallow angle to the fiber end face.

Nitrogen gas or compressed dust remover can also be used.

CAUTION

Do not shake, tip, or invert compressed air canisters, because this releases particles in the can into the air. Refer to instructions provided on the compressed air canister.

Caring for Electrical Connections

The following list includes the basic principles of microwave connector care. For more information on microwave connectors and connector care, consult the *Connector Care Manual*, part number 08510-90064.

Handling and Storage

- Keep connectors clean
- Extend sleeve or connector nut
- Use plastic endcaps during storage
- Do *not* touch mating plane surfaces
- Do *not* set connectors contact-end down

Visual Inspection

- Inspect all connectors carefully before every connection
- Look for metal particles, scratches, and dents
- Do *not* use damaged connectors

Cleaning

- Try cleaning with compressed air first
- Clean the connector threads
- Do *not* use abrasives
- Do *not* get liquid onto the plastic support beads

Making Connections

- Align connectors carefully
- Make preliminary connection lightly
- To tighten, turn connector nut *only*
- Do *not* apply bending force to connection
- Do *not* overtighten preliminary connection
- Do *not* twist or screw in connectors
- Do *not* tighten past the “break” point of the torque wrench

Electrostatic Discharge Information


Electrostatic discharge (ESD) can damage or destroy electronic components. All work on electronic assemblies should be performed at a static-safe work station. The following figure shows an example of a static-safe work station using two types of ESD protection:

- Conductive table-mat and wrist-strap combination.

NOTE

For the 86030A 50 GHz LCA system, the static strap is attached to the 86032A front panel grounding receptacle. Refer to “[Front Panel Features](#)” on page 2-8.

- Conductive floor-mat and heel-strap combination.



Both types, when used together, provide a significant level of ESD protection. Of the two, only the table-mat and wrist-strap combination provides adequate ESD protection when used alone.

To ensure user safety, the static-safe accessories must provide at least $1\text{ M}\Omega$ of isolation from ground. Refer to [Table 17 on page 2-46](#) for information on ordering static-safe accessories.

WARNING

These techniques for a static-safe work station should not be used when working on circuitry with a voltage potential greater than 500 volts.

Reducing ESD Damage

The following suggestions may help reduce ESD damage that occurs during testing and servicing operations.

- Personnel should be grounded with a resistor-isolated wrist strap before removing any assembly from the unit.
- Be sure all instruments are properly earth-grounded to prevent a buildup of static charge.

Table 17. Static-Safe Accessories

Agilent Part Number	Description
9300-0797	Set includes: 3M static control mat 0.6 m × 1.2 m (2 ft. × 4 ft.) and 4.6 cm (15 ft.) ground wire. (The wrist-strap and wrist-strap cord are not included. They must be ordered separately.)
9300-0980	Wrist-strap cord 1.5 m (5 ft.)
9300-1383	Wrist-strap, color black, stainless steel, without cord, has four adjustable links and a 7 mm post-type connection.
9300-1169	ESD heel-strap (reusable 6 to 12 months).

Quick Start


This procedure steps you through the process of making your first measurement. The verification kit supplied with your system contains a photo detector, which we will use to make an optical-to electrical (O/E) bandwidth response measurement.

Photodiode responsivity (amps/watt) refers to how a change in optical power is converted to a change in output electrical current. As the frequency of modulation increases, eventually the receiver responsivity will rolloff. Thus, the device has a limited modulation bandwidth. The measurement of modulation bandwidth consists of stimulating the photodiode with a source of modulated light and measuring the output response current with an electrical receiver. The frequency of the modulation is swept to allow examination of the photodiode over a wide range of modulation frequencies.


- 1 From the Windows **Start** menu on the 86030A computer, select **Programs, Agilent, 86030A Main** to open the software.

NOTE

Do NOT attempt to close the analyzer application until the 86030A system status window says “System Ready.”



- 2 Follow the instructions for the Laser power prompt, then press **OK**.




- 3 When the software is first opened, a modulator auto-bias will automatically be performed, which takes approximately 2 minutes. The modulator is automatically biased to the optimum (quadrature) performance condition.

An auto-bias does not need to be performed before each individual measurement but should be performed for any of the following conditions:

- at least once every eight hours
- if the temperature has drifted more than 3°C from the user calibration temperature
- if the jumper between the 86032A LASER OUTPUT and LASER INPUT has been removed and replaced.

This routine takes approximately two minutes and the results will be displayed on the screen. Refer to “Auto Bias” on page 2-20.



- 4 When the auto bias is finished, click **OK** to close the Modulator Auto Bias window.

The system has finished setup procedures.

Making an Optical to Electrical Measurement

- 1 In the System Modes area, click on **O/E** (the default mode) to set up for an optical to electrical measurement.



- 2 In the Measurement Types area, click on **BandWidth**.
- 3 In the Control Options area, click on **To Setup, New User Cal**.
- 4 The message, “Set 8510 to desired Start Frequency, Stop Frequency, and the Number of Points” appears. To do this:
 - a On the 8510 analyzer under the STIMULUS area, set the Start frequency and the Stop Frequency to the frequency range required for your measurement.
 - b From the STIMULUS MENU, select *NUMBER of POINTS*, then *801*.
 - c From the RESPONSE MENU, select AVERAGING ON and set to 128 points.
- 5 Click **OK** in the application message box.

- 6 Follow the onscreen instructions to configure the test set for calibration, then press **OK**.
- 7 In the Control Options area, click on **Resp-Isol** to perform a response plus isolation calibration.
- 8 Follow the on-screen instructions for the Response portion of the calibration procedure.
- 9 Follow the on-screen instructions for the Isolation portion of the calibration procedure.

The system first takes an uncorrected measurement of the internal O/E converter in the 86032A test set. This raw data along with factory calibration data for the internal O/E are used to construct a calibration file for the system.

You can monitor the System Status area as the calibration is in progress. Once the calibration is completed, you can view the calibration results in the Calibration Information area.


You are now ready to make a bandwidth response measurement.

- 10 Follow the on-screen instructions for the measurement setup.
- 11 From the 8510 RESPONSE menu, adjust the scale to best fit the trace on the screen.
 - a Select *REFVALUE* and use the knob to center the trace around the display line.
 - b Select *SCALE* and decrease the dB/div to expand the trace across the display (approximately 2 dB/div).
 - c Repeat steps a and b to get the best view.
- 12 Select the RESPONSE MENU key, then SMOOTHING ON.
- 13 Save the trace data to an Excel file by selecting **File, Save Data, Excel File**, then, **Form Log Mag**.
- 14 In the Save to Excel dialog box, enter `quick_start` as the trace file name then click **OK**.

You can now view the trace by selecting **File, Graph Excel Data, Form Log Mag** and then **Open** the **Quick_Start** file. Alternately, you can open a session of Excel and view or manipulate the trace file from there.

Or, you can further analyze the trace data by using the controls on the 8510C.

Getting Started
Quick Start



The Calibrations	3-2
Saving and Reusing 86030A Calibration Sets	3-5
O/O Response and Isolation Bandwidth Calibration	3-8
O/E Response and Isolation Bandwidth Calibration	3-11
O/E Response and Match Bandwidth Calibration	3-14
E/O Response and Isolation Bandwidth Calibration	3-23
Agilent 86030A System Example Measurements	3-28
Electrical Mismatch Ripple and its Effects on Measurements	3-29
Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver	3-41
O/E RF Overload Detection Measurement	3-51

Measurement Techniques

The Calibrations

The 86030A software can perform many different types of calibrations depending on your device type and measurement needs. Following is a list of all of the available calibrations.

- **O/O**
 - Bandwidth Measurement
 - Response
 - Response/Isolation
 - Reflection Measurement
 - Response
 - Response/Isolation
- **O/E**
 - Bandwidth
 - Response
 - Response/Isolation
 - Response/Match
 - Reflection
 - Response
 - Response/Isolation
 - Bandwidth & Reflection
 - Response
 - Response/Isolation
- **E/O**
 - Bandwidth
 - Response
 - Response/Isolation
 - Reflection
 - Response
 - Bandwidth & Reflection
 - Response
 - Response/Isolation
 - Reflection Sensitivity
 - Response

- **E/E**

Use the 8510C for electrical calibrations and measurements.

Table 3-1. Purpose and Use of Different Calibration Procedures

Calibration Procedure	Corresponding Measurement	Errors Removed	Standard Procedure
Electrical			
Response	Transmission or reflection measurement when the highest accuracy is not required.	Frequency response	Thru for transmission, open or short for reflection.
Response & Isolation	Transmission of high insertion loss devices or reflection of high return loss devices. Not as accurate as 1-port or 2-port calibration.	Frequency response plus isolation in transmission or directivity in reflection.	Same as response plus isolation std (load).
S11 1-port	Reflection of any one-port device or well terminated two-port device.	Directivity, source match, frequency response	Short, open, and load(s).
S22 1-port	Reflection of any one-port device or well terminated two-port device.	Directivity, source match, frequency response	Short, open, and load(s).
Full 2-port	Transmission or reflection measurements of highest accuracy for two-port devices.	Directivity, source match, load match, isolation, frequency response, each in forward and reverse directions.	Short, open, and load(s). Two loads needed for isolation.
Optical (O, O/O)			
Response	Transmission or reflection measurement when the highest accuracy is not required.	Frequency response	Optical thru for transmission, Fresnel or Reflector for reflection.
Response & Isolation	Transmission of high insertion loss devices or reflection of high return loss devices.	Frequency response, plus isolation in transmission or directivity in reflection.	Same as response plus disconnect cable or turn off laser.
Optical (O/E)			
Response	Transmission measurement	Frequency response	Optical and/or electrical thrus.
Response & Isolation	Transmission of high Insertion loss devices	Frequency response plus isolation	Same as Response plus disconnect cable or turn off laser.
Response & Match	Transmission measurement for devices with large electrical reflectivity.	Frequency response plus electrical mismatch	Same as Response plus short, opens, and loads.

Table 3-1. Purpose and Use of Different Calibration Procedures

Calibration Procedure	Corresponding Measurement	Errors Removed	Standard Procedure
Optical (E/O)			
Response	Transmission or reflection measurements.	Frequency response	Optical and /or electrical thru for transmission, optical load for reflection sensitivity.
Response and Isolation	Transmission of high insertion loss devices.	Frequency response plus isolation	Same as response plus disconnect the cable or turn off the laser.
Note: If cables, connectors, or adapters are removed from the measurement setup that were used in the calibration, their effect must be accounted for by adding a port extension equivalent to the electrical length of the missing component(s).			

Measurement Error Correction for Devices with V Connectors (1.85 mm)

To accurately measure devices with V connectors (1.85 mm), adapt the 2.4 mm electrical cables that are part of the 86030A system, to a 1.85 mm connector. Then perform a measurement calibration on the 86030A system with an 85058 D (1.85 mm) calibration kit. This process will remove the effects of the small reflections from the 2.41/1.85 mm interface.

Saving and Reusing 86030A Calibration Sets

After you have performed a measurement calibration, the 86030A creates a calibration set that is applied to the measurement, reducing systematic errors. To save time with later measurements, you may want to use a previously created calibration set rather than creating a new set.

The 86030A uses the 8510 calibration set registers 1, 2, and 3 to create new calibration sets. If you perform another measurement calibration, the previous calibration set would be overwritten. Therefore, if you want to reuse a calibration set, you must move it out of calibration set registers 1-3 by doing one of the following:

- Move the calibration set to 8510 calibration set register 4, 5, 6, 7, or 8.
- Store the calibration set to a floppy disk.

Each calibration set is calculated based on a particular measurement state. Therefore, the error reduction and resulting measurement accuracy from a calibration is only valid if you use the same measurement settings that were used to create the calibration set.

There are also other variables that can affect measurement accuracy when you are reusing calibration sets:

- Differences in the ambient temperature between when you performed the measurement calibration and when you measured the device under test.
- Differences in the test port cables and accessories you used in the measurement calibration and in the device measurements.

To Save and Reuse Calibration Sets

To save time, you may want to save and reuse a calibration set. Follow these general steps:

- 1 Either move the calibration set to 8510 calibration set registers (4-8) or store the set to a floppy disk.
- 2 Save the measurement settings as an instrument state.

- 3 Reload and/or recall the calibration set and measurement settings.

Move or Store a Calibration Set

- 1 To move the calibration set from 8510 calibration set registers (1-3) to calibration set registers (4-8):
 - a Make sure the calibration set is enabled on the 8510 by pressing CAL, CORRECTION ON, and press CAL SET (1-3).
 - b Press CAL, MORE, MODIFY CALSET, FREQUENCY SUBSET, CREATE & SAVE, CAL SET (4-8).
 - c Repeat this step if you want to save more than one calibration set. For example, if you have performed a response and match calibration, there would be a calibration set in CAL SET 1 and CAL SET 2.
- 2 To store a calibration set to a floppy disk:
 - a On the 8510, press DISC, STORE, CAL SET 1-8, and select the calibration set that you want to store. If you want to store all of the calibration sets, select CALSET ALL.
 - b Press STORE FILE.

Save the Measurement Settings as an Instrument State

- 3 Press SAVE, INST STATE (1-7) to save the measurement settings in an instrument state register.
- 4 If you want to store the instrument state on a floppy disk, press DISC, STORE, INST STATE 1-8, then select the state that you want to store.

Recall the Calibration Set and Measurement Settings

- 5 To recall the measurement settings and the associated calibration set from the 8510 registers:
 - a Press RECALL, INST STATE 1-7 and select the instrument state you want to recall.

- b** Press CAL, CAL SET and select the calibration state that you want to recall.
- 6** To load the measurement settings and the associated calibration set files from a floppy disk and recall them to the 8510:
 - a** Press DISC, LOAD, INST STATE 1-8, then select the state that you want to load.
 - b** Press RECALL, INST STATE 1-7 and select the instrument state you want to recall.
 - c** Press DISK, LOAD, CAL SET 1-7 , then select the set that you want to load.
 - d** Press CAL, CAL SET 1-8 and select the calibration state that you want to recall.

NOTE

If you are recalling calibration sets for a response and match calibration, you must return the sets to CAL SET 1, and CAL SET 2. The analyzer will apply the calibration sets from those two registers for error correction of a response and match measurement.

O/O Response and Isolation Bandwidth Calibration

The following procedure shows you how to make a response and isolation bandwidth calibration.

- 1** In the System Modes area in the Setup Screen, click on **O/O** to setup for an optical to optical measurement.
- 2** In the Measurement Types area, click on **BandWidth**.
- 3** In the Control Options area, click on **New User Cal**.
- 4** The message, “Set 8510 to desired Start Frequency, Stop Frequency, Averaging, and the Number of Points” appears. To do this:
 - a** On the 8510 analyzer under the **STIMULUS** area, set the Start frequency and the Stop Frequency to the frequency range required for your measurement.
 - b** From the **STIMULUS MENU**, select *NUMBER of POINTS*, then select the number of data points, for example, 801 points.
 - c** From the **RESPONSE MENU**, select *AVERAGING ON/restart*, then enter the number of averages. For example, for 128 averages enter 128 x1.
- 5** In the Control Options area, click on **Resp-Isol** to perform a response plus isolation calibration.
- 6** Follow the on-screen instructions to complete the calibration procedure.



O/O Response and Isolation Bandwidth Calibration

The figure below shows the results of an optical to optical measurement of a through line with 0 dB loss. The magnitude of the trace (that is, the vertical axis) is measured in dB. For more information, refer to [“O/O Display Scaling Calculations”](#) on page 5-18.




Figure 3-1. Measurement results of a through line


O/E Response and Isolation Bandwidth Calibration

The following procedure shows you how to make an Optical to Electrical response and isolation bandwidth calibration.

- 1** In the System Modes area in the Setup Screen, click on **O/E** to setup for an optical to electrical measurement.
- 2** In the Measurement Types area, click on **BandWidth**.
- 3** In the Control Options area, click on **New User Cal**.
- 4** The message, “Set 8510 to desired Start Frequency, Stop Frequency, Averaging, and the Number of Points” appears. To do this:
 - a** On the 8510 analyzer under the **STIMULUS** area, set the Start frequency and the Stop Frequency to the frequency range required for your measurement.
 - b** From the **STIMULUS MENU**, select *NUMBER of POINTS*, then select the number of data points, for example, 801 points.
 - c** From the **RESPONSE MENU**, select *AVERAGING ON/restart*, then enter the number of averages. For example, for 128 averages enter 128 x1.
- 5** In the Control Options area, click on **Resp-Isol** to perform a response plus isolation calibration.


O/E Response and Isolation Bandwidth Calibration

- 6 Follow the on-screen instructions for the response portion of the calibration procedure. See figure below.



- 7 Follow the on-screen instructions for the isolation portion of the calibration procedure.

See figure below.




O/E Response and Match Bandwidth Calibration

The 86030A is capable of reducing the mismatch measurement uncertainty of a device under test by utilizing a response and match calibration. The advantage of a response and match calibration is that it compensates for the mismatch of the device under test, providing a more accurate calibration and measurement. Significant reduction of electrical mismatch error results.


For this calibration, you will need to use some of the accessories supplied in the 85056A 2.4 mm Calibration Kit.

The following procedure shows you how to make an Optical to Electrical response and match bandwidth calibration.

- 1** In the System Modes area in the Setup Screen, click on **O/E** to setup for an optical to electrical measurement.
- 2** In the Measurement Types area, click on **BandWidth**.
- 3** In the Control Options area, click on **New User Cal**.
- 4** The message, “Set 8510 to desired Start Frequency, Stop Frequency, Averaging, and the Number of Points” appears. To do this:
 - a** On the 8510 analyzer under the **STIMULUS** area, set the Start frequency and the Stop Frequency to the frequency range required for your measurement.
 - b** From the **STIMULUS MENU**, select *NUMBER of POINTS*, then select the number of data points, for example, 801 points.
 - c** From the **RESPONSE MENU**, select *AVERAGING ON/restart*, then enter the number of averages. For example, for 128 averages enter 128 x1.



5 When the following message appears, click **OK** to continue.




6 In the Control Options area, click on **Resp-Match** to perform a response plus impedance match calibration.



One-Port Calibration on Port 2

- 7 Connect the equipment as shown on-screen, choosing an Open to connect to the end of the 8517B Port 2 cable.



- 8 From the 8510C function keys, press *Open*.

Once a sweep of the trace is completed, the message “*Connect STD then press key to Measure*” appears, and you will notice that the Open function key on the 8510C is now underlined. This indicates that the Open portion of the calibration process is completed and you are ready to continue with a Short.

- 9 Connect the equipment as shown on the screen, choosing a Short to connect to the end of the 8517B Port 1 cable.

- 10 From the 8510C function keys, press *Short*.

Once a sweep of the trace is completed, the message “*Connect STD then press key to Measure*” appears, and you will notice that the Short function key on the 8510C is now underlined. This indicates that the Short portion of the calibration process is completed and you are ready to continue with a Load.

- 11 Connect the equipment as shown onscreen, choosing a 50 ohm load to connect to the end of the 8517B Port 1 cable.

- 12 From the 8510C function keys, press *Loads* then *Broadband*.

Once a sweep of the trace is completed, you will notice that the Broadband function key on the 8510C is now underlined. This indicates that the Load Broadband portion of the calibration process is completed.

- 13 From the 8510C function keys, press *Done Loads*.

- 14 From the 8510C function keys, press *Save 1-Port Cal*.

NOTE

When the 8510C message “Select Calibration Set” appears, *do not* select a cal set to save. This completes the Port 2 portion of the match calibration.

- 15 From the 86030A software, click **OK** to continue with the Port 1 portion of the match calibration.

One-Port Calibration on Port 1

- 16 Repeat [Step 7](#) through [Step 15](#) by attaching the Open, Short, and Load to the 8517B Port 2 instead of Port 1. Refer to [Figure 3-2](#).




Figure 3-2.

Measurement of Port 1 Reflectivity

- 17 Connect the equipment as shown in [Figure 3-3](#) then click **OK**.



Figure 3-3.

Measurement of 86030A Internal O/E Response

- 18 Connect the equipment as shown in Figure 3-4 then click **OK**.




Figure 3-4.

Measurement of Device Under Test

- 19 Connect the equipment as shown in [Figure 3-5](#) then click **OK**.




Figure 3-5.


Once the calibration is completed, the results will be displayed in the User Calibration Information area.

New Device Under Test (DUT)

The disadvantages of a response plus match calibration is that it is a more complicated and lengthy procedure and it is only valid for a particular DUT.

Using the New DUT function, in the Control Options area, repeats only the DUT reflectivity portion of the calibration. This greatly reduces the calibration time when a measurement of a new test device is desired, or if the electrical port match has changed.

The 86030A also provides a capability to mathematically reduce the effects of electrical mismatch. In order to do this, the DUT response information is modified using measurements of the electrical reflectivity of the DUT and the electrical reflectivity of the 86030A. Significant reduction of electrical mismatch error results.



E/O Response and Isolation Bandwidth Calibration

The procedure below shows you how to make an Electrical to Optical response and isolation bandwidth calibration.

E/O Measurement Considerations:

- Modulator measurements require an external polarization controller connected in the test setup. However, the output of the 86030A is keyed to the slow axis of PMF (polarization maintaining fiber), and if the modulator under test is similarly keyed and PMF is used from the laser output to the input of the modulator, the polarization controller may be eliminated. Otherwise setup the equipment as follows and shown in [Figure 3-6 on page 3-26](#):
 - Connect the 86030A LASER OUTPUT to the polarization controller.
 - Connect the polarization controller to the modulator (DUT) input.
 - Connect the modulator (DUT) output to the 86030A OPTICAL RECEIVER INPUT.
 - Connect the 86030A RF OUTPUT through a bias tee (if needed) to the modulator (DUT) RF input.
 - Adjust the bias and the polarization controller for maximum output, as seen on the analyzer screen.
 - Modulator measurement response is dependent on both the RF drive level and the amplitude of the signal at the modulator output. To make comparisons between modulators, both signal levels should be controlled.
 - Set the RF drive level and the optical power at the modulator (DUT) output to 1 mW.
 - The RF drive level to the modulator (DUT) should be ± 0.5 mW across the band. If the drive varies more than ± 0.5 mW, try shortening the RF cable or making a series of measurements over smaller ranges.
- 1 In the System Modes area in the Setup Screen, click on **E/O** to setup for an electrical to optical measurement.
 - 2 In the Measurement Types area, click on **BandWidth**.
 - 3 In the Control Options area, click on **New User Cal**.
 - 4 The message, "Set 8510 to desired Start Frequency, Stop Frequency,

E/O Response and Isolation Bandwidth Calibration

Averaging, and the Number of Points” appears. To do this:

- a On the 8510 analyzer under the STIMULUS area, set the Start frequency to and the Stop Frequency to the frequency range required for your measurement.
 - b From the STIMULUS MENU, select *NUMBER of POINTS*, then select the number of data points, for example, 801 points.
 - c From the RESPONSE MENU, select *AVERAGING ON/restart*, then enter the number of averages. For example, for 128 averages enter 128 x1.
- 5 In the Control Options area, click on **Resp-Isol** to perform a response plus isolation calibration.
 - 6 Follow the on-screen instructions to perform the Response portion of the calibration procedure. See figure below.



- 7 Follow the on-screen instructions to perform the Isolation portion of the calibration procedure. See figure below.



E/O Response and Isolation Bandwidth Calibration

- 8 The calibration is complete. Connect the E/O device under test. For example, the figure below shows the test setup for a modulator measurement.





Figure 3-6. Setup for a Modulator Measurement

The figure below shows the results of a measurement of an external E/O modulator. The magnitude of the trace (that is, the vertical axis) is measured in dB. For more information, refer to [“E/O Display Scaling Calculations”](#) on page 5-17.



Agilent 86030A System Example Measurements

This section provides example measurements. These examples are not intended to cover all applications of the systems.

This section contains the following:

- Electrical mismatch ripple and its effects on measurements
- Optical reflection measurement between a splice and a cleave
- Bandwidth and reflection measurement of a lightwave source
- Magnitude response and deviation from linear phase for an optical receiver

CAUTION

Costly replacement of an entire lightwave assembly will result from damage to an optical test port connector. Keep optical cables connected to the test ports to protect the connectors from damage.

CAUTION

When you use improper cleaning and handling techniques, you risk expensive system repairs, damaged cables, and compromised measurements. Repair of damaged connectors due to improper use is not covered under warranty.

Clean all cables before applying to any connector. Refer to [“Choosing the Right Connector” on page 2-33](#) and to [“Cleaning Connectors” on page 2-40](#).

WARNING

Do NOT under any circumstances, look into the optical output of any fiber/device attached to the output while the laser is in operation. Refer to [“Laser Safety Considerations” on page 2-30](#) for more information.

Electrical Mismatch Ripple and its Effects on Measurements

Mismatch ripple is caused by a mismatch between the impedance of the device under test and the nominal 50 ohm input port on the 8517B test set. Depending on the phase of the desired (incident signal) and undesired signal (three times the path length of the reflected signal), the mismatch error signal either adds or subtracts to the magnitude of the desired signal. This phenomenon, called mismatch ripple, causes the trace to periodically deviate above and below the correct value. For devices that have high electrical reflectivity, the ripple is quite apparent. For devices that are well matched to 50 ohms, the mismatch ripple is much less visible.

[Figure 3-7](#) will help to explain the effects of the trace ripple.

Electrical Mismatch Ripple and its Effects on Measurements




Figure 3-7. Effects of Electrical Mismatch Ripple

reflec

Electrical Mismatch Ripple and its Effects on Measurements

Spacing between successive peaks of this mismatch ripple is described by the equation:

$$\text{ripple period Hz} = \frac{\text{Velocity in cable}}{2 \cdot L_{\text{cable}}}$$

As an example, the 85133-60017 cable has a physical length of approximately 1 meter and a velocity of $2 \times 10^8 \frac{m}{s}$. In this case,

$$\text{ripple period Hz} = \frac{2 \times 10^8 \frac{m}{s}}{2 \cdot 1 \text{ meter}} = 1 \times 10^8, \text{ or } 100 \text{ MHz}$$

For devices that have high reflectivity in the electrical port, the addition of a 6 dB attenuator on the electrical test port will substantially reduce the trace ripple. (A 6 dB attenuator is supplied in the verification kit.) However, there is a trade off of system sensitivity since the signal to noise floor will be reduced by 6 dB. Refer to [“801 Data Points and No Attenuation Added” on page 3-35](#) and to [“Ripple Measurement, 201 Points, with 6 dB Attenuator” on page 3-38](#).

The appearance of the trace ripple is also affected by the number of points selected for measurement.

When 801 points is used for a 50 GHz frequency span, there is approximately 62.5 MHz between data points. See [Figure 3-8](#).

When 201 points is used for a 50 GHz frequency span, there is approximately 250 MHz between data points. Refer to [“201 Data Points and 6 dB Attenuator” on page 3-38](#).

Electrical Mismatch Ripple and its Effects on Measurements




Figure 3-8. The Number of Points for Measurement Effect Mismatch Ripple

Compare the trace data taken with 201 points versus the trace data taken with 801 points. Notice that the 201 point trace has more of a sawtooth appearance. When fewer data points are taken, it affects your ability to discern the response of the device under test (DUT) from the effects of the ripple.

To demonstrate the effects of the system ripple, we will measure the 83440D lightwave detector supplied in the verification kit. The lightwave detector was selected for this example since it has high reflectivity (reflectivity ≈ 1) in the electrical port which will show the worst-case ripple.

Ripple Measurement, 801 Points, No Attenuator

The first measurement example will use the maximum number of data points allowed by the network analyzer, but with no attenuation on the electrical port of the DUT.

O/E Calibration

- 1 Connect a BNC 50 ohm load on Port 1 Bias on the 86032A rear panel.
A BNC 50 ohm load can be found in the verification kit.
- 2 In the System Modes area, click on **O/E** to setup for an optical to electrical measurement.
- 3 In the Measurement Types area, click on **BandWidth**.
- 4 In the Control Options area, click on **New Cal**.
- 5 Follow the on-screen instructions to configure and perform the test set calibration.
- 6 The message, “Set 8510 to desired Start Frequency, Stop Frequency, and the Number of Points” appears. To do this:
 - a On the 8510 analyzer under the STIMULUS area, set the Start frequency to 45 MHz and the Stop Frequency to 50 GHz.
 - b From the STIMULUS MENU, select *NUMBER of POINTS*, then *801*.
- 7 In the Control Options area, click on **Resp-Isol Cal**.



**Detector
Response
Measurement**

- 8 When the calibration is complete, connect the 83440D lightwave detector as shown. Remember to connect the 87421A power supply (found in the verification kit) to the DC bias port of the detector.

NOTE

The 83440D Option 050 photodiode that is in the N1012A verification kit is internally terminated, and will not show as dramatic a change as the standard 83440D shown in this section.



- 9 From the 8510 RESPONSE menu, adjust the scale to display the entire trace with the best sensitivity.
 - a Select *REF VALUE* and use the up and down arrow keys to center the trace around the display line.
 - b Select *SCALE* and decrease the dB/div to expand the trace across the display (approximately 2 dB/div).
 - c Repeat [Step a](#) and [Step b](#) to scale the trace across the display.
 - d Note the REF VALUE _____ and SCALE _____ as these set-

tings will be used for the following comparison measurements.




Figure 3-9. 801 Data Points and No Attenuation Added

- 10** Save the trace data to an Excel file by selecting **File, Save Data, Excel File, Form Mag Log**.
- 11** In the Save dialog box, enter the file name `ripple_801pts_nopad`.

Once the following measurement methods had been completed and the data saved, you can compare the results of the different measurement methods.

Ripple Measurement, 801 Points, with 6 dB Attenuator

For devices that have a high reflectivity in their electrical port, adding an attenuator will reduce the effects of electrical mismatch ripple. However, you trade off system sensitivity for the reduced ripple since the signal to noise floor will be reduced by 6 dB.

- 1 Connect a 6 dB attenuator to the end of the 8517B Port 1 cable that connects to the electrical port of the 83340D lightwave detector.

The attenuator must be present for both the calibration and measurement procedures. Keep the attenuator and cable mated during the entire calibration and measurement procedure.

NOTE

The addition of the 6 dB attenuator to the test port cable causes this port to have a dc connection to ground. Insure that your DUT is compatible with having a dc path to ground.




Figure 3-10. O/E measurement with 6 dB attenuator

- 2 Repeat “O/E Calibration” on page 3-33.
- 3 Repeat “Detector Response Measurement” on page 3-34. In Step 11, enter the file name ripple_801pts_6dbpad.




Figure 3-11. 801 Data Points and 6 dB Attenuator

Ripple Measurement, 201 Points, with 6 dB Attenuator

The appearance of trace ripple is affected by the number of data points used for the measurement. When 201 point is selected for a 50 GHz span, there is approximately 250 MHz between data points. Thus, when viewing the trace data, it makes it difficult to discern the effects of the system ripple and the device characteristics.

- 1 Repeat “O/E Calibration” on page 3-33. In Step b of Step 6, select 201 points.
- 2 Repeat “Detector Response Measurement” on page 3-34. In Step 11, enter the file name ripple_201pts_6dbpad.

Compare the trace data taken with 201 points versus the trace data taken with 801 points. Notice that the 201 point trace has more of a sawtooth appearance. When fewer data points are taken, it affects your ability to discern the response of the device under test (DUT) from the effects of the ripple.




Figure 3-12. 201 Data Points and 6 dB Attenuator

Ripple Measurement, 801 Points, Smoothing On, and 6 dB Attenuator

Turning Smoothing on can also help reduce trace ripple. Smoothing averages the points within the specified span. For this example, we will smooth the trace using 0.3% of the trace width. In this case, we have a 50 GHz trace width with each segment being 0.3% of 50 GHz or 150 MHz. If the DUT has features that do not vary significantly over a 150 MHz window, accurate measurements will be made. If this is not the case, then some distortion of the measurement will occur. Care should be taken when using this function, as important trace data may be masked by the effects of smoothing.

- 1 Repeat “[O/E Calibration](#)” on page 3-33. In [Step b](#) of [Step 6](#), select 801 points.
- 2 Repeat “[Detector Response Measurement](#)” on page 3-34. In [Step 9](#), select Smoothing On and set to 0.3% of span. In [Step 11](#), enter the file name ripple_801pts_smoothingon_6dbpad.

Use of Response and Match Calibration


The 86030A also provides a capability to mathematically reduce the effects of electrical mismatch. In order to do this, the DUT response information is modified using measurements of the electrical reflectivity of the DUT and the electrical reflectivity of the 86030A. Significant reduction of electrical mismatch error results.

The disadvantage of a response plus match calibration is that it is a more complicated and lengthy procedure.

A response and match calibration is only valid for a particular DUT. If a measurement of a new DUT is desired, or if the electrical port match has changed, clicking on New DUT, in the Control Options area, will repeat the DUT reflectivity portion of the calibration.

- 1 Perform a Response and Match calibration. Refer to “[Follow the on-screen instructions for the isolation portion of the calibration procedure.](#)” on page 3-13.
- 2 Repeat “[Detector Response Measurement](#)” on page 3-34. In [Step 11](#), enter the file name ripple_matchcal.

Electrical Mismatch Ripple and its Effects on Measurements



Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver

This example measures a lightwave receiver's transfer characteristics and deviation from linear phase. A receiver's transfer function is expressed in terms of receiver slope responsivity. This is the ratio of the RF current out to the intensity-modulated optical power in and is expressed in amp/watt or dB referenced to 1 A/W.

Calibrating the system

- 1 Perform an O/E Bandwidth calibration. [Refer to "O/E Response and Isolation Bandwidth Calibration" on page 3-11.](#)

Connecting the device

- 2 When the calibration is complete, connect the device as shown in the Measure window.



Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver

The 8510C displays the transfer characteristics of the lightwave receiver as shown in [Figure 3-13](#). The measured device is an amplified photodiode receiver.

- 3 To locate the maximum amplitude of the receiver, press, *MARKER, MORE*, then *MAXIMUM*.




Figure 3-13. Responsivity of a Photodiode Receiver

Measuring Deviation from Linear Phase

The analyzer can measure and display phase over the range of -180° to $+180^\circ$. As phase changes beyond these values, a sharp 360° transition occurs in the displayed data. The electrical length effect can be removed to view the deviation from linear phase. To remove length effect, the analyzer mathematically implements a function similar to the mechanical “line stretchers” of earlier analyzers. This feature simulates a variable length of lossless transmission line. The simulation can be added to or removed from the analyzer’s internal reference port to compensate for the length of interconnecting cables, and so forth.

In this example, the electronic line stretcher measures the electrical delay of a photodiode receiver.

- 1 In the *RESPONSE* area, press *MENU, ELECTRICAL DELAY*.

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver**2** Enter the delay time.

Pressing the *AUTO DELAY* function key on the 8510C will correctly perform a delay measurement if the device length is within the alias-free range of the measurement. The alias-free range is the range where you can correctly measure a response.

3 To view the insertion phase response of the photodiode receiver, in the *FORMAT* area, press *PHASE*.

The modulation phase of the photodiode receiver is shown in [Figure 3-14](#).




Figure 3-14. Modulation Phase Response of a Photodiode Receiver

The analyzer measures and displays phase over the range of -180° to $+180^\circ$. As phase changes beyond these values, a sharp 360° transition occurs in the displayed data. The Δ measured between two adjacent frequency points must be $<180^\circ$. If the phase is $>180^\circ$, incorrect delay information may result. For example, the first set of frequency points shown in [Figure 3-14](#) has a $\Delta = <180^\circ$. If the delta is $<180^\circ$ between adjacent frequency points, the network analyzer will be successful in making group delay measurements on the DUT.

[Figure 3-15](#) illustrates an example where the delta is $>180^\circ$. In this example there is a data point measuring -165° and the following data point measuring -5° (but on a different tooth of the sawtooth waveform). In order to compare the absolute phase difference between these two points, you must translate the -165° upward by 360° (one revolution on the cartesian scale). Resulting in

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver

a translated phase value of $+195^\circ$. The difference between the points can now be compared, $195^\circ - -5^\circ = 200^\circ$. Since the delta between points is $> 180^\circ$, this situation will lead to erroneous values while making delay measurements.




Figure 3-15. Phase Samples

To measure a correct phase response, the electrical delay must be within the alias free range.

- 4 Calculate the alias-free range for the measurement parameters of the analyzer.

This range can be determined by:

$$AFR = \pm \frac{1}{2(\Delta f)}$$

Δf = frequency spacing between points

$$\Delta f = \frac{\text{start frequency} - \text{stop frequency}}{\text{number of points} - 1}$$

For example, if:

start frequency = 130 MHz

stop frequency = 20 GHz

number of data points = 201

then:

$$AFR = \pm \left[\frac{1}{\left(\frac{2(20 \times 10^9 - 130 \times 10^6)}{201 - 1} \right)} \right] = \pm 5 \text{ ns}$$

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver

This means that the alias-free range is ± 5 ns. **Figure 3-16** shows a time domain response from an electrical delay of 8 ns with a ± 5 ns alias free range. Notice the response repeats every 10 ns. The correct response is at 8 ns, but the auto delay function on the 8510C would give delay information of -3 ns since it is closest to zero.

If the electrical delay is set to the true value, the phase response is correct, but the time response is only correct in 1 alias free range around the delay time.




Figure 3-16. Time Domain Response with the Alias Free Range

Alias Free Range

The number of data points may be increased to obtain an alias-free range larger than the electrical length of the device. If the number of data points is increased to 401, then the alias-free range is calculated as follows.

$$AFR = \pm \left[\frac{1}{\left(\frac{2(20 \times 10^9 - 130 \times 10^6)}{401 - 1} \right)} \right] = \pm 10 \text{ ns}$$

Note

The frequency span can also be made smaller to increase the alias-free range.

Determining Electrical Length

Before a calibrated measurement is performed, a delay measurement may be taken with a small frequency span and compared to the calculated alias-free range. If the delay measurement result is longer than the alias-free range, the measurement parameters or electrical delay value needs to be changed.

- 5** To narrow the span, in the *STIMULUS* area, press *CENTER 2 [G/n]* then *SPAN 100 [M/u]*.

A new calibration can be done at this time. Without a calibration, the delay value may be off by ± 5 ns.

Note

A frequency span of 100 MHz with 201 measurement points gives an alias-free range of 1 μ s (approximately 300 meters). As the frequency span decreases, the alias-free range increases.

- 6** To measure delay, in the *RESPONSE MENU*, press *DELAY*, then *AUTO DELAY*.
Read the value from the analyzer display.
- 7** To remove delay measurement noise in the *RESPONSE* area, press *MENU*, *AVERAGING ON/RESTART*, then *SMOOTHING ON 20 [x1]*.
Record the delay value_____.
- 8** In the *MENUS* area, press *DOMAIN*, then *FREQUENCY*.
- 9** To change the parameters back to the original setup, in the *STIMULUS* area, press *START 130 [M/u]*, then *STOP 20 [G/n]*.
- 10** In the *FORMAT* area, press *LOG MAG/*.
When parameters are changed, another measurement calibration must be performed.
- 11** Perform an O/E Bandwidth calibration.
- 12** When the calibration is complete, connect the device between the optical and electrical test ports as shown on the Measure window.



13 To measure the delay with the Auto Delay function, in the FORMAT area, press PHASE

14 In the RESPONSE area, press MENU, AUTO DELAY, then ELECTRICAL DELAY.

Notice the delay and phase information on the analyzer display.

If the electrical delay of the device is longer than the alias-free range, the Auto Delay function will not give the correct electrical delay, and the phase information will be offset by $(\text{difference of correct and incorrect delays}) \times (\text{start frequency}) \times (360^\circ)$.

Enter the electrical delay value recorded in [Step 7](#).

15 Turn the front panel knob to change the electrical length until the best flat line is achieved as shown in [Figure 3-17](#).

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver




Figure 3-17. Electrical Length Added

Note

The drop in the trace at the beginning of the sweep in [Figure 3-17](#) is because of a transition from $+180^\circ$ to -180° . The receiver measured is an inverting receiver. The phase of the output is inverted 180° from the input. To view the phase response that is out 180° , you may offset the phase reference.

- 16** To offset the phase by 180° , in the RESPONSE area, press MENU then *PHASE OFFSET* 180 [x1].

[Figure 3-18](#) shows the result of a phase offset.

Magnitude Response and Deviation From Linear Phase of a Lightwave Receiver




Figure 3-18. Phase Offset by 180°

O/E RF Overload Detection Measurement

High-gain O/E converters may supply too much power to 8517B Port 1 inducing an RF overload condition. This may cause amplitude measurement errors to occur. The following procedure will help you to determine if any signals within the measured frequency range could cause an overload condition.

- 1 Perform an O/E Response and Match calibration. Refer to “O/E Response and Isolation Bandwidth Calibration” on page 3-11.
- 2 Connect the DUT as shown below and wait until an entire sweep of the trace has been taken.



- 3 In the 8510C Menu area, press DISPLAY, DATA and MEMORIES, DATA → MEMORY # to store the active trace.

O/E RF Overload Detection Measurement

4 From the Display menu, press *MATH OPERATIONS*, and select *DIVIDE (/)* for the active memory register.

5 From the DISPLAY menu, press *MATH (/)* so that it is underlined.

This operation normalizes the memory to the data. This is useful for ratio comparisons between two traces, for example, measurements of gain or attenuation.

6 In the Response area, press SCALE and enter 1 x1 to set the magnitude scale to 1 dB per division.

7 From the 50 GHz LCA software, click on the **Tools** menu then **Modify Test Set**.

8 In the Modify Test Set dialog box, enter **9** dBm in the Set Laser Output Power box (that is, set the power to 1 dB lower than the value displayed in the Current Laser Output Power box) and then click **Modify Power**.

9 Monitor the change of the stored trace on the 8510C display. For the 1 dB decrease in optical power, you should see a 2 dB decrease in electrical power (that is, 2 divisions) across the entire trace. Any portion of the trace that doesn't drop by 2 dB indicates that there is an overload condition at that point.

10 If an overload condition is detected, you will need to reduce the input power to the point where a 1 dB optical change results in a 2 dB electrical change.

11 Once you have verified that an overload condition does not exist, set the Laser Output Power to the highest possible power without causing an overload condition.

86030A Remote Operation Overview	4-3
COM Fundamentals	4-5
Getting a Handle to the Server Object	4-9
Configuring for DCOM Programming	4-12
COM Data Types	4-15
Tutorial Using 86030A Remote Operation	4-18
System Properties	4-29
System Methods	4-32
Data Methods	4-34
Network Analyzer Methods	4-39
Calibration Methods	4-41
86032A Testset Methods	4-77
Enumerated Values	4-80
Optical Test Set Error and Action Messages with Descriptions	4-84
System Error and Action Messages with Descriptions	4-86
Network Analyzer Error and Action Messages with Descriptions	4-91
Error Codes and Error Handling	4-94

Remote Operation

Chapter Overview

This chapter includes the following sections for describing the 86030A remote operation and showing you how you can use it to automate measurements on the lightwave component analyzer.

- 86030A Remote Operation Overview
- COM Fundamentals
- Getting a Handle to the Server Object
- Configure for DCOM Programming
- COM Data Types
- 86030A Remote Operation Tutorial
- 86030A Server API Overview
- List of Available Commands
- Description of Available Commands

The tutorial section contains information that show you how to do the following:

- Connect to the 86030A server
- Perform measurements
- Retrieve data
- Handle any errors

This chapter also introduces some COM fundamentals for the beginning COM programmer. Information on configuring DCOM to work with the 86030A and a client or controlling PC is also included. You can see most of the concepts described in this chapter by looking at the example program that comes with this system. The example program is on the client software CDROM and is installed on the client PC along with the 86030A client software. This document gives the perspective of the Visual Basic programmer. All example code and references are to the Visual Basic development environment.

86030A Remote Operation Overview

The 86030A system includes a dedicated computer that contains the analyzer remote operation server. This server contains an API that allows you to operate the 86030A remotely, using your own computer and the programs that you have created. The graphic below shows the configuration for the 86030A system computer, your computer (client computer), and the connecting LAN. This configuration is used to isolate the 86030A from the your company's intranet. Refer to [“Step 6. Configure for Remote Operation” on page 1-12](#) for more information.




Figure 4-1. Configuration for 86030A Remote Operation

NOTE

A direct connection between the 86030A and private LAN requires a cross-over cable. The preferred connection method uses a cross-over hub or LAN hub.

The 86030A software is designed as a standalone COM compliant automation server. Therefore, the terms “server” and “object” are used interchangeably in this chapter.

The 86030A server supports only Synchronous methods. Each method of the server blocks until it has completed the command execution. That is, calls do not return until the server has finished executing the desired request.

At the end of this chapter there is a list of the available commands that you can use for creating programs to control the 86030A system and to perform measurement calibrations.

NOTE

It is always good practice to verify that the laser is on before making a measurement. See the `gTestSetup` command. If a program starts the `LCA86030Amain` application remotely, it is important to insure that there are no previous `LCA86030Amain` programs running on the server computer. Failure to end the `86030Amain` program can lead to unreliable operation. If you are in doubt, use the NT task manager on the server computer to end all `86030Amain` applications prior to running the remote program.

COM Fundamentals

The following terms are discussed in this section:

- Server Object
- Methods
- Properties
- Events

NOTE

The information in this section is intended for an experienced SCPI programmer transitioning to COM programming. This is NOT a comprehensive tutorial on COM programming.

Server Object

The 86030A system computer functions as a remote automation server. The server contains the 86030A measurement automation application structure of a single programmable object. All of the methods and properties discussed in this chapter are associated with this one server object.

In SCPI programming, you must first select a measurement before making any settings. With COM, you first get a handle to the object (server) and refer to that object in order to change or read settings on the 86030A system.

For more information on working with objects, see [Getting a Handle to an Object](#).

The server IP settings come from the factory as follows:

IP Address	192.169.000.002
Subnet Mask	255.255.255.000
Default Gateway	192.168.000.001

Methods

A method is an action that is performed on the 86030A system server object. In the following example, SysInit is a method that applies to the server (object). The SysInit method is shown to initialize the 86030A system.

```
Sub InitSystem()  
serverSysInit  
End Sub
```

Properties

A property is an attribute of the server object, defining one of the object's characteristics such as start frequency, stop frequency, or number of points. To change the characteristics of the server object, you change the values of its properties. The server properties should be viewed as the 86030A measurement state.

To change the value of a property, follow the reference to 86030A server object with:

- a period (.)
- the property name
- an equal sign (=)
- the new property value

For example, the following statement sets the number of averages on the analyzer to 32 averages at each point.

```
sLCA.Averaging=32
```

You can also read the current value of a property. The following statement reads the current Averaging setting for the analyzer in to the variable intAverages.

```
IntAverages=sLCA.Averaging
```

Some properties cannot be set. Later in this chapter, there is a listing for each property that indicates if you can:

- Set and read the property (Write/Read)
- Only read the property (Read-only)

Events

An event is an action recognized by the 86030A server object. In the Windows operating system, the applications respond to user-initiated events such as mouse moves and mouse clicks. A mouse click produces an event that the programmer can either ignore or handle by providing an appropriate subroutine like this:

```
Sub DoThis_onClick  
Perform something  
End Sub
```

If this subroutine were in your program and the mouse-click event occurred on your PC, it would generate a “Callback” to the client and interrupt whatever it was doing and handle the event.

The 86030A system supports the following single event.

ERRHANDLER

This event is used to notify you when an error has been encountered by the system. For example, if a method of the server is called and an error occurs while executing the method, the event ERRHANDLER is initiated which sends a message to the client (controlling) computer. For a definition of the ERRHANDLER event refer to “[Public Event ERRHANDLER\(strERROR As String, intErrorCode As enumStatus\)](#)” on page 4-94.

If you decide to use the COM event ERRHANDLER to get a callback, your program must do two things:

1 Subscribe to events.

You must tell the application object that you are interested in receiving event callbacks. This process is called subscription.

In Visual Basic, this is done by including “WithEvents” in the declaration statement. The declaration below dimensions an Application object (myLCA) and subscribes to the event(s) produced by the Application.

```
Dim WithEvents myLCA as A86030_LCAServer.A86030Sync
```

2 Implement the Event Handler.

In Visual Basic (VB), click on the object window (upper left pane). Find the Application object and check it. The event interface ERRHANDLER will appear in the upper right pane. As you click on the event, VB supplies the first

Remote Operation

COM Fundamentals

line of code. You fill in the rest of the handler routine to service the event. The following is an example of an event handler subroutine responding to the ERRHANDLER event.

```
Private Sub myLCA_ERRHANDLER (strERROR As String, intEr-  
rorCode As enumStatus)  
` Programmers Code goes here to respond to any errors  
End Sub
```

Getting a Handle to the Server Object

The following topics are discussed in this section:

- What is a Handle
- Declaring an Object Variable
- Assigning an Object Variable

What is a Handle

In SCPI programming you must first select a measurement before changing or reading settings. In COM programming the 86030A, you first get a handle to the server object and refer to that object to change or read its settings.

NOTE

This process is also called "getting an instance of an object", and "returning an object." In this manual, "object" refers to the 86030A server, residing on the 86030A system computer.

There are two steps for getting a handle to the server object:

- 1 Declaring a variable as an object.
- 2 Assigning an object to the variable.

Declaring a Variable As an Object

Use the Dim statement or one of the other declaration statements (Public, Private, or Static) to declare a variable. The type of variable that refers to an object must be a Variant, an Object, or a specific type of object. For example, all three of the following declarations are valid:

- `Dim sLCA`
- `Dim sLCA As Object`
- `Dim sLCA As A86030_LCAServer.A86030Sync`

Getting a Handle to the Server Object**NOTE**

If you use a variable without first declaring it, the data type of the variable is Variant by default.

If you know the specific object type, you should declare the object variable as that object type. Declaring specific object types provides automatic type checking, faster code, and improved readability.

A reference to the 86030A automation server should look like one of the following:

- **Dim sLCA As A86030_LCAServer.A86030Sync**
- or
- **Public sLCA As A86030_LCAServer.A86030Sync**

Assigning an Object to a Variable

The only object to assign to a variable is the Application object (the 86030A Lightwave Component Analyzer). When assigning an object to a variable, use the Set keyword before the object variable that was previously declared. In the following example, “sLCA” is the variable we declared in the previous example. So we assign the current A86030_LCAServer Application to “sLCA.”

Because the A86030_LCAServer object is the Application server, you must use the CreateObject keyword with the (classname, server name) parameters.

- classname for the analyzer object is always **“A86030_LCAServer.A86030Sync”**.
- server name corresponds to the name given to the PC in the 86030A system. By default this name is **“XXXLWD”**. Where **“XXX”** is a set of unique characters assigned at the factory.

For example, the following statements would create an instance of the Analyzer object.

```
Dim sLCA as A86030_LCAServer.A86030Sync
Set sLCA = CreateObject (“A86030_LCAServer.A86030Sync”, “XXXLWD”)
```

NOTE

These statements will start the 86030A application if it is not already running on your instrument.

Once you have created an object variable, you can refer to it exactly the same as you would refer to the corresponding object. You can set or return the properties of the object or use any of its methods. For example:

sLCA.SysStartUp

At this point the programmer is connected to the server that resides on the 86030A computer. By using the methods and properties of the server, the programmer can access the functionality of the 86030A system to perform calibrations and measurements.

Refer to [“Overview of the 86030A Server API” on page 4-24](#) for a complete list of properties and methods supported by the 86030A server

Configuring for DCOM Programming

The Distributed Component Object Model (DCOM) refers to accessing the analyzer application from a remote PC. The Component Object Model (COM) refers to accessing the analyzer application from the analyzer's system server. However, this last method of access is not supported for the 86030A LCA.

Before developing or running a DCOM program, you should first establish communication between your PC (client PC) and the 86030A system server. Then load the 86030A Client Software on the client PC and the 86030A type library is registered automatically.

NOTE

Your programming environment may require you to set a reference to the type library on the client PC.

This section discusses the following topics on DCOM programming:

- Access Concepts
- Access Procedures

Access Concepts

Agilent 86030A Lightwave Component Analyzers (LCA) are shipped from the factory such that Everyone has permission to launch and access the 86030A application via COM/DCOM. The term Everyone refers to a different range of users depending on whether the 86030A is a member of a Domain or Workgroup (it must be one or the other; not both).

Workgroup

A workgroup is established by the LCA administrator, declaring the workgroup name and declaring the LCA as a member of the workgroup. A workgroup does not require a network administrator to create it or control membership.

Everyone includes only those users who have been given logon accounts on the client PC.

By default, the LCA is configured as members of a workgroup named WORKGROUP.

NOTE

For DCOM access, the user's log-on account name and password must match their PC logon account name and password EXACTLY.

Domain

A domain is typically a large organizational group of computers. Network administrators maintain the domain and control which machines have membership in the domain.

Everyone includes those people who have membership in the domain. In addition, those with logon accounts can also access the LCA.

In summary:

A Workgroup requires no maintenance, but allows DCOM access to only those users with a log-on account for the LCA.

A Domain requires an administrator, but all members of the domain are automatically allowed DCOM access to the LCA.

The next level of security is to allow only selected (not Everyone) domain and workgroup users DCOM Access and Launch capability of the analyzer.

Access Procedures

NOTE

Before performing this procedure, the user must first have a log-on account on the client PC.

This procedure is used for the following:

- Allowing only selected users remote (DCOM) Access and Launch capability to the analyzer. (Launch capability is starting the analyzer application if it is not already open.)
- Verifying you have DCOM access to the analyzer.

Perform the following steps for both Access and Launch capabilities:

- 1 On the LCA, click the Windows Start button.
- 2 Click Run.
- 3 In the Open box, type dcomcnfg.

Remote Operation
Configuring for DCOM Programming

- 4 Click OK.
- 5 In the Distributed COM Configuration Properties window, click on A86030_LCAServer in the Applications list.
- 6 Click Properties and select the Security tab.

Access Capability The following steps configure the LCA to grant specific users DCOM access to the LCA application:

- 1 In the Agilent LCA Series Properties dialog box, click the Security tab.
- 2 Click Use custom access permissions, Edit.
- 3 In Registry Value Permissions, select Everyone.
- 4 Click Remove, Add.
- 5 In Add Users and Groups select the name(s) to have access to the LCA application.
- 6 Click Add, OK.

**Launch
Permission**

The following steps configure the LCA to allow selected users to Launch (start) the LCA application:

- 1 Click Use custom launch permissions, Edit.
- 2 In Registry Value Permissions, select Everyone.
- 3 Click Remove, Add.
- 4 In Add Users and Groups select the name(s) to have access to the LCA application.
- 5 Click Add, OK.
- 6 In the Agilent LCA Series Properties dialog box, click the Identity tab.
- 7 Click The interactive user. This function allows access to the GUI interface.

COM Data Types

The 86030A system server uses several data types to communicate with the client (customer) computer. Before using a variable, you should declare the variable as the type of data it will store. This will save memory and usually gain faster access. The following are the most common data types:

- Long Integer
- Single Precision (Real)
- Double Precision (Real)
- Boolean
- String
- Object
- Enumeration
- Variant

Long	Long integer variables are stored as signed 32-bit (4-byte) numbers ranging in value from -2,147,483,648 to 2,147,483,647.
Double	Double-precision floating-point variables are stored as IEEE 64-bit (8-byte) floating-point numbers ranging in value from -1.79769313486232E308 to -4.94065645841247E-324 for negative values and from 4.94065645841247E-324 to 1.79769313486232E308 for positive values.
Single	Single-precision floating-point variables are stored as IEEE 32-bit (4-byte) floating-point numbers, ranging in value from -3.402823E38 to -1.401298E-45 for negative values and from 1.401298E-45 to 3.402823E38 for positive values.
Boolean	Boolean variables are stored as 16-bit (2-byte) numbers, but they can only be True or False. Use the keywords True and False to assign one of the two states to Boolean variables.

COM Data Types

When other numeric types are converted to Boolean values, 0 becomes False and all other values become True. When Boolean values are converted to other data types, False becomes 0 and True becomes -1.

String String variables hold character information. A String variable can contain approximately 65,535 bytes (64K), is either fixed-length or variable-length, and contains one character per byte. Fixed-length strings are declared to be a specific length. Variable-length strings can be any length up to 64K, less a small amount of storage overhead.

Object Object variables are stored as 32-bit (4-byte) addresses that refer to objects within the analyzer or within some other application. A variable declared as Object is one that can subsequently be assigned (using the Set statement) to refer to the actual analyzer object.

Enumerations Enumerations (Enum) are a set of named constant values. They allow the programmer to refer to a constant value by name. For example:

```
Enum DaysOfWeek
```

```
Sunday = 0
```

```
Monday = 1
```

```
Tuesday = 2
```

```
Wednesday = 3
```

```
Thursday = 4
```

```
Friday = 5
```

```
Saturday = 6
```

```
End Enum
```

Given this set of enumerations, the programmer can then pass a constant value as follows:

```
SetTheDay (Monday)
```

rather than

```
SetTheDay (1) where the reader of the code has no idea what the value 1 refers to.
```

However, the analyzer returns a long integer, not the text.

```
Day = DaysofWeek (today) `Day=1
```

Variant If you don't supply a data type, the variable is given the Variant data type. The Variant data type can represent many different data types in different situations.

The analyzer provides and receives Variant data in several instances because there are programming languages that cannot send or receive "typed" data. Variant data transfers at a slower rate than "typed" data.

Tutorial Using 86030A Remote Operation

The example programs are a great place to start when you are learning to program the 86030A system. However, these programs are not warranted by Agilent Technologies and are intended to serve only as examples to aid you in learning the 86030A remote operation interface. The tutorial shows you how to do the following steps.

- 1** Connect to the 86030A server.
- 2** Initialize the server and the 86030A system.
- 3** Configure the 86030A system using the server.
- 4** Perform measurements using the remote operation interface.
- 5** Retrieve measurement data.
- 6** Check for any encountered errors.

The flow chart on the next page shows a suggested program sequence for operating the 86030A system remotely.




Figure 4-2. Suggested Program Sequence

Step 1. Connect to the 86030A Server

The Visual Basic editor must be able to see the A86030_LCAServer.TLB file. This file contains the definition of the server interface.

- 1 To include this type library in your Visual Basic application, click Project, References, Browse.
 - 2 Navigate to C:\Program Files\AgilentTechnologies\86030A and select the A86030_LCAServer.TLB file.
 - 3 Declare and obtain a handle to the 86030A server. See [“Getting a Handle to the Server Object” on page 4-9](#) for the details of how to connect to the server.
-

Step 2. Instantiate and Initialize the 86030A Server

Initializing the server loads needed configuration information for placing the server, the optical test set, and the network analyzer into a known state. After the initialization, you can access the methods and properties of the 86030A server.

- 1 Execute the following statement so the server automatically establishes communication with the network analyzer.

```
Set sLCA=CreateObject ("A86030_LCAServer.A86030Sync", "XXXLWD")
```

- 2 Once a connection has been established execute the following statement to start the 86030A server.

```
sLCA.SysStartUp
```

- 3 Execute the SysInit method so the 86030A system is initialized. This should be the first method called after establishing a connection to the server. For example:

```
ErrorCode = server.SysInit
```

ErrorCode is a type integer and will be a 0 if the method was successful or a -1 if an error was encountered during the initialization. See [“Events” on page 4-7](#) to see how errors are handled with the 86030A server.

The 86030A server is now initialized and contains the appropriate settings for the optical test set, and 8510. At this point you have full access to the functionality of the server. Also, the system is operating with a fully initialized and calibrated instrument.

NOTE

The SysInit method can also be used to reset the instrument. This method places the system into a known state.

Step 3. Configure the 86030A System Server for Calibration

Once you get a handle to the server object and initialize the server, you may want to make modifications to the 86030A current settings, or start a measurement calibration.

- 1 Modify the measurement settings using properties.

You can use properties to modify the measurement settings. Refer to [“System Properties” on page 4-25](#) for a list of the properties available for the 86030A.

For example, the following use of a property sets the averaging factor of the 8510 to 32 averages at each point.

```
server.Averaging = 32
```

- 2 Set up a measurement state for a calibration using the “sSetupCal” method.

The main method for setting up a calibration is named “**sSetupCal**”. The following is an example call to this method. Refer to [“List of Available Commands” on page 4-25](#) for more details on the measurement settings and the use of this method.

```
server.sSetupCal OE_BW_RESPONSE, POINTS401, 32,  
45000000#, 50000000000#
```

- **OE_BW_REPONSE** is an enumerated value that selects an Optical to Electrical Bandwidth Response calibration.
- **POINTS401** is an enumerated value that selects 401 points on the 8510.
- **32** is the number of averages at each point.
- **45000000#** is a parameter for the start frequency.
- **50000000000#** is a parameter for the stop frequency.

Through the use of properties and methods the system is configured for the appropriate calibration. At this point the server is initialized and the 86030A system is configured for an O/E bandwidth response calibration.

Step 4. Performing Measurements Using the Remote Operation Interface

Once the system has been configured for an appropriate calibration, a number of calibration standards must be measured as part of the calibration process.

The calibration standards must be measured in a specific order. Refer to “[Calibration Methods](#)” on page 4-41 for information on the correct sequence of standard measurements for each calibration type.

- 1 Determine the standards that must be measured for the measurement calibration type.
- 2 Determine the sequence in which the standards must be measured during the calibration process.
- 3 Make good connections for each of the calibration standard measurements.
- 4 Make a call to perform the standard measurement.

In the following example the O/E bandwidth response calibration has only one standard to measure.

```
ErrorCode = server.OEBWRESP_STD1
```

The above call will cause the measurement of standard 1, which allows the 86030A system to reduce measurement errors. When the method returns ErrorCode it will either contain one of the following:

- 0 indicating success
- -1 indicating failure

If a -1 is returned, the system status register can be queried to help determine the cause of the error. For example:

```
ErrorCode32 = server.SysStatusReg
```

The ErrorCode32 must be a 32 bit value or Long in Visual Basic. This code can be matched against the provided error codes to help determine the failure. The value in the system status register represents the last encountered error the system experienced.

More detailed errors can be obtained by using the ERRHANDLER event of the 86030A server. This event provides a detailed message and error code to help determine the encountered error.

To use this ERRHANDLER event you must create the handle to the server using WithEvents. For example:

```
Public WithEvents server As A86030_LCAServer.A86030Sync
```

You will also need to write an error handler to do something with the information that the server provides. For example:

```
Public Sub A86030_LCAServer_ERRHANDER (strerr as string,  
interr as enumStatus)  
  
‘ Your code goes here which takes the appropriate action  
for the error that is encountered.  
  
End Sub
```

Step 5. Retrieve Measurement Data

There are methods that allow you to obtain measurement and calibration data from the 8510 using the 86030A remote operation. See [“Data Methods” on page 4-34](#) to learn proper usage of these methods. The following code examples show different ways to obtain data.

- Obtaining measurement data:

```
Private Sub cmdGetMeasurementData_Click()  
Dim Traces As Integer  
Dim Points As Integer  
Dim TraceData() As Single  
server.GetTraceData LOGMAG_TYPE, Traces, Points, Trace-  
Data  
End Sub
```

NOTE

The call to GetTraceData in the above example will return data from the 8510 into the array TraceData.

- Obtaining calibration data:

```
Private Sub cmdPlotCurrentCalibration_Click()  
Dim Sets As Integer  
Dim Points As Integer  
Dim CalibrationData() As Single  
server.GetCalibrationData Sets, Points, CalibrationData  
End Sub
```

NOTE

The call to GetCalibrationData in the above example will return data from the 8510 into the array CalibrationData.

This method allows you use the 86030A remote operation to download the correction coefficients from the 8510.

Step 6. Check for Any Encountered Errors

You can use two different approaches to obtain error information remotely.

- In the first approach you can use the return values of methods and the system status register.
- In the second approach you can use the ERRHANDLER event provided by the server.

Almost all methods return a 0 or a -1 to indicate success or failure respectively. If the method was successful (returned 0), there is no reason to query the system status register. If a -1 was returned, then the system status register can provide information as to the reason for the error.

The second approach, using the ERRHANDLER event, provides the most information when an error is encountered. The handle to the 86030A server object must be declared WithEvents. Then an error handler must be written on the client or controlling computer to use this method of retrieving error information.

Overview of the 86030A Server API

System Properties	Use these properties to modify the current measurement settings on the 86030A.
System Methods	Use these methods to initialize, verify, and shutdown the 86030A system.
Data Methods	Use these methods to retrieve, save, and output measurement data.
Network Analyzer Methods	Use these methods to control the network analyzer portion of the 86030A system.
Calibration Methods	Use these methods to perform measurement calibrations. Along with each method that is associated with measuring a calibration standard, a graphic is included to show the connections that must be in place before the method is called.
Testset Functions	Use these methods to control the lightwave test set portion of the 8603A system.

List of Available Commands

System Properties

Averaging As Integer	page 4-29
BiasInterval As Single	page 4-29
CouplerPower As Single [Read-only]	page 4-29
LaserPower As Single	page 4-29
MaxBiasVoltage As Single [Read-only]	page 4-29
Meas As Integer [Read-only]	page 4-29
MinBiasVoltage As Single [Read-only]	page 4-30
ModBias As Single [Read-only].	page 4-30
Mode As Integer [Read-only].	page 4-30
NumberOfPoints As Integer	page 4-30
QuadVoltage As Single [Read-only].	page 4-30
ReceiverPower As Single [Read-only]	page 4-30
ReflectSTD As Single	page 4-30
RunningLocal As Boolean.	page 4-30
SourcePowerEO As Single	page 4-31
SourcePowerOE As Single	page 4-31
StartFrequency As Single	page 4-31
StopFrequency As Single	page 4-31
SysStatusReg As Long [Read-only]	page 4-31

System Methods

Public Function SysStartUp() As Integer	page 4-32
Public Function SysInit() As Integer.	page 4-32
Public Function SysVerifyStart() As Integer	page 4-33
Public Function SysVerifyFinish() As Boolean.	page 4-33
Public Function SysShutDown() As Integer.	page 4-33

List of Available Commands**Data Methods**

Public Function gTraceData () As Integer	page 4-34
Public Function SaveTraceText() As Integer	page 4-34
Public Function SaveTraceExcel() As Integer	page 4-35
Public Function ExcelGraph() As Integer	page 4-35
Public Function gResponse () As Integer	page 4-36
Public Function gResponseLogMag () As Integer	page 4-36
Public Function gResponsePhase() As Integer	page 4-36
Public Function gResponseDelay () As Integer	page 4-36
Public Function gCalibrationData () As Integer	page 4-37

Network Analyzer Methods

Public Function Write8510(ByVal strgWriteBuffer As String) As Integer . . . page 4-39	
Public Function Read8510() As String	page 4-39
Public Function sExternalLeveling(ByVal OnOff As Boolean) As Integer . . . page 4-39	
Public Function sSweepTime(ByVal SwTime As Single) As Integer . . .page 4-40	
Public Function selectDefaultPowerSettings() As Integer	page 4-40
Public Function TakeCompleteSweep() As Integer	page 4-40
Public Function ResumeContSweep() As Integer	page 4-40

Calibration Methods

Public Function sSetupCal(.	page 4-41
Public Function gCalSetup(.	page 4-43
Public Function OOBWRESP_STD1() As Integer	page 4-43
Public Function OOBWRESPNISOL_STD1() As Integer	page 4-44
Public Function OOBWRESPNISOL_STD2() As Integer	page 4-44
Public Function OORFRESP_STD1() As Integer	page 4-45
Public Function OORFRESPNISOL_STD1() As Integer	page 4-47
Public Function OORFRESPNISOL_STD2() As Integer	page 4-47
Public Function OOBWRESP_STD1() As Integer	page 4-48
Public Function OOBWRESPNISOL_STD1() As Integer	page 4-50
Public Function OOBWRESPNISOL_STD2() As Integer	page 4-50
Public Function OORFRESP_STD1() As Integer	page 4-51
Public Function OORFRESPNISOL_STD1() As Integer	page 4-53
Public Function OORFRESPNISOL_STD2() As Integer	page 4-53

Public Function OEBWNRFPRESP_STD1() As Integer	page 4-53
Public Function OEBWNRFPRESP_STD2() As Integer	page 4-54
Public Function OEBWNRFPRESPNISOL_STD1() As Integer	page 4-56
Public Function OEBWNRFPRESPNISOL_STD2() As Integer	page 4-56
Public Function OEBWNRFPRESPNISOL_STD3() As Integer	page 4-56
Public Function OEBWNRFPRESPNISOL_STD4() As Integer	page 4-57
Public Function OERESPNUMATCH_STD1() As Integer	page 4-57
Public Function OERESPNUMATCH_STD2Open() As Integer	page 4-58
Public Function OERESPNUMATCH_STD3Short() As Integer	page 4-58
Public Function OERESPNUMATCH_STD4Load() As Integer	page 4-59
Public Function OERESPNUMATCH_STD5Open() As Integer	page 4-59
Public Function OERESPNUMATCH_STD6Short() As Integer	page 4-59
Public Function OERESPNUMATCH_STD7Load () As Integer	page 4-60
Public Function OERESPNUMATCH_STD8 () As Integer	page 4-61
Public Function OERESPNUMATCH_STD9 () As Integer	page 4-62
Public Function OERESPNUMATCH_STD10 () As Integer	page 4-62
Public Function EOBWRESP_STD1() As Integer	page 4-64
Public Function EOBWRESPNISOL_STD1() As Integer	page 4-66
Public Function EOBWRESPNISOL_STD2() As Integer	page 4-66
Public Function EORFPRESP_STD1() As Integer	page 4-67
Public Function EORFPRESP_STD2Open() As Integer	page 4-68
Public Function EORFPRESP_STD3Short() As Integer	page 4-68
Public Function EORFPRESP_STD4Load() As Integer	page 4-69
Public Function EOBWNRFPRESP_STD1() As Integer	page 4-70
Public Function EOBWNRFPRESP_STD2Open() As Integer	page 4-70
Public Function EOBWNRFPRESP_STD3Short() As Integer	page 4-70
Public Function EOBWNRFPRESP_STD4Load() As Integer	page 4-71
Public Function EOBWNRFPRESP_STD5() As Integer	page 4-71
Public Function EOBWNRFPRESPNISOL_STD1() As Integer	page 4-73
Public Function EOBWNRFPRESPNISOL_STD2Open() As Integer	page 4-73
Public Function EOBWNRFPRESPNISOL_STD3Short() As Integer	page 4-73
Public Function EOBWNRFPRESPNISOL_STD4Load() As Integer	page 4-74
Public Function EOBWNRFPRESPNISOL_STD5() As Integer	page 4-74
Public Function EOBWNRFPRESPNISOL_STD6() As Integer	page 4-74
Public Function EOREFSENSE_STD1() As Integer	page 4-75

List of Available Commands

86032A Testset Methods

Public Function gTestSetSetup As Integer	page 4-77
Public Function TurnLaserOn() As Integer	page 4-78
Public Function TurnLaserOff() As Integer	page 4-78
Public Function sBiasModAuto() As Integer	page 4-78
Public Function sBiasModMax() As Integer	page 4-78
Public Function sModeOO() As Integer	page 4-78
Public Function sModeOE() As Integer	page 4-78
Public Function sModeEO() As Integer	page 4-79
Public Function sModeEE() As Integer	page 4-79
Public Function gVoltageLevels() As Integer	page 4-79
86032A Events	page 4-79
86032A Enumerated Types	page 4-80
86032A Error Codes and Error Handling	page 4-94

System Properties

Averaging As Integer

Network Analyzer number of averages per measurement point.

BiasInterval As Single

86032A testset modulator auto-bias interval in minutes.

5 < = BiasInterval <= 9999. Default is 480minutes

CouplerPower As Single [Read-only]

The power coming from the OPTICAL OUTPUT port on the optical test set (dBm).

LaserPower As Single

The power coming from the LASER OUTPUT port on the optical test set (dBm). Range is -10 to + 10 dBm. Default is 10 dBm.

MaxBiasVoltage As Single [Read-only]

86032A testset current modulator bias voltage required for maximum optical output power. This value is obtained during autobias, and is only valid after an autobias has been completed.

Meas As Integer[Read-only]

86030A current measurement type.

- BANDWIDTH = 0
- REFLECTION = 1
- BW_N_REFL = 2
- REFL_SENS = 3
- RESPNMATCH = 4

MinBiasVoltage As Single [Read-only]

86032A Testset current modulator bias voltage required for minimum optical output power. This value is obtained during autobias, and is only valid after an autobias has been completed.

ModBias As Single

86032A Testset current modulator bias. Range is -9.9 volts to + 9.9 volts. This value is set by the 86030A system automatically after an autobias has been completed.

Mode As Integer [Read-only]

86030A current system mode.

- OTOO = 0
- OTOE = 1
- ETOO = 2
- ETOE = 3

NumberOfPoints As enumPointType

Network Analyzer number of points.

QuadVoltage As Single[Read-only]

86032A testset current modulator quadrature voltage. This value is obtained during autobias, and is only valid after an autobias has been completed.

ReceiverPower As Single[Read-only]

Optical power (dBm) at the OPTICAL RECEIVER INPUT port of the optical test set.

ReflectSTD As Single

Optical reflection standard in percentage. Range is 0 to 100. This reflection standard is used during optical reflection calibrations.

RunningLocal As Boolean

Enables (True) or disables (False) system running on instrument computer.

If `RunningLocal` is `True`, the system will turn on the instrument computer. If `RunningLocal` is `False`, the system will be in remote operation.

SourcePowerEO As Single

Network Analyzer source power (dBm) for EO system mode.

-66 dBm < SourcePowerEO <= 20 dBm

SourcePowerOE As Single

Network Analyzer source power (dBm) for OE and OO system mode.

-66 dBm < SourcePowerOE <= 20 dBm

StartFrequency As Single

Start frequency of the network analyzer (Hz).

StopFrequency As Single

Stop frequency of the network analyzer (Hz).

SysStatusReg As enumStatus[Read-only]

Value of the System Status register. This value is the last error encountered by the system or the last action being executed. Once read it is cleared, its value is returned to 0 (`SYSTEM_NORMAL`).

System Methods

Public Function SysStartUp() as Integer

Description: This function is called immediately after obtaining a handle to the server. This method starts the server application and brings up the Graphic User Interface (GUI). This method is always followed by a SysInit to run the interface remotely.

NOTE This method must be called to start the 86030A server.

Public Function SysInit() As Integer

Description: Initializes 86030A system.

Pre-Conditions: The system has not been initialized before. If it has then this function does nothing. Public Event StatusAvailable(Message As String).

Post-Conditions: The 86030A System is initialized. A 0 is returned once the system is initialized, a -1 is returned if an error was encountered in the process.

Initialization:

- 1 TestSet and software are placed into O/E bandwidth mode.
- 2 Network analyzer is initialized to work with the 86030A optical test set.
- 3 Autobias is performed for the first time.

```
Public Function SysShutDown() as Integer
```

Description: This function is called when user wishes to close and shut down the 86030 system. This function should be called directly before the handle to the server is released.

```
Public Sub SysVerifyStart() as Integer
```

Description: First function executed when performing a system verification. This function will initiate the system verification process. The following functions are needed to make up the complete verification process. Returns 0 if successful or -1 if error is encountered.

```
server:SysVerifyStart
server:OERESPMATCH_STD1
server:OERESPMATCH_STD2Open
server:OERESPMATCH_STD3Short
server:OERESPMATCH_STD4Load
server:OERESPMATCH_STD5Open
server:OERESPMATCH_STD6Short
server:OERESPMATCH_STD7Load
server:OERESPMATCH_STD8
server:OERESPMATCH_STD9
server:OERESPMATCH_STD10
boo SystemPass=server.SysVerifyFinish
If boo SystemPass=True Then
MsgBox "System Passed", vbOKOnly
Else
MsgBox "System Failed", vbCritical
End If
```

```
Public Function SysVerifyFinish() As Boolean
```

Description: Last function called when performing a system verification.

Return Value: TRUE / FALSE Boolean value. TRUE indicates the system passed, and FALSE indicates the system failed.

Data Methods

These methods are used for capturing, saving, and graphing measurement data.

```
Public Sub GTraceData (tracetype As enumTraceType, Traces As Integer, Points As Integer,
TraceData() As Single)
```

Description: This method is associated with the calibration that was previously performed. If a bandwidth and reflection calibration has been performed then both the bandwidth measurement and the reflection measurement will be returned in a multidimensional array. The reflection measurement will be returning in the following manner.

COMPLEX_TYPE

- Reflection
- TraceData(2,0 to Points - 1) contain all the real data points
- TraceData(3,0 to Points - 1) contain all the imaginary data points

Formatted Types(LOGMAG_TYPE, PHASE_TYPE, DELAY_TYPE)

- Bandwidth or Reflection
- TraceData(0, 0 to Points - 1) contain all the data points
- TraceData(1, 0 to Points - 1) contain all 0s

The bandwidth portion of the measurement will be returned in array index 0 - 1.

```
Public Function SaveTraceText(strFilename As String, tracetype As enumTraceType) As Integer
```

Description: Saves the active trace from the 8510 into a text file.

strFilename: Absolute path where the file will be saved. For example:

StrFilename: "D:\LCA50GHz\Data\filename.xls"

Tracetype: Selects the trace type (COMPLEX_TYPE, LOGMAG_TYPE, PHASE_TYPE, DELAY_TYPE)

NOTE If a bandwidth and reflection calibration was the last calibration performed, the software assumes that both measurements are of interest. This method will append a “_BW” or “_RF” to the filename. Both files will appear in the D:\LCA50GHZ\Data directory as the following:
File1 = filename1_BW.xls
File2 = filename2_RF.xls

```
Public Function SaveTraceExcel (strFilename As String, tracetype As enumTraceType)As Integer
```

Description: Saves the active trace from the 8510 into an excel file.

strFilename: Absolute path where the file will be saved. For example:
StrFilename: “D:\LCA50GHz\Data\filename.xls”

Tracetype: Selects the trace type (COMPLEX_TYPE, LOGMAG_TYPE, PHASE_TYPE, DELAY_TYPE)

```
Public Function ExcelGraph(filenameExcel As String, tracetype As enumTraceType) As Integer  
Syn
```

Description: Creates graph within existing excel file. This excel file must have already been saved using the method call SaveTraceExcel.

filenameExcel: Absolute path where the file will be saved. For example:
filenameExcel: “D:\LCA50GHz\Data\filename.xls”

Tracetype: Selects the trace type (COMPLEX_TYPE, LOGMAG_TYPE, PHASE_TYPE, DELAY_TYPE)

NOTE If a bandwidth and reflection calibration was the last calibration performed, the software assumes that both measurements are of interest. This method will append a “_BW” or “_RF” to the filename. Both files will appear in the D:\LCA50GHZ\Data directory as the following:
File1 = filename1_BW.xls
File2 = filename2_RF.xls

```
Public Function gResponse(arResponse() As Single, intmeas As Integer) As Integer
```

Description: This function returns an array through arResponse() containing the real and imaginary data for each point of measurement. An array dimensioned as arResponse (1 to 2 * Number of Points) as single should be passed to it. The data points are returned in arResponse(). The format for arResponse is odd indexes 1,3,5...contains real and even indexes 2,4,6...contain imaginary arResponse(1) and arResponse(2) make up a single data point.

intMeas: tells what type of measurement was performed either BANDWIDTH, REFLECTION, or BW_N_REFL.

```
Public Function gResponseLogMag(arResponse() As Single, intmeas As Integer) As Integer
```

Description: This function returns the Log Magnitude of the response displayed on the 8510. Only odd indexes of arResponse are of interest. All even indexes are 0. This function forces the 8510 into displaying Log Magnitude.

intMeas: is the type of measurement of interest.

```
Public Function gResponsePhase(arResponse() As Single, intmeas As Integer) As Integer
```

Description: This function returns the Phase of the response displayed on the 8510. Only odd indexes of arResponse are of interest. All even indexes are 0. This function forces the 8510 into displaying phase.

intMeas: is the type of measurement of interest.

```
Public Function gResponseDelay(arResponse() As Single, intmeas As Integer) As Integer
```

Description: This function returns the Delay of the response displayed on the 8510. Only odd indexes of arResponse are of interest. All even indexes are 0. This function forces the 8510 into displaying delay.

intMeas: is the type of measurement of interest.

Public Function gCalibrationData(Sets As Integer, Points As Integer, CalibrationData() As Single) As Integer

Description: This method returns the calibration array of the 8510. The contents are the calibration correction coefficients calculated during the last calibration. A valid calibration must have been performed before calling this method.

Return Types: CalibrationData(): multidimensional array of single. The dimension of the array is dependent on the type of calibration performed. If a response and isolation calibration was performed then the array will return both the response and isolation portions of the calibration. The returned array will be as follows.

- CalibrationData(0, 0 to Points - 1) = Real portion of isolation coefficients.
- CalibrationData(1, 0 to Points - 1) = Imaginary portion of isolation coefficients.
- CalibrationData(2, 0 to Points - 1) = Real portion of response coefficients.
- CalibrationData(3, 0 to Points - 1) = Imaginary portion of response coefficients.

If only a response calibration was performed then CalibrationData() will be as follows.

- CalibrationData(0, 0 to Points - 1) = Real portion of response coefficients.
- CalibrationData(1, 0 to Points - 1) = Imaginary portion of response coefficients.

Sets: This is an integer value specifying the dimension of the returned array. This value is a 1 for response calibrations, and a 2 for response and isolation calibrations.

Data Methods

Points:

This is an integer value specifying the number of points for the returned calibration. This value is 0 if no valid calibration was available.

This function returns a 0 for success and a -1 for failure.

If a bandwidth and reflection calibration has been performed and both coefficients are desired. The methods `sBandwidth` and `sReflection` must be used to switch the system into the corresponding measurement mode and then to make the call to `gCalibrationData`.

For example:

```
Server.sBandwidth      `Puts system into bandwidth mode
Server.gCalibrationData(.....) `Gets the calibration
data.
```

Network Analyzer Methods

The following methods are used to setup the 8510C network analyzer.

```
Public Function Write8510(ByVal strgWriteBuffer As String)As Integer
```

Description: Performs a Pass-through to the Vector Network Analyzer (VNA). strgWriteBuffer is a GPIB VNA compatible mnemonic, this command is passed to the VNA of the 86030A System.

```
Public Function Read8510() (StrgReadBuffer) As Integer
```

Description: Performs a Passthrough read to the VNA

Pre-Conditions: Active-Function on VNA specified.

Post-Conditions: Data is contained in string passed back.

```
Public Function sExternalLeveling(ByVal OnOff As Boolean)As Integer
```

Description: Causes the Source to be externally leveled. Leveling path goes through the testset if OnOff is TRUE. Otherwise Source of VNA uses internal leveling.

Pre-Conditions: None.

Post-Conditions: Leveling path is now through the testset (optical). If OnOff is TRUE. Otherwise source is using internal leveling.

```
Public Function sSweepTime(ByVal SwTime As Single)As Integer
```

Description: Sets the sweep time of VNA in milliseconds.

Pre-Conditions: None.

Post-Conditions: Sweep time of VNA set.

```
Public Function selectDefaultPowerSettings() As Integer
```

Description: Restores the default network analyzer power settings.

Pre-Conditions: None.

Post-Conditions: Default network analyzer power settings restored.

```
Public Function TakeCompleteSweep() As Integer
```

Description: Causes network analyzer to take a single complete sweep and then go to a hold state.

Pre-Conditions: None.

Post-Conditions: Network analyzer is stopped after taking a complete sweep.

```
Public Function ResumeContSweep() as Integer
```

Description: Causes network analyzer to resume sweeping.

Pre-Conditions: None.

Post-Conditions: Network analyzer is in sweep mode.

Calibration Methods

The following methods enable you to setup and perform a calibration. Each calibration has a number of standards that need to be measured to properly calibrate the system. Standards can be called individually, but they must be in an expected order.

For example:

OEBWNRFPRESPNISOL_STD1 is a method call that measures a single standard. The needed connections for this standard can be viewed in this document.

All calibration methods follow the naming convention shown.

- OE = Optical to Electrical measurement.
- BW = Bandwidth
- RF = Reflection
- BWNRF = Bandwidth and Reflection
- RESP = Response
- ISOL = Isolation
- Note: RESPNISOL = Response and Isolation
- STD1 = Standard 1

```
Public Function sSetupCal(ByVal CalType As enumStandards, ByVal Points As enumPointType,  
ByVal Average As Integer, ByVal Startf As Single, ByVal Stopf As Single) As Integer
```

Description: This is the Main Calibration Configuration Function Call, and is called before each new user calibration to setup the network analyzer and software to perform the calibration.

Calibration Methods

Parameters: CalType Valid: 0-17 Specifies Calibration Type - Valid values for this parameter are:

OO_BW_RESPONSE = 0
OO_BW_RESPNISOL = 1
OO_RF_RESPONSE = 2
OO_RF_RESPNISOL = 3
OE_BW_RESPONSE = 4
OE_BW_RESPNISOL = 5
OE_RF_RESPONSE = 6
OE_RF_RESPNISOL = 7
OE_BWNRF_RESPONSE = 8
OE_BWNRF_RESPNISOL = 9
OE_RESPNMATCH = 10
EO_BW_RESPONSE = 11
EO_BW_RESPNISOL = 12
EO_RF_RESPONSE = 13
EO_RF_RESPNISOL = 14
EO_BWNRF_RESPONS = 15
EO_BWNRF_RESPNISOL = 16
EO_REFSENSE = 17

Power Valid: -66dBm to 20dBm Format 32-bit single Between -66 and 20

Points Valid: Integer Valid values for parameter

POINTS51 = 51
POINTS101 = 101
POINTS201 = 201
POINTS401 = 401
POINTS801 = 801

Average Valid: Integers (0, 4096) network analyzer accepts only powers of 2: 0,1,2,4,..., 64,128,256,...1024

Startf Valid: 32-bit single < then 50GHz and > than 45MHz

Stopf Valid: 32-bit single < then 50GHz and > than 45MHz

```
Public Function gCalSetup(CalType As Integer, Power As Single, _ Points As Integer, Average  
As Integer, Startf As Single, Stopf As Single) As Integer
```

Description: Returns the current calibration configuration.

Pre-Conditions: Software has been initialized previously.

Post-Conditions: Above values returned.

```
Public Function sBandwidth() As Integer
```

Description: This method switches the system to the bandwidth mode after the bandwidth and reflection calibration have been performed.

Pre-Conditions: A valid bandwidth and reflection calibration has been performed on the 86030A system.

Post-Conditions: The system will be in the bandwidth mode.

```
Public Function sReflection() As Integer
```

Description: This method switches the system to the reflection mode after and bandwidth and reflection calibration have been performed.

Pre-Conditions: A valid bandwidth and reflection calibration has been performed on the 86030A system.

Post-Conditions: The system will be in the reflection mode.

```
Public Function OOBWRESP_STD1() As Integer
```

Description: Performs the O/O standard 1 calibration for bandwidth response calibration.

Pre-Conditions: The connections in [Figure 4-3](#) have been made on the instrument.

Post-Conditions: Standard for O/O bandwidth response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-3. Connections for O/O Bandwidth Response (Std1), and O/O Bandwidth Response and Isolation (Std1, Std2)

Public Function OOBWRESPNISOL_STD1() As Integer

Description: Part of the optical-to-optical bandwidth response and isolation calibration. Measures the response calibration standard for the O/O bandwidth response and isolation.

Pre-Conditions: The connections in [Figure 4-3](#) have been made on the instrument.

Post-Conditions: Response standard for O/O bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OOBWRESPNISOL_STD2() As Integer

Description: Part of the optical-to-optical bandwidth response and isolation calibration. Measures the isolation calibration standard for the O/O bandwidth response and isolation.

Pre-Conditions: OOBWRESPNISOL_STD1 have already been performed. The connections in [Figure 4-3 on page 4-44](#) have been made on the instrument.

Post-Conditions: Standard for O/O bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails. Measurement Connections in [Figure 4-4](#) are for a device under test, after performing an O/O bandwidth response and isolation calibration.




Figure 4-4. Measurement Connections for a Device Under Test after an O/O Bandwidth Response and Isolation Calibration

```
Public Function OORFRESP_STD1()As Integer
```

Description: Part of the optical-to-optical reflection response calibration. Measures the response calibration standard for O/O reflection.

Pre-Conditions: The connections in [Figure 4-5 on page 4-46](#) have been made on the instrument.

Post-Conditions: Standard 1 for O/O reflection and response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-5. Connections for O/O Reflection Response Calibration (Std1), and O/O Reflection Response Calibration (Std1, Std2)

Measurement Connections in [Figure 4-6](#) are for a device under test, after performing an O/O reflection response or O/O reflection response and isolation calibrations.



Figure 4-6. Measurement Connections for a Device Under Test after an O/O Reflection Response Calibration

Public Function OORFRESPNISOL_STD1() As Integer

Description: Part of the optical-to-optical reflection response and isolation calibration. Measures the response calibration standard for the O/O reflection response and isolation calibration.

Pre-Conditions: The connections in [Figure 4-5 on page 4-46](#) have been made on the instrument.

Post-Conditions: Response standard for reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OORFRESPNISOL_STD2() As Integer

Description: Part of the optical-to-optical reflection response and isolation calibration. Measures the isolation calibration standard for the O/O reflection response and isolation calibration.

Pre-Conditions: OORFRESPNISOL_STD1 has already been performed. The connections in [Figure 4-5 on page 4-46](#) have been made on the instrument.

Post-Conditions: Standard 2 for O/O reflection response and isolation calibration has been performed.

Measurement Connections in [Figure 4-7 on page 4-48](#) are for a device under test, after performing an O/O reflection response and isolation calibration.



Figure 4-7. Measurement Connections for a Device Under Test after an O/O Reflection Response and Isolation Calibration

```
Public Function OEBWRESP_STD1() As Integer
```

Description: Measures the response calibration standard for O/E bandwidth response calibration.

Pre-Conditions: The connections in [Figure 4-8 on page 4-49](#) have been made on the instrument.

Post-Conditions: Response standard for O/E bandwidth response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.




Figure 4-8. Connections for O/E Bandwidth Response Calibration (Std1), and O/E Bandwidth Response & Isolation Calibration (Std1, Std2)

Measurement Connections in [Figure 4-9 on page 4-49](#) are for a device under test, after performing an O/E bandwidth response calibration.



Figure 4-9. Measurement Connections for a Device Under Test after an O/E Bandwidth Response Calibration

Public Function OEBWRESPNISOL_STD1() As Integer

- Description:** Measures the isolation calibration standard for O/E response and isolation calibration.
- Pre-Conditions:** The connections in [Figure 4-8 on page 4-49](#) have been made on the instrument.
- Post-Conditions:** Response standard for O/E bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
-

Public Function OEBWRESPNISOL_STD2() As Integer

- Description:** Measures the isolation calibration standard for the O/E bandwidth response and isolation calibration.
- Pre-Conditions:** OEBWRESPNISOL_STD1 have already been performed. The connections in [Figure 4-8 on page 4-49](#) have been made on the instrument.
- Post-Conditions:** Isolation standard for O/E bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
- Measurement Connections in [Figure 4-10 on page 4-51](#) are for a device under test, after performing an O/E bandwidth response and isolation calibration.




Figure 4-10. Measurement Connections for a Device Under Test after an O/E Bandwidth Response and Isolation Calibration

Public Function OERFRESP_STD1() As Integer

- Description:** Measures the response calibration standard for the O/E reflection response calibration.
- Pre-Conditions:** The connections in [Figure 4-11 on page 4-52](#) have been made on the instrument.
- Post-Conditions:** Response standard for the O/E reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Remote Operation
Calibration Methods



Figure 4-11. Connections for O/E Reflection Response Calibration (Std1), and O/E Reflection Response and Isolation Calibration (Std1, Std2)

Measurement Connections in [Figure 4-12 on page 4-52](#) are for a device under test, after performing an O/E reflection and response calibration.



Figure 4-12. Measurement Connections for a Device Under Test after an O/E Reflection Response Calibration or an O/E Reflection Response & Isolation Calibration

Public Function OERFRESPNISOL_STD1() As Integer

- Description:** Measures the response calibration standard for the O/E reflection response and isolation calibration.
- Pre-Conditions:** The connections in [Figure 4-11 on page 4-52](#) have been made on the instrument.
- Post-Conditions:** Response standard for O/E reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OERFRESPNISOL_STD2() As Integer

- Description:** Measures the isolation calibration standard for the O/E reflection response and isolation calibration.
- Pre-Conditions:** OERFRESPNISOL_STD1 has already been performed. The connections in [Figure 4-11 on page 4-52](#) have been made on the instrument.
- Post-Conditions:** Isolation standard for the O/E reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
- Measurement Connections in [Figure 4-12 on page 4-52](#) are for a device under test, after performing an O/E reflection response and isolation calibration.

Public Function OEBWNRFPRESP_STD1() As Boolean

- Description:** Measures the reflection response calibration standard for the O/E bandwidth reflection response calibration.
- Pre-Conditions:** The connections in [Figure 4-13](#) have been made.

Post-Conditions: Reflector response standard for the O/E bandwidth reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.




Figure 4-13. Connections for O/E Bandwidth Reflection Response Calibration (Std1), and O/E Bandwidth Reflection Response & Isolation Calibration (Std1, Std2)

Public Function OEBWNRFPRESP_STD2() As Integer

Description: Measures the bandwidth response calibration standard for a O/E bandwidth and reflection response calibration.

Pre-Conditions: The connections in [Figure 4-14 on page 4-55](#) have been made on the instrument.

Post-Conditions: Standard for bandwidth reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.




Figure 4-14. Connections for O/E Bandwidth Reflection Response Calibration (Std2), and O/E Bandwidth Reflection Response & Isolation Calibration (Std3, Std4)

Measurement Connections in [Figure 4-15 on page 4-55](#) are for a device under test, after performing an O/E bandwidth reflection response calibration.




Figure 4-15. Measurement Connections for a Device Under Test after an O/E Bandwidth Reflection Response Calibration or O/E Bandwidth Reflection Response & Isolation Calibration

Public Function OEBWNRFPRESPNISOL_STD1() As Integer

- Description:** Measures the reflection response calibration standard for O/E bandwidth and reflection response and isolation calibration.
- Pre-Conditions:** The connections in [Figure 4-13 on page 4-54](#) have been made on the instrument.
- Post-Conditions:** Reflection response standard for the O/E bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OEBWNRFPRESPNISOL_STD2() As Integer

- Description:** Measures the reflection isolation calibration standard for an O/E bandwidth and reflection response and isolation calibration.
- Pre-Conditions:** OEBWNRFPRESPNISOL_STD1 has already been performed. The connections in [Figure 4-13 on page 4-54](#) have been made on the instrument.
- Post-Conditions:** Reflection isolation standard for an O/E bandwidth and reflection response and isolation calibration has been performed. Returns True if the calibration succeed and False if the calibration failed.

Public Function OEBWNRFPRESPNISOL_STD3() As Integer

- Description:** Measures the bandwidth response calibration standard for an O/E bandwidth and reflection response and isolation calibration.
- Pre-Conditions:** OEBWNRFPRESPNISOL_STD1 and OEBWNRFPRESPNISOL_STD2 have already been performed. The connections in [Figure 4-14 on page 4-55](#) have been made on the instrument.

Post-Conditions: Bandwidth response standard for an O/E bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

```
Public Function OEBWNRFPRESNISOL_STD4() As Integer
```

Description: Measures the bandwidth isolation calibration standard for an O/E bandwidth and reflection response and isolation calibration.

Pre-Conditions: OEBWNRFPRESNISOL_STD1, OEBWNRFPRESNISOL_STD2 and OEBWNRFPRESNISOL_STD3 have already been performed. The connections in [Figure 4-14 on page 4-55](#) have been made on the instrument.

Post-Conditions: Bandwidth response standard for an O/E bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Measurement Connections in [Figure 4-15 on page 4-55](#) are for a device under test, after performing an O/E bandwidth reflection response and isolation calibration.

```
Public Function OERESPMATCH_STD1() As Integer
```

Description: Measures calibration standard 1 for an O/E response and match calibration.

Pre-Conditions: The connections in [Figure 4-16 on page 4-58](#) have been made on the instrument.

Post-Conditions: Standard 1 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-16. Connections for O/E Response and Match Calibration (Std1, Std2, Std3, Std4)

```
Public Function OERESPMATCH_STD2Open() As Integer
```

Description: Measures calibration standard 2 for an O/E response and match calibration.

Pre-Conditions: OERESPMATCH_STD1 has been performed. The following connections in [Figure 4-16 on page 4-58](#) have been made on the instrument.

Post-Conditions: Standard 2 for an O/E Response and Match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

```
Public Function OERESPMATCH_STD3Short() As Integer
```

Description: Measures calibration standard 3 for an O/E response and match calibration.

Pre-Conditions: OERESPMATCH_STD1 and OERESPMATCH_STD2Open have been performed. The following connections in [Figure 4-16 on page 4-58](#) have been made on the instrument.

Post-Conditions: Standard 3 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OERESPNMATCH_STD4Load() As Integer

- Description:** Measures calibration standard 4 for an O/E response and match calibration.
- Pre-Conditions:** OERESPNMATCH_STD1, OERESPNMATCH_STD2Open and OERESPNMATCH_STD3Short have been performed. The following connections in [Figure 4-16 on page 4-58](#) have been made on the instrument.
- Post-Conditions:** Standard 4 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OERESPNMATCH_STD5Open() As Integer

- Description:** Measures calibration standard 5 for an O/E response and match calibration.
- Pre-Conditions:** OERESPNMATCH_STD1, OERESPNMATCH_STD2Open, OERESPNMATCH_STD3Short and OERESPNMATCH_STD4Load have been performed. The following connections in [Figure 4-17 on page 4-60](#) have been made on the instrument.
- Post-Conditions:** Standard 5 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OERESPNMATCH_STD6Short() As Integer

- Description:** Measures calibration standard 6 in an O/E response and match calibration.
- Pre-Conditions:** OERESPNMATCH_STD1, OERESPNMATCH_STD2Open, OERESPNMATCH_STD3Short, OERESPNMATCH_STD4Load and OERESPNMATCH_STD5Open have been performed. The following connections in [Figure 4-17 on page 4-60](#) have been made on the instrument.
- Post-Conditions:** Standard 6 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-17. Connections for O/E Response and Match Calibration (Std5, Std6, Std7)

```
Public Function OERESPNMATCH_STD7Load () As Integer
```

Description: Measures calibration standard 7 in an O/E response and match calibration.

Pre-Conditions: OERESPNMATCH_STD1, OERESPNMATCH_STD2Open, OERESPNMATCH_STD3Short, OERESPNMATCH_STD4Load, OERESPNMATCH_STD5Open and OERESPNMATCH_STD6Short have been performed. The following connections in [Figure 4-17 on page 4-60](#) have been made on the instrument.

Post-Conditions: Standard 7 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function OERESPMATCH_STD8 () As Integer

Description: Measures calibration standard 8 in an O/E response and match calibration.

Pre-Conditions: OERESPMATCH_STD1, OERESPMATCH_STD2Open, OERESPMATCH_STD3Short, OERESPMATCH_STD4Load, OERESPMATCH_STD5Open, OERESPMATCH_STD6Short and OERESPMATCH_STD7Load have been performed. The following connections in [Figure 4-18](#) have been made on the instrument.

Post-Conditions: Standard 8 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-18. Connections for O/E Response and Match Calibration (Std8)

Public Function OERESPMATCH_STD9 () As Integer

Description: Measures calibration standard 9 in an O/E response and match calibration.

Pre-Conditions: OERESPMATCH_STD1, OERESPMATCH_STD2Open, OERESPMATCH_STD3Short, OERESPMATCH_STD4Load, OERESPMATCH_STD5Open, OERESPMATCH_STD6Short, OERESPMATCH_STD7Load and OERESPMATCH_STD8 have been performed. The following connections in Figure 4-19 have been made on the instrument.

Post-Conditions: Standard 9 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-19. Connections for O/E Response and Match Calibration (Std9)

Public Function OERESPMATCH_STD10 () As Integer

Description: Measures calibration standard 10 in an O/E response and match calibration.

Pre-Conditions: OERESPNMATCH_STD1, OERESPNMATCH_STD2Open, OERESPNMATCH_STD3Short, OERESPNMATCH_STD4Load, OERESPNMATCH_STD5Open, OERESPNMATCH_STD6Short, OERESPNMATCH_STD7Load, OERESPNMATCH_STD8 and OERESPNMATCH_STD9 have been performed. The following connections in [Figure 4-20](#) have been made on the instrument.

Post-Conditions: Standard 10 for an O/E response and match calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails. When standards 1 through 9 for the response calibration are successfully measured, calibration standard 10 may be called repeatedly to perform an calibration for a new device under test. When a different calibration or method is called, the first 1-9 standards must be called again for the calibration to be valid.

For example:

- 1 Measure calibration standards 1 through 9.
- 2 Connect a device under test, as shown in [Figure 4-20](#).
- 3 Call the method OERESPNMATCH_STD10. When the calibration standard measurement is complete and the correction is up-loaded to the network analyzer, the corrected trace will be shown in the analyzer screen.
- 4 Call the method TakeCompleteTrace to verify that a complete sweep has been performed.
- 5 Save the trace data.
- 6 Connect a new device under test, as shown in [Figure 4-20](#).
- 7 Again, call the method OERESPNMATCH_STD10. This measurement calibration will use the information from the previous calibration standards.

NOTE

If no measurement settings are changed, you can use this approach to continually calibrate for new devices avoiding the measurements of calibration standards 1 through 9.




Figure 4-20. Connections for O/E Response and Match Calibration (Std10), and a Device Under Test after an O/E Response and Match Calibration

Measurement Connections in [Figure 4-20](#) are for a device under test, after performing an O/E response and match calibration.

Public Function EOBWRESP_STD1() As Integer

- Description:** Measures the response standard for an E/O bandwidth response calibration.
- Pre-Conditions:** The following connections in [Figure 4-21 on page 4-65](#) have been made on the instrument.
- Post-Conditions:** Response standard for an E/O bandwidth response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-21. Connections for E/O Bandwidth Response Calibration (Std1), and E/O Bandwidth Response & Isolation Calibration (Std1)

Measurement Connections in [Figure 4-22](#) are for a device under test, after performing an E/O bandwidth response calibration.



Figure 4-22. Measurement Connections for a Device Under Test after an E/O Bandwidth Response Calibration or an E/O Bandwidth Response & Isolation Calibration

Public Function EOBWRESPNISOL_STD1() As Integer

- Description:** Measures the response calibration standard for an E/O bandwidth response and isolation calibration.
- Pre-Conditions:** The following connections in [Figure 4-21 on page 4-65](#) have been made on the instrument.
- Post-Conditions:** Response standard for an E/O bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
-

Public Function EOBWRESPNISOL_STD2() As Integer

- Description:** Measures the isolation calibration standard for an E/O bandwidth response and isolation calibration.
- Pre-Conditions:** EOBWRESPNISOL_STD1 has been performed. The following connections in [Figure 4-23 on page 4-67](#) have been made on the instrument.
- Post-Conditions:** Isolation standard for an E/O bandwidth response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-23. Connections for E/O Bandwidth Response and Isolation Calibration (Std2), and E/O Bandwidth Reflection Response and Isolation Calibration (Std6)

Measurement Connections in [Figure 4-22 on page 4-65](#) are for a device under test, after performing an E/O bandwidth response and isolation.

```
Public Function EORFRESP_STD1() As Integer
```

- Description:** Measures the calibration standard 1 for an E/O reflection response calibration.
- Pre-Conditions:** The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 1 for an E/O reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-24. Connections for E/O Reflection Response Calibration (Std1, Std2, Std3, Std4), and E/O Bandwidth Reflection Response Calibration (Std1, Std2, Std3, Std4), and E/O Bandwidth Reflection Response & Isolation Calibration (Std1, Std2, Std3, Std4)

```
Public Function EORFRESP_STD2Open() As Integer
```

Description: Measures the calibration standard 2 for an E/O reflection response calibration.

Pre-Conditions: EORFRESP_STD1 has been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 2 for an E/O reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

```
Public Function EORFRESP_STD3Short() As Integer
```

Description: Measures the calibration standard 3 for an E/O reflection response calibration.

Pre-Conditions: EORFRESP_STD1 and EORFRESP_STD2Open have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 3 for an E/O reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function EORFRESP_STD4Load() As Integer

Description: Measures the calibration standard 4 for an E/O reflection response calibration.

Pre-Conditions: EORFRESP_STD1, EORFRESP_STD2Open and EORFRESP_STD3Short have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 4 for an E/O reflection response calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Measurement Connections in [Figure 4-25](#) are for a device under test, after performing an E/O reflection response calibration.



Figure 4-25. Measurement Connections for a Device Under Test after an E/O Reflection Response Calibration

Public Function EOBWNRFPRESP_STD1() As Integer

- Description:** Measures calibration standard 1 for an E/O bandwidth and reflection response.
- Pre-Conditions:** The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 1 for an E/O bandwidth and reflection response calibration has been performed.
-

Public Function EOBWNRFPRESP_STD2Open() As Integer

- Description:** Measures calibration standard 2 for an E/O bandwidth and reflection response.
- Pre-Conditions:** EOBWNRFPRESP_STD1 has been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 2 for an E/O bandwidth and reflection response calibration has been performed.
-

Public Function EOBWNRFPRESP_STD3Short() As Integer

- Description:** Measures calibration standard 3 for an E/O bandwidth and reflection response.
- Pre-Conditions:** EOBWNRFPRESP_STD1 and EOBWNRFPRESP_STD2Open have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 3 for an E/O bandwidth and reflection response calibration has been performed.
-

Public Function EOBWNRFPRESP_STD4Load() As Integer

- Description:** Measures calibration standard 4 for an E/O bandwidth reflection response.
- Pre-Conditions:** EOBWNRFPRESP_STD1, EOBWNRFPRESP_STD2Open and EOBWNRFPRESP_STD3Short have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 4 for an E/O bandwidth reflection response calibration has been performed.

Public Function EOBWNRFPRESP_STD5() As Integer

- Description:** Measures bandwidth response calibration standard for an E/O bandwidth reflection response.
- Pre-Conditions:** EOBWNRFPRESP_STD1, EOBWNRFPRESP_STD2Open, BWNRFRESP_STD3Short and EOBWNRFPRESP_STD4Load have been performed. The connections in [Figure 4-26 on page 4-72](#) have been made on the instrument.
- Post-Conditions:** Bandwidth response standard for an bandwidth reflection response calibration has been performed.

Remote Operation
Calibration Methods



Figure 4-26. Connections for E/O Bandwidth Reflection Response Calibration (Std5), and E/O Bandwidth Reflection Response & Isolation Calibration (Std5)

Measurement Connections in [Figure 4-27 on page 4-72](#) are for a device under test, after performing an E/O bandwidth reflection response calibration.



Figure 4-27. Measurement Connections for a Device Under Test after an E/O Bandwidth Reflection Response Calibration

Public Function EOBWNRFPRESPNISOL_STD1() As Integer

Description: Measures calibration standard 1 for an E/O bandwidth reflection response and isolation calibration.

Pre-Conditions: The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 1 for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function EOBWNRFPRESPNISOL_STD2Open() As Integer

Description: Measures calibration standard 2 for an E/O bandwidth and reflection response and isolation calibration.

Pre-Conditions: EOBWNRFPRESPNISOL_STD1 has been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 2 for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function EOBWNRFPRESPNISOL_STD3Short() As Integer

Description: Measures calibration standard 3 for an E/O bandwidth and reflection response and isolation calibration.

Pre-Conditions: EOBWNRFPRESPNISOL_STD1 and EOBWNRFPRESPNISOL_STD2Open have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.

Post-Conditions: Standard 3 for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Public Function EOBWNRFPRESPNISOL_STD4Load() As Integer

- Description:** Measures calibration standard 4 for an E/O bandwidth and reflection response and isolation calibration.
- Pre-Conditions:** EOBWNRFPRESPNISOL_STD1, EOBWNRFPRESPNISOL_STD2Open and EOBWNRFPRESPNISOL_STD3Short have been performed. The following connections in [Figure 4-24 on page 4-68](#) have been made on the instrument.
- Post-Conditions:** Standard 4 for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
-

Public Function EOBWNRFPRESPNISOL_STD5() As Integer

- Description:** Measures bandwidth response calibration standard for an E/O bandwidth and reflection response and isolation calibration.
- Pre-Conditions:** EOBWNRFPRESPNISOL_STD1, EOBWNRFPRESPNISOL_STD2Open, EOBWNRFPRESPNISOL_STD3Short and EOBWNRFPRESPNISOL_STD4Load have been performed. The following connections in [Figure 4-26 on page 4-72](#) have been made on the instrument.
- Post-Conditions:** Bandwidth response standard for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.
-

Public Function EOBWNRFPRESPNISOL_STD6() As Integer

- Description:** Bandwidth isolation standard for an E/O bandwidth and reflection response and isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Pre-Conditions: EOBWNRFPRESPNISOL_STD1, EOBWNRFPRESPNISOL_STD2Open, EOBWNRFPRESPNISOL_STD3Short, EOBWNRFPRESPNISOL_STD4Load and EOBWNRFPRESPNISOL_STD5 have been performed. The following connections in [Figure 4-23 on page 4-67](#) have been made on the instrument.

Post-Conditions: Standard for Bandwidth and Reflection Response and Isolation calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.

Measurement Connections in [Figure 4-22 on page 4-65](#) are for a device under test, after performing an E/O bandwidth and reflection response and isolation calibration.

Public Function EOREFSENSE_STD1() As Integer

Description: Measures the reflection sensitivity calibration standard for an E/O reflection sensitivity calibration.

Pre-Conditions: The following connections in [Figure 4-28 on page 4-76](#) have been made on the instrument.

Post-Conditions: Reflection sensitivity standard for an E/O reflection sensitivity calibration has been performed. Returns 0 if the calibration succeeds and -1 if the calibration fails.



Figure 4-28. Connection for E/O Reflection Sensitivity Calibration (Std1)

Measurement Connections in [Figure 4-29 on page 4-76](#) are for a device under test, after performing an E/O reflection sensitivity calibration.




Figure 4-29. Measurement Connections for a Device Under Test after an E/O Reflection Sensitivity Calibration

86032A Testset Methods

The following methods are used to control the 86032A optical testset. These methods shouldn't normally be used.

```
Public Function gTestSetSetup(lboolLaserON As Boolean, lsnglLaserPower As Single, lsnglModBias As Single, lsnglReflectionSTD As Single, lsnglBiasInterval As Single, lintMode As Integer, lsnglCouplerPower As Single, lsnglReceiverPower As Single, lsnglPowerLevel1 As Single, lsnglPowerLevel2 As Single, lsnglPowerLevel3 As Single, lsnglPowerLevel4 As Single, lsnglSourcePowerEO As Single, lsnglSourcePowerOE As Single) As Integer
```

Description:

Returns the above 86032A testset values.

- **boolLaserON:** TRUE - Internal laser is enabled (turned on). FALSE - Internal laser is disabled (turned off) without modifying the power applied to the laser.
- **snglLaserPower:** A 32-bit signed number (Single) representing internal laser output power in dBm. Range is -10 dBm to +10dBm.
- **snglModBias:** A 32-bit signed number (Single) representing the internal modulator bias voltage in volts. Range is - 10 to +10 volts.
- **snglReflectionSTD:** A 32-bit signed number (Single) representing the percent of reflection of the optical reflection standard used for optical reflection calibrations. Range is 0 to 100. 100 represents 100 % reflected power from the standard.
- **snglBiasInterval:** An integer representing the number of minutes between the internal modulator auto-biases.
- **intMode:** An integer value that determines which mode the optical testset is in.

OTOO = 0 Optical To Optical

OTOE = 1 Optical to Electrical

ETOO = 2 Electrical to Optical

ETOE = 3 Electrical to Electrical

Remote Operation
86032A Testset Methods

Pre-Conditions: Optical test set has been initialized, either through the use of properties or by calling SysInit.

Post-Conditions: Above values are returned.

Public Function TurnLaserOn() as Integer

Description: Turns on the 86032A testset internal laser at the current defined laser power.

Public Function TurnLaserOff() as Integer

Description: Turns off the 86032A testset internal laser.

Public Function sBiasModAuto() as Integer

Description: Performs an auto-bias on the 86032A testset internal modulator.

Public Function sBiasModMax() as Integer

Description: Biases the 86032A testset internal modulator for max power output.

Public Function sModeOO() as Integer

Description: Puts the internal testset switch into optical mode.

Pre-Conditions: None.

Post-Conditions: test set is in optical mode.

Public Function sModeOE() as Integer

Description: Puts the internal testset switch into optical mode.

Pre-Conditions: None.

Post-Conditions: test set is in optical mode.

```
Public Function sModeEO() as Integer
```

Description: Puts the internal testset switch into electrical mode.

Pre-Conditions: None.

Post-Conditions: test set is in electrical mode.

```
Public Function sModeEE() as Integer
```

Description: Puts the internal testset switch into electrical mode.

Pre-Conditions: None.

Post-Conditions: test set is in electrical mode.

```
Public Function gVoltageLevels(Pwr1 As Single, Pwr2 As Single, Pwr3 As Single, Pwr4 As Single)
```

Description: Returns the 86032A testset power supply output voltages.

Pre-Conditions: None.

Post-Conditions: Values returned are those of the individual supply voltages within the optical testset.

Enumerated Values

Many of the parameters to the Server's methods have been enumerated to easy in programming the 86030A. These enumerated values are listed below.

```
Public Enum enumPointType
INVALID_POINTS = -1
POINTS51 = 51
POINTS101 = 101
POINTS201 = 201
POINTS401 = 401
POINTS801 = 801
MaxCalPoints = 801
End Enum
```

Description: Enumerates the valid number of points the system accepts for calibration.

```
Public Enum enumTraceType
COMPLEX_TYPE = 0
LOGMAG_TYPE = 1
PHASE_TYPE = 2
DELAY_TYPE = 3
End Enum
```

Description: Enumerates the valid trace types.

```
Public Enum enumStandards
OO_BW_RESPONSE = 0
OO_BW_RESPNISOL = 1
OO_RF_RESPONSE = 2
OO_RF_RESPNISOL = 3
OE_BW_RESPONSE = 4
OE_BW_RESPNISOL = 5
OE_RF_RESPONSE = 6
OE_RF_RESPNISOL = 7
OE_BWNRF_RESPONSE = 8
OE_BWNRF_RESPNISOL = 9
OE_RESPNMATCH = 10
EO_BW_RESPONSE = 11
EO_BW_RESPNISOL = 12
```

```
EO_RF_RESPONSE = 13  
EO_RF_RESPNISOL = 14  
EO_BWNRF_RESPONSE = 15  
EO_BWNRF_RESPNISOL = 16  
EO_REFSENSE = 17  
End Enum
```

Description: Enumerates the valid calibrations for the system.

```
Public Enum enumStatus  
SYSTEM_NORMAL  
SYSTEM_ERR_UNDEFINED End Enum
```

Description: These enumerated values provide information about system status or state. A definition for each follows below.

- SYSTEM_NORMAL indicates the system is functioning normally.
- SYSTEM_ERR_UNDEFINED indicates that an error has been encountered that is not defined.

System Messages

TestSet Errors	ERR_AUTOBIAS_LASER_NOT_ON ERR_RFLSTD_INVALID ERR_BIAS_INTRVL_INVALID ERR_INVALID_LASER_POWER ERR_INVALID_BIAS_VOLTAGE ERR_INVALID_MODE ERR_POWER_COUPLER_NOT_SETTLED
TestSet Actions	SYS_TS_LASERON SYS_TS_LASEROFF SYS_TS_AUTOBIAS
System Errors	ERR_INVALID_CALIBRATION ERR_MAINCONFIG_FILE_MISSING ERR_INI_FILE_MISSING ERR_CALIBRATION_FILE_MISSING ERR_INIFILE_MISSING_VER ERR_INI_TESTSET ERR_LCA_DIRECTORY ERR_MAIN_DIRECTORY ERR_MAINCONFIG_FILE_MISSING ERR_SYSTEM_ALREADY_RUNNING ERR_SYSTEM_NOT_RUNNING ERR_NOVALID_DATA ERR_FILE_NOT_FOUND ERR_CAL_STD_OUT_OF_SEQUENCY ERR_CALIBRATION_STDS_MISSING

System Actions

SYS_INITIALIZING
SYS_INIT_GPIB
SYS_INIT_TESTSET
SYS_INIT_GETINIT_FILES
SYS_INIT_GUI
SYS_INIT_VNA
SYS_INIT_AUTOBIAS
SYS_SHUTDOWN
SYS_SHUTDOWN_GPIB
SYS_SHUTDOWN_CLNUP
SYS_VERIFY
SYS_VERIFY_FINISH

**Network Analyzer
Errors**

ERR_UNDETERMINED_VNA
ERR_EO_PWR_INVALID
ERR_OE_PWR_INVALID
ERR_INVALID_START_FREQUENCY
ERR_INVALID_STOP_FREQUENCY
ERR_INVALID_NUM_POINTS
ERR_INVALID_AVERAGE

**Network Analyzer
Actions**

SYS_WRITING_VNA_COMMAND
SYS_READING_VNA_RESPONSE
SYS_REQUESTING_CALDATA
SYS_RECEIVING_CALDATA
SYS_REQUESTING_TRACEDATA
SYS_RECEIVING_TRACEDATA

Optical Test Set Error and Action Messages with Descriptions

ERR_AUTOBIAS_LASER_NOT_ON

The internal laser has been detected to be off. This is detected before and auto bias of the internal optical modulator is performed. This error can be reached if the laser is off, or if the laser power is too low. The laser can be turned off through software or through the use of the front panel key. The auto bias requires enough power to be present to auto bias the modulator. The default laser power setting that is applied during initialization is guaranteed to provide enough power.

Status register value (hexidecimal): 80040201

ERR_RFLSTD_INVALID

An invalid value has been applied for the reflection standard.

Status register value (hexidecimal): 80040202

ERR_BIAS_INTRVL_INVALID

An invalid value has been applied for the bias interval.

Status register value (hexidecimal): 80040203

ERR_INVALID_LASER_POWER

An invalid value has been applied for the laser power.

Status register value (hexidecimal): 80040204

ERR_INVALID_BIAS_VOLTAGE

An invalid value has been applied for the bias voltage to the optical modulator.

Status register value (hexidecimal): 80040205

ERR_INVALID_MODE

An invalid value has been applied for the mode of the system.

Status register value (hexidecimal): 80040206

ERR_POWER_COUPLER_NOT_SETTLED

The value read from the internal coupler that resides after the optical modulator is not stable. This can occur due to instability in the path from the laser to the coupler. A more common error is that the laser power is too low. Increase the laser power.

Status register value (hexidecimal): 80040207

SYS_TS_LASERON

The system is in the progress of turning on the laser.

Status register value (hexidecimal): 8004021E

SYS_TS_LASEROFF

The system is in the progress of turning off the laser.

Status register value (hexidecimal): 8004021F

SYS_TS_AUTOBIAS

The system is in the progress of auto biasing the optical modulator.

Status register value (hexidecimal): 80040220

System Error and Action Messages with Descriptions

ERR_INVALID_CALIBRATION

A calibration has been invalidated.
Status register value (hexidecimal): 80040265

ERR_MAINCONFIG_FILE_MISSING

The main configuration (configMain.ini) file is missing.
Status register value (hexidecimal): 80040266

ERR_INI_FILE_MISSING

The file config86030ASN.ini is missing.
Status register value (hexidecimal): 80040267

ERR_CALIBRATION_FILE_MISSING

The systems calibration file (LWCxxxxx) is missing. Where xxxxx is the system service number.
Status register value (hexidecimal): 80040268

ERR_INIFILE_MISSING_VER

The file ConfigVerDev.ini is missing.
Status register value (hexidecimal): 8004026E

ERR_INI_TESTSET

The file testset configuration file (config86030Axxxxx.ini) is missing. Where xxxxx is the system service number.

Status register value (hexadecimal): 8004026F

ERR_LCA_DIRECTORY

The directory D:\LCA50GHz is missing or corrupted.

Status register value (hexadecimal): 80040272

ERR_MAIN_DIRECTORY

The directory C:\Program Files\Agilent\86030a is missing or corrupted.

Status register value (hexadecimal): 80040271

ERR_MAINCONFIG_FILE_MISSING

The main configuration file ConfigMain.ini is missing from C:\Program Files\Agilent\86030a

Status register value (hexadecimal): 80040266

ERR_SYSTEM_ALREADY_RUNNING

There has been an attempt to start the system when it is already running.

Status register value (hexadecimal): 80040273

ERR_SYSTEM_NOT_RUNNING

There has been an attempt to call methods of the server before the method SysStartUp has been called.

Status register value (hexadecimal): 80040274

ERR_NOVALID_DATA

Attempt to retrieve data that does not exist.

Status register value (hexidecimal): 8004026A

ERR_FILE_NOT_FOUND

Attempt to access a file that does not exist.

Status register value (hexidecimal): 3EC

ERR_CAL_STD_OUT_OF_SEQUENCY

One of the calibration standards has been called out of order.

Status register value (hexidecimal): 80040275

ERR_CALIBRATION_STDS_MISSING

One of the calibration standards is missing. This error arises when the calibration method that was called does not complete successfully.

Status register value (hexidecimal): 8004026D

SYS_INTIALIZING

System is in the progress of Initializing.

Status register value (hexidecimal): 80040282

SYS_INIT_GPIB

System is in the progress of initializing GPIB communication to the 8510 network analyzer.

Status register value (hexidecimal): 80040283

SYS_INIT_TESTSET

System is in the progress of initializing the optical test set.

Status register value (hexidecimal): 80040284

SYS_INIT_GETINIT_FILES

System is in the progress of accessing initialization files.

Status register value (hexidecimal): 80040285

SYS_INIT_GUI

System is in the progress of initializing the GUI.

Status register value (hexidecimal): 80040286

SYS_INIT_VNA

System is in the progress of initializing the 8510 network analyzer.

Status register value (hexidecimal): 80040287

SYS_INIT_AUTOBIAS

System is in the progress of performing an initial auto bias.

Status register value (hexidecimal): 80040288

SYS_SHUTDOWN

System is in the progress of shutting down.

Status register value (hexidecimal): 80040289

SYS_SHUTDOWN_GPIB

System is in the progress of shutting down the GPIB communication drivers.

Status register value (hexidecimal): 8004028A

SYS_SHUTDOWN_CLNUP

System is in the progress of cleaning up system resources.

SYS_VERIFY

System is in the progress of performing a system verification.

Status register value (hexidecimal): 8004028C

SYS_VERIFY_FINISH

System is in the progress of analyzing system verification data to determine system integrity.

Status register value (hexidecimal): 8004028D

Network Analyzer Error and Action Messages with Descriptions

ERR_UNDETERMINED_VNA

An error has occurred within the 8510 network analyzer.
Status register value (hexidecimal): 800402C9

ERR_EO_PWR_INVALID

An invalid power has been specified for the 8510 source when the system is operating in electrical to optical mode.
Status register value (hexidecimal): 800402CA

ERR_OE_PWR_INVALID

An invalid power has been specified for the 8510 source when the system is operating in optical to electrical mode.
Status register value (hexidecimal): 800402CB

ERR_INVALID_START_FREQUENCY

An invalid start frequency has been specified for the 8510.
Status register value (hexidecimal): 800402CC

ERR_INVALID_STOP_FREQUENCY

An invalid stop frequency has been specified for the 8510.
Status register value (hexidecimal): 800402CE

ERR_INVALID_NUM_POINTS

An invalid number of points has been specified for the 8510.

Status register value (hexidecimal): 800402CF

ERR_INVALID_AVERAGE

An invalid number of averages has been specified for the 8510.

Status register value (hexidecimal): 800402D0

SYS_WRITING_VNA_COMMAND

System is in the progress of writing a command to the 8510.

Status register value (hexidecimal): 800402E6

SYS_READING_VNA_RESPONSE

System is in the progress of getting a response from the 8510.

Status register value (hexidecimal): 800402E7

SYS_REQUESTING_CALDATA

System is in the process of requesting calibration data from the 8510.

Status register value (hexidecimal): 800402E8

SYS_RECEIVING_CALDATA

System is downloading calibration data from the 8510.

Status register value (hexidecimal): 800402E9

SYS_REQUESTING_TRACEDATA

System is in the process of requesting measurement data from the 8510.

Status register value (hexidecimal): 800402EA

SYS_RECEIVING_TRACEDATA

System is in the process of receiving measurement data from the 8510.

Status register value (hexidecimal): 800402EB

Error Codes and Error Handling

You can use two different approaches to obtain error information using the 86030A remote operation.

- In the first approach you can use the return values of methods and the system status register.
- In the second approach you can use the `ERRHANDLER` event provided by the server.

Almost all methods return a 0 or a -1 to indicate success or failure respectively. If the method was successful (returned a 0), there is no reason to query the system status register. If a -1 was returned, then the system status register can provide information as to the reason for the error. The system status register can take on the values of the `enumStatus` type. If the value of the status register is prefixed with an `EER` this represents the last error encountered while the method was executing. If the value of the status register is prefixed with an `SYS` this indicates the last action the server was performing when an error was encountered.

The second approach, using the `ERRHANDLER` event, provides more descriptive error information. The handle to the 86030A server object must be declared `WithEvents`. Then an error handler must be written on the client or controlling computer to use this method of retrieving error information. This handler returns both a string containing description, and an error code. The definition of the `ERRHANDLER` is repeated below.

```
Public Event ERRHANDLER(strERROR As String, intErrorCode As enumStatus)
```

The variable `strERROR` contains a string that helps better identify and explain the cause of the error encountered. The variable `intErrorCode` returns one of the enumerated values defined in `enumStatus`. Together these values provide details to the cause of errors encountered.

System Operation 5-2
Lightwave Test Set Operation 5-3
Measurement Calibration 5-6
O/O Measurement Calibration 5-7
O/E Measurement Calibration 5-9
E/O Measurement Calibration 5-11
Electrical Measurement Calibration 5-14
O/E Display Scaling Calculations 5-16
E/O Display Scaling Calculations 5-17
O/O Display Scaling Calculations 5-18

Theory of Operation

System Operation

The lightwave test set is designed to operate with an 8510C microwave network analyzer system. Figure 5-1 shows a conceptual system block diagram. The 8510C network analyzer system consists of a microwave source, a reference receiver, and one or more measurement receivers. The microwave source is applied to the 86032A RF INPUT. The lightwave test set then provides a reference signal to the 8517B electrical test set, which provides a reference signal to the network analyzer. This reference signal is used for phase lock of the system.

The conceptual system block diagram shows an optical-to-optical (O/O) DUT (fiber) measurement configuration. The signal is routed from the OPTICAL OUTPUT through the fiber, demodulated by the test set's optical receiver, and then routed to the analyzer's measurement receiver. A similar configuration is used for electrical-to-optical (E/O) DUTs, except the device drive signal is the lightwave test set's RF OUTPUT. For O/E DUTs, the drive signal is from the OPTICAL OUTPUT and the DUT signal is routed to the analyzer's measurement receiver.




Figure 5-1. Conceptual System Block Diagram

Lightwave Test Set Operation

The lightwave test set consists of four major functional blocks:

- Lightwave source deck (LSD)
- Amplified optical receiver
- Microwave modulation
- Printed circuit boards containing the internal amplifiers and other microcircuits




Figure 5-2. 86032A Test Set Block Diagram

Lightwave Source Deck

The lightwave source deck converts RF energy into modulated laser light. The source of light is an unmodulated (CW) semiconductor distributed feedback laser (DFB) operating at approximately 1550 nm. The light is directed through a high-performance isolator (greater than 90 dB isolation) to prevent reflections from affecting the semiconductor laser.

A key component of the lightwave source deck is the lithium niobate (LiNbO_3) modulator. To work correctly, the modulator is biased with a fixed dc offset (quadrature voltage—half way between maximum and minimum optical intensity) that is supplied by the digital to analog converter. The modulator bias level is under PC control for optimal performance and to reduce unwanted effects such as source signal level drift.

After exiting the modulator, the laser light is routed to the front panel OPTICAL OUTPUT connector via a 5/95 coupler. The 5% arm of the optical coupler is used to monitor the average optical power that is delivered to the OPTICAL OUTPUT of the lightwave test set. Appropriate corrections are made to the modulator bias by the 86030A software to keep the modulator bias point at quadrature. The software initiates the modulator bias adjustment after every Mode Change to O/O and O/E. It can also be user initiated through the Auto Bias feature.

Amplified Optical Receiver

The amplified optical receiver completes the lightwave path. This receiver consists of a high speed photodiode followed by RF amplification.

The lightwave receiver is the key component for the measurement calibration. A factory measurement of the magnitude and phase response of the lightwave receiver is saved on the hard drive of the PC and also on the supplied backup disk. This factory calibrated optical receiver becomes the standard for both optical-to-electrical and electrical-to-optical calibrations.

Microwave Modulation

The 85107 RF network analyzer's microwave source is applied to the rear-panel RFINPUT connector of the lightwave test set. This signal is split internally. One path goes to the RF reference output connector for the lightwave test set used to phase lock the 85107 system. The other path from the splitter is routed to an RF switch. The RF switch is controlled by the 86030A software. Depending on the measurement mode selected by the user, the switch routes the signal to either the optical modulator (O/O and O/E modes), or to the RF OUTPUT port of the 86032A lightwave test set (E/O mode).

Main Printed Circuit Board

The internal printed circuit (PC) board provides the correct drive voltages to the internal microcircuits.

Drive Voltages

The power supply provides five voltages (+15V, -15V, +6V, +5V).

Note

The lightwave test set power switch will need to be in the ON state, even for electrical-to-electrical (E/E) measurements.

Measurement Calibration


The lightwave test system provides calibrated measurements of lightwave components. The reference for an E/O (electrical to optical) and an O/E (optical to electrical) measurement is the lightwave photodiode receiver.

Calibration Data

The response (magnitude and phase) of the lightwave receiver in your test set is measured at the factory and stored on a disk. This calibration data is combined with the user calibration measurement to provide accurate lightwave component analysis.

O/O Measurement Calibration

A measurement calibration for an optical to optical device is a thru response calibration of an optical cable. The measurement of the optical device under test (DUT) is displayed relative to the thru line. When the device is measured, the response displayed is the device under test. The analyzer firmware performs the mathematical operations. The following figure shows the calibration measurement and device measurement configurations.



Theory of Operation
O/O Measurement Calibration

These are the equations for the calibration and device measurements:

$$\begin{aligned} \text{calibration measurement} &= (ES)(OS)(LWCABLE)(OR)(ER) \\ \text{device measurement} &= (ES)(OS)(DUT)(LWCABLE)(OR)(ER) \end{aligned}$$

Therefore:


$$\begin{aligned} \text{device measurement} / \text{calibration measurement} &= \\ \frac{(ES)(OS)(DUT)(LWCABLE)(OR)(ER)}{(ES)(OS)(LWCABLE)(OR)(ER)} &= DUT \text{ response} \end{aligned}$$

Where:

- ES = electrical source
- OS = optical source
- LWCABLE = lightwave cable
- OR = optical receiver
- ER = electrical receiver
- DUT = device under test
- ECABLE = electrical cable
- ORCAL = optical receiver calibration data

O/E Measurement Calibration

A user measurement calibration for an optical to electrical device is combined with the calibration data stored on disk to provide accurate optical to electrical device characterizations. The following figure shows the calibration measurement and device measurement configurations.



O/E Measurement Calibration

These are the equations for the calibration and device measurements:

$$\text{calibration measurement} = (ES)(OS)(LWCABLE)(OR)(ECABLE)(ER)$$

$$\text{device measurement} = (ES)(OS)(LWCABLE)(DUT)(ECABLE)(ER)$$

The calibration measurement is combined with the optical receiver response data (contained on disk) to form a calibration response.

Therefore:

$$\begin{aligned} & \text{device measurement} / \text{calibration measurement} = \\ & \frac{(ES)(OS)(DUT)(LWCABLE)(ECABLE)(ER)}{(ES)(OS)(LWCABLE)(OR)(ECABLE)(ER)(1/ORCAL)} = DUT \text{ response} \end{aligned}$$


Where:

- ES = electrical source
- OS = optical source
- LWCABLE = lightwave cable
- OR = optical receiver
- ER = electrical receiver
- DUT = device under test
- ECABLE = electrical cable
- ORCAL = optical receiver calibration data

The optical receiver response calibration data (contained on disk) and the optical receiver response are ideally the same: $(OR)(1/(OR)) = 1$. Differences between these are reflected in the response uncertainty.

E/O Measurement Calibration

The measurement calibration for an electrical to optical device is accomplished by measuring the microwave path from the lightwave test set to the network analyzer. The microwave response of the system is now known, and is combined with the lightwave test set optical receiver response to provide a complete response calibration. In the device measurement, the response calibration is subtracted from the full path measurement, leaving only the response of the DUT. The optical cable connected between the DUT and the lightwave receiver contributes to the DUT response. The following figure shows the calibration measurement and device measurement configurations.



eoc
Electrical to Optical Configurations

These are the equations for the calibration and device measurements:

$$\text{calibration measurement} = (ES)(ECABLE)(ER)$$

The calibration measurement is combined with the test set optical receiver response data in the analyzer to form a calibration response.

$$\text{calibration response} = (ES)(ECABLE)(ER)(ORCAL)$$

$$\text{device measurement} = (ES)(ECABLE)(DUT)(LWCABLE)(OR)(ER)$$

Therefore:

$$\frac{\text{device measurement} / \text{calibration measurement}}{(ES)(ECABLE)(ER)(ORCAL)} = (DUT)(LWCABLE)$$

Where:

- ES = electrical source
- OS = optical source
- LWCABLE = lightwave cable
- OR = optical receiver
- ER = electrical receiver
- DUT = device under test
- ECABLE = electrical cable
- ORCAL = optical receiver calibration data

A port extension should be added in order to mathematically remove the electrical length added by the lightwave cable. Lightwave cables less than 10 meters long have negligible frequency response.

Port Extensions

The 8510C port extension is accessed from the CAL front panel key. To add a port extension and remove the effects of the lightwave cable in an E/O measurement, press:

CAL, MORE, PORT EXTENSIONS 2

Enter the delay time associated with the length of the lightwave cable that is connected between the E/O device and the lightwave receiver. Terminate the entry by pressing the G/n key on the analyzer.

For example: a 40 cm cable with an index of refraction of 1.46 has a delay of:

$$t = Ln/v = ((40 \text{ cm})(1.46))/3 \times 10^{10} \text{ cm/s} = 1.95 \text{ ns}$$

Electrical Measurement Calibration

The measurement calibration for electrical devices does not involve the lightwave test set. Refer to the network analyzer documentation for information on performing microwave measurements and calibrations.

Bias Voltage to the Modulator

Under typical circumstances, the lightwave modulator is biased to operate at quadrature. Quadrature is where the midpoint of the average optical power curve and the peak of the modulated optical power curve occur. Refer to [Figure 5-3](#). This maximizes the modulation response and minimizes distortion of the modulated signal.




Figure 5-3. The Effect of Bias Voltage on Average and Modulated Optical Power

O/E Display Scaling Calculations

The marker reads out the actual value in dB compared to 1 amp/watt responsivity. Suppose marker 1 has a value of 36 dB, indicating the gain of the receiver at a specific frequency. This corresponds to the responsivity (R) of the receiver in A/W, at the given frequency, that can be calculated as shown below.

R (dB) = responsivity in dB at a given frequency compared to 1 A/W as read by the 86030A

R (A/W) = responsivity in units of amps/watt

$$R(dB) = 20 \log_{10} \frac{R(A/W)}{1(A/W)}$$

$$\frac{R(dB)}{20} = \log_{10} \frac{R(A/W)}{1(A/W)}$$

$$1(A/W) \times 10^{R(dB)/20} = \frac{R(A/W)}{1(A/W)} \times 1(A/W)$$

$$R(A/W) = 10^{R(dB)/20} \times 1(A/W)$$

For example, if R(dB) = +36 dB, then:

$$R = 10^{(36/20)} = 10^{1.8} = 63.1(A/W) = 63.1 \frac{mA}{mW}$$

To read the result directly, in the FORMAT area press MENU, then LINEAR MAGNITUDE.

E/O Display Scaling Calculations

The marker reads out the actual value in dB compared to 1 watt/amp responsivity. Suppose marker 1 has a value of -40 dB, indicating the efficiency of the transmitter at a specific frequency. (This is a typical value for a LiNbO₃ optical modulator.) This corresponds to the responsivity (R_s) of the transmitter in W/A, at the given frequency, that can be calculated as shown below.

R_s (dB) = responsivity in dB at a given frequency compared to 1 W/A as read by the 86030A

R_s (W/A) = responsivity in units of watts/amp

$$R_s(\text{dB}) = 20 \log_{10} \frac{R_s(\text{W/A})}{1(\text{W/A})}$$

$$\frac{R_s(\text{dB})}{20} = \log_{10} \frac{R_s(\text{W/A})}{1(\text{W/A})}$$

$$1(\text{W/A}) \times 10^{R_s(\text{dB})/20} = \frac{R_s(\text{W/A})}{1(\text{W/A})} \times 1(\text{W/A})$$

$$R_s(\text{W/A}) = 10^{R_s(\text{dB})/20} \times 1(\text{W/A})$$

For example, if $R(\text{dB}) = -40 \text{ dB}$, then:

$$R = 10^{(-40/20)} = 10^{-2} = .01(\text{W/A}) = .01 \frac{\text{mW}}{\text{mA}}$$

To read the result directly, in the FORMAT area press MENU, then LINEAR MAGNITUDE.

O/O Display Scaling Calculations

The 0/0 mode scales the vertical axis using the formula:

$$Gain (dB) = 10 \log \frac{P}{P_{ref}}$$

Thus, the gain is in optical dBs.

P_{ref} is the power measured in the reference calibration trace. Optical through lines are most often used in the reference calibration.

To read the result directly, in the FORMAT area press MENU, then *LINEAR MAGNITUDE*.

Lightwave Verification 6-3

If the Lightwave Verification Test Fails 6-7

System Verification

Introduction

In order to verify the system, it is necessary to perform the procedures described here. The recommended verification cycle is one year.

The system verification monitors the long-term stability and repeatability of the system hardware.

Note

Although this lightweight verification is a subset of the total process for verifying the system's conformance to specifications, this procedure can be used alone as a functional test and can be helpful in the following ways:

- It can be used at incoming inspection to check that no major degradation has occurred in the system during shipment.
- It provides a means to periodically monitor measurement stability.
- It can help isolate the cause of incorrect measurement results. (When the system passes the test, you will have confidence the system is operating correctly and any problem is in the setup or DUT.)

Lightwave Verification

Description

A verification device is included in the N1012A Verification Kit. It consists of a lightwave detector and its associated amplitude and phase data. This verification device can be used at any time to verify the measurement integrity of your system. A guided verification routine is provided which measures the verification device, and displays a graph of its response versus acceptable tolerances. The verification device can be used periodically to monitor system calibration, and indicate when the optical test set needs to be recalibrated. It can also be used to resolve uncertainty if unexpected results are obtained from a test device. This verification capability provides confidence in the measurement integrity of the system. If the new data measured does not fall within these limits, refer to [“If the Lightwave Verification Test Fails” on page 6-7.](#)


Procedure

- 1** Load the verification device data into the 86030A. The device data is on the floppy disk that is included in the verification kit.
 - a** Insert the N1012A verification device data disk into the floppy drive of the 86030A system computer.
 - b** From the Windows Desktop, double-click My Computer.
 - c** Double-click on the A: drive and then setup.bat.
- 2** Ensure that the following front panel connections are made:
 - Connect LASER OUTPUT to LASER INPUT.
 - Connect OPTICAL OUTPUT to OPTICAL RECEIVER INPUT.
 - Connect OPTICAL RECEIVER RF OUTPUT to PORT 1 of the electrical test set.
 - Connect a 50-ohm termination to PORT 2 of the electrical test set.
- 3** On the 86032A test set, turn the laser key to the “ON” position.
- 4** On the system computer desktop screen, double-click the 86030A system


System Verification
Lightwave Verification

software icon to start the system software.

- 5 In the **Options** menu, select **System Verification**.




- 6 From the System Verification dialog box, click **Verification**.



- 7 The System Verification procedure will start by performing an auto-bias routine.

NOTE

Ensure that a BNC 50 ohm load is connected to the Port 1 bias tee on the 8517B rear panel.



The screenshot shows a dialog box titled "Modulator Auto-Biasing ...". It contains six input fields with the following values:

Parameter	Value
Power at Quadrature (dBm)	1.6
Voltage at Quadrature (V)	-4.238976
Voltage at Maximum Optical Power (V)	-1.871995
Voltage at Minimum Optical Power (V)	-6.605958
Maximum Optical Power (dBm)	4.1999980926514
Minimum Optical Power (dBm)	-6.30000019073486

An "OK" button is located at the bottom left of the dialog box.


- 8 Follow the on-screen instructions to perform an O/E response and isolation calibration.
- 9 When the calibration procedure is complete, you will be prompted to connect the equipment as shown. The lightwave detector, that is included in the verification kit, is the DUT for the verification procedure. The DUT is powered by a power supply that is also included in the verification kit.

NOTE

Be sure to connect the the dc bias port of the detector to the power supply. Also, be sure to connect the power supply to an AC power outlet.

- 10 Once an entire sweep is displayed on the 8510C, click **OK** to continue.
- 11 The verification process is completed. Click on **Finished** to save and view the verification results on an Excel worksheet.

System Verification
Lightwave Verification



Example of Verification Test Results

If the Lightwave Verification Test Fails

- 1** If any part of the test fails, measurement integrity is not confirmed. Proceed with the following checks.
 - a** Clean all the optical and electrical connectors and make sure the connections are finger tight.
 - b** Clean all the RF connectors and make sure the connections are made to the correct torque. Refer to “Accurate Measurements” on page 2-33.
 - c** Run the lightwave verification test again.
- 2** Check electrical connectors for damage, especially the center female pins.
- 3** Check the flexible 2.4 mm cables for damage.
- 4** If the test still fails, perform an autobias.
 - a** Select Options, Autobias from the menu bar.
 - b** Allow two hours for the modulator to stabilize, and then run the measurement stability test again.
- 5** If the test still fails, reload the verification device data into the 86030A and run the verification test again. The device data is on the floppy disk that is part of the N1012A Verification Kit.
- 6** If the test still fails, refer to [Chapter 7, “Maintenance”](#).

Troubleshooting 7-3
86032A Test Set Troubleshooting Diagnostics 7-7
 To verify the RF path integrity of the 86032A 7-13
Modulator Troubleshooting Tips 7-16
Agilent Technologies Support and Maintenance 7-17
Electrostatic Discharge Information 7-19
Returning the System for Service 7-22
Agilent Technologies Service Offices 7-25
After Repair 7-26
 To install the system calibration files 7-26
 To install the verification device data files 7-26

Maintenance

Maintenance

This chapter shows you how to troubleshoot the system to the instrument level. To prevent voiding product warranty, do not remove any instrument covers. The Agilent 86032A test set is *not* customer serviceable. Do not open the Agilent 86030A covers for any reason.

WARNING

These servicing instructions are for use by qualified personnel only. To avoid electrical shock, do not perform any servicing unless you are qualified to do so.

WARNING

The opening of the system or removal of parts is likely to expose dangerous voltages. Disconnect the product from all voltage sources while it is being opened.

WARNING

The power cord is connected to internal capacitors that may remain live for 5 seconds after disconnecting the plug from its power supply.

WARNING

This is a Safety Class 1 Product (provided with a protective earthing ground incorporated in the power cord). The mains plug shall only be inserted in a socket outlet provided with a protective earth contact. Any interruption of the protective conductor inside or outside of the product is likely to make the product dangerous. Intention interruption is prohibited.

WARNING

To prevent electrical shock, disconnect the Agilent Technologies 86030A system from mains before cleaning. Use a dry cloth or one slightly dampened with water to clean the external case parts. Do not attempt to clean any instrument internally.

CAUTION

The warranty and calibration will be voided on systems where the individual instruments, including fiber-optic cables, RF cables, or GPIB cables are removed by the customer. The system should only be disassembled by an Agilent Technologies Customer Engineer. Instruments should not be swapped or removed by non-Agilent Technologies personnel.

Troubleshooting

Troubleshooting consists of checking the setup and the connections. If a problem persists, contact Agilent Technologies.

Check the Setup

Plug in the system and listen for the sound of the fan. Even in standby (STBY) mode, the E/E LED should be on and the fan should run. Turn on the system. The O/O LED should turn on.

If either LED does not light or if the fan does not run, contact Agilent Technologies.

WARNING

Do NOT, under any circumstances, look into the optical output or any fiber/device attached to the output while the laser is in operation. Refer to “Laser Safety Considerations” on page 2-30 for additional information.

CAUTION

When you use improper cleaning and handling techniques, you risk expensive system repairs, damaged cables, and compromised measurements. Repair of damaged connectors due to improper use is not covered under warranty.

Clean all cables before applying to any connector. Refer to “Choosing the Right Connector” on page 2-33 and to “Inspecting Connectors” on page 2-36.

Use the key to turn on the laser. The laser LED should turn on. If not, check the REMOTE SHUTDOWN BNC connector on the rear panel. That connector must be shorted for the laser (and the front panel LED) to turn on. Connect the BNC short to the connector. If the laser LED does not turn on, contact Agilent Technologies. If the LED does turn on, continue.

If the setup has been changed or the optical power output seems low, you may have to check the optical connections.

Optical connections are a critical part of consistent measurements, as detailed in “Accurate Measurements” on page 2-33. Are all of the connections clean and properly made?

To perform a quick check

Common troubleshooting skills can be used to locate many problems. The following steps are suggested for quickly narrowing down the problem.

- 1 Inquire about recent repairs or changes to the system. Often, this will help pinpoint current problems even if the system was operating correctly after the repair or change to the system.
- 2 Setup or reinstall the 86030A software to determine whether the problem is a hardware or a software problem. Refer to [Chapter 1, “Installation”](#).

Refer to [Table 7-2 on page 7-6](#) for the correct addresses for the computer and the 86030A lightwave component analyzer system. If reinstalling the software does not solve the problem, the problem may not be a software error.

- 3 Check that all system components are wired correctly.
- 4 Remove, clean, and reinstall all optical connections.
- 5 Ensure that all cables are secure.
- 6 Check for a 50Ω load in the two bias ports of the 8517B electrical test set.

To check the 8510C network analyzer

- Refer to the *8510C Onsite Service Guide* (Agilent part number 08510-90282) for 8510C troubleshooting procedures.

To check the computer

- For problems with the personal computer that are unrelated to the rest of the 86030A, refer to the computer manual that was shipped with this system, or call your local IT department.
- If either the wireless keyboard or mouse are not responding, check the batteries.
- Troubleshoot the computer's connection to the 86030A:
 - a Ensure that the GPIB and computer addresses are correct. The correct GPIB and I/O addresses for the computer and system are located in [Table 7-2 on page 7-6](#) and [Table 7-1 on page 7-6](#).

- ❑ Perform the following step:
 - a With a voltage meter, measure the voltage from the cable. It should be reading between 2 and 4 volts.
- ❑ If any of the following system failures occur, you can reinstall the 86030A computer operating system and applications:
 - Windows operating system
 - 86030A measurement application
 - PC applications included on the 86030A system
 - System diagnostic programs

To Reinstall the 86030A System Software

- 1 Move any needed data that is on the 86030A computer hard drive to another storage media. This may include measurement setups as well as measurement data.
- 2 Insert the 86030A Operating System Software disk in the computer CDROM drive. This disk was included in the 86030A shipment.
- 3 Switch the 86030A system power off and then on. The installation program will automatically load. Follow the prompts that appear on the screen to complete the system software installation.
- 4 Refer to “[After Repair](#)” on [page 7-26](#) for instructions on how to reinstall the calibration coefficient file and the verification device data file.

To check the network

- ❑ Make sure the LAN cable is connected properly to the computer.
- ❑ Setup the computer LAN card according to the manufacturer’s specifications.
- ❑ Disconnect the LAN cable, and test it using a LAN cable testing tool.
- ❑ Refer to the Windows NT documentation on networking the system. The Windows NT help system also contains a *Networking Troubleshooter* section which will guide you through the most common networking problems.
- ❑ Refer to your local IT department, or call the Agilent Test and Measurement Customer Support line at (800) 452-4844.
- ❑ Correct GPIB and I/O addresses for the computer and system are located in [Table 7-2 on page 7-6](#) and [Table 7-1 on page 7-6](#).

Maintenance
Troubleshooting

There are many types of inter-office LANs. Because of this, this manual can only give very basic troubleshooting information.

Table 7-1. Computer I/O Addresses

Test Set Component	I/O Address
Modulation Bias DAC	&h300

Table 7-2. GPIB Addresses

Instrument Name	GPIB Address
86032A optical test set	24
8510C network analyzer	16
8517B electrical test set	20
83651B synthesized sweeper	19

86032A Test Set Troubleshooting Diagnostics


Using the 50 GHz LCA Diagnostic software and an electrical power meter with an Agilent/HP 8487A power sensor (2.4 mm connector), you can do a thorough verification of the Agilent 86032A test set. The Diagnostic software will verify the functionality of the:

- laser
- modulator
- receiver
- RF paths

To open the Diagnostic software

- 1 From the **Start** menu, click on **Programs, Agilent Technologies 50 GHz LCA, 50 GHz LCA Diagnostic**.

Maintenance
86032A Test Set Troubleshooting Diagnostics




To verify power supply operation

The purpose of this test is to verify that the 86032A test set is properly connected to the system computer. Verification of the 86032A power supply functionality is also confirmed.

- 2 In the Power Supply Conditions area of the diagnostic software, the left column lists the power supplies used in the 86032A test set. The right column lists the actual value of these power supplies. Make sure that these values are close to the values in the left column.

Power Supply Conditions	
5V =	5.214844
+15V =	14.91211
-15V =	-14.90234
6V =	5.996094


Tip: When the power supplies are functioning properly, the Status area will display “Test Set is Connected.”



To verify System Mode switching function

The purpose of this test is to verify that you can control the electrical switch inside the 86032A test set.

- 3 In the Front Panel LEDs area of the diagnostic software, click on each of the four system modes in the following order: **E/E**, **O/E**, **E/O** then **O/O**.



- 4 For each mode, you should hear a clicking noise from the 86032A test set indicating that the switch is working. Also, as each mode is selected, verify that the corresponding LED lights up on the test set front panel.

To check laser conditions

The purpose of this test is to see if the internal DFB laser is producing the correct amount of output power.

WARNING


Do NOT, under any circumstances, look into the optical output or any fiber/device attached to the output while the laser is in operation.

Refer to “Laser Safety Considerations” on page 2-30 for additional information.


Note

To verify proper operation of the laser, the laser must be controlled via the 50 GHz Diagnostic software. Also, insure that a BNC short is connected to the Laser Remote Shutdown connector on the 86032A rear panel.

- 5 Select a fiber cable from the 86030A verification kit.
- 6 Clean and then connect the cable between the 86032A OPTICAL OUTPUT and the OPTICAL RECEIVER INPUT. Refer to “Cleaning Connectors” on page 2-40.
- 7 On the 86032A front panel, turn the Laser key to the ON position.
- 8 In the Laser Conditions area of the diagnostic software, click the Turn On Laser button. Verify that the 86032A LASER ON LED lights up.



- 9 In the Laser Conditions area, set the Laser Power to 10 dBm and observe the power as indicated in the Output Power area. There should be some indication of power.




The actual power out is not a fixed value since the state of the modulator cannot be predicted. If the laser is not functioning, the power level will register -9999 or some other extremely low value.

To check modulator conditions

The purpose of this test is to see if the electrical input voltage to the modulator can control the modulator loss.

- 10 In the Front Panel LEDs area of the diagnostic software, click on **E/E** to remove the modulation from the lightwave path.
- 11 In the Mod Conditions area, enter 1 Volt in the text box, and then press **Set**. Observe the Output Power level. Now, increase the voltage to 2V. There should be a noticeable change to the Output Power level. There is no way of determining if the power will increase or decrease because it is not known where 1 volt lies on the Modulator Bias Curve. See [Figure 7-1 on page 7-12](#).



- 12 In the 8510C STIMULUS area, select CENTER and enter 25 G (25 GHz), then select SPAN and enter 0 [x1] (0 Hz).
- 13 From the Diagnostic software's **Modulator Bias** menu, select **Trace Out Mod Curve**.

Follow the on-screen instructions. It will take a few minutes to trace the output curve.

- 14 To view the trace, open a session of Excel, then click **File, Open** to open *C:\LCA50GHZ>Data\Pwrcurve*.

This shows the output power versus applied voltage to the optical modulator. The voltage difference between the minimum and maximum power point is referred to as V_{π} . A typical value of V_{π} is between 2.5 and 6 volts. The extinction ratio of the modulator is defined to be the ratio of the maximum power to the minimum power as expressed in dB. The typical value of extinction ratio is between 8 and 20 dB.





Figure 7-1.

To verify the RF path integrity of the 86032A



This series of tests will check the RF path integrity for three different routes.

- Path A, From 83651B input to To 8517B output
- Path B, From 83651B input to Optical Receiver RF Output
- Path C, From 83651B input to RF Output

Path A Test

The purpose of this test is to check Path A continuity.

- 15 Connect an electrical power meter to the 86032A rear panel RF REF OUTPUT.
- 16 In the 8510C STIMULUS area, select CENTER and enter 25 G (25 GHz), then select SPAN and enter 0 [x1] (0 Hz).
- 17 From the 8510 STIMULUS MENU, select Power Menu, Power Source 1 and enter 0 [X1] (0 dBm).

- 18 The power meter should read >5 dBm.

Tip: If the power is low, verify that the power out of the 83651A is 0 dBm. You can verify the power to 83651A by connecting the 8487A power sensor directly to the 83651A rear panel output.

Path B Test

The purpose of this test is to check Path B continuity.

- 19 Connect the 8487A power sensor to the 86032A OPTICAL RECEIVER RF OUTPUT.


Ensure that a fiber cable is connected between the Optical Output and Receiver Input connectors on the front panel.

Tip: You will need a female-to female 2.4 adapter between the power sensor and the RF output, which you can find in the 85056A 2.4 mm calibration kit.

- 20 From the Front Panel LEDs area, click on the O/E mode button.


Setting up the Laser Source Power

- 21 In the Laser Conditions area of the diagnostic software, enter **10** dBm in the text box, and then click **Set**.



Setting Up the Modulator Bias Voltage

- 22 From the Diagnostic software main menu, select **Modulator Bias, Bias Modulator**.



- 23 In the Auto Bias window, click **Bias at Quadrature**.
- 24 Once the auto bias is completed, the power reading in the Output Power area and Optical Receiver Conditions area should be within 1 dB of each other.

This step verifies that there is a low loss connection between the Optical Output port and Optical Receiver Input port.
- 25 Connect the power meter to the OPTICAL RECEIVER RF OUTPUT. The power meter should read > -20 dBm.

Path C Test

The purpose of this test is to check Path C continuity.

- 26 From the Diagnostic Front Panel LEDs area, click on **E/O**.
- 27 Connect the 8487A power sensor to the 86032A RF OUTPUT.

Tip: You will need a female-to-female 2.4 adapter between the power sensor and the RF output.
- 28 In the 8510C STIMULUS area, select CENTER and enter 25 G (25 GHz), then select SPAN and enter 0 [x1] (0 Hz).
- 29 The power meter should read ≥ -5 dBm.
- 30 From the Diagnostic Front Panel LEDs area, click on **O/O**. The power meter reading should go to a very low value.

Modulator Troubleshooting Tips

- If Maximum Optical Power is not greater than 3 dB, the problem could be one of the following.
 - Clean and reconnect the jumper cable that goes between the LASER OUTPUT to the LASER INPUT.
 - From the Start menu, click on Agilent Technologies 50 GHz LCA, and then 50 GHz LCA Diagnostics. In the Diagnostics window, check the Laser Power Setting. The Laser Power should be approximately 10 dBm.
 - If the Voltage at Maximum Optical Power – Voltage at Minimum Optical Power is not between 3 and 6 volts, then try running a manual auto bias. From the Options menu, click on AutoBias, Quadrature.

Agilent Technologies Support and Maintenance

On-site service by an Agilent Technologies customer engineer is available to ensure that your system uptime is maximized. You can order per-incident, contractual, or customized on-site system repair and on-site system calibration services. Just contact your local sales office, and give the operator the name of your company and the city where you're located. Then, ask to speak with a field sales engineer. If you're currently covered by a per-incident, contractual or customized program, contact your customer engineer through your local sales office to obtain on-site service.

Note

On-site repair and calibration are available for the 8510C network analyzer portion of the system in many parts of the world. In some areas, the PC also has on-site support. The 86032A lightwave test set must be returned to the factory for repair and calibration. Contact your local CE for more information. [Refer to "Agilent Technologies Service Offices" on page 7-25.](#)

Definition of On-site System Repair

When you order one of Agilent's on-site system repair options, a customer engineer (CE) is assigned to your company. The CE becomes intimately acquainted with your environment and assumes personal responsibility for managing your system's maintenance program. Your CE will also perform preventive maintenance on a regular basis.

Definition of On-Site System Calibration

When you order an on-site calibration agreement as part of your on-site system repair program, your assigned customer engineer (CE) will have calibrations on your system completed to the same level of quality that is applied to instruments that are returned to Agilent.

Calibration services for systems include the following:

- Calibration measurements traceable to national and international standards
- U.S. measurements traceable to the National Institute of Standards and Tech-

Maintenance

Agilent Technologies Support and Maintenance

nology (NIST)

- Product performance compared to standards of known accuracy to ensure conformance with published specifications
- Calibration at Agilent-recommended intervals
- Complete data reports for all measured product performance
- Calibration certificate and sticker showing date of next scheduled calibration
- Calibration at no charge after a repair performed by Agilent on products covered under a calibration agreement or under Agilent Support Options

Other Test and Measurement Support Programs

In addition to Hardware Support, the Test and Measurement division offers a wide range of other service and support programs.

- Software Support
- Application Consulting and Training
- Solution Engineering and Manufacturing Process Consulting

Electrostatic Discharge Information

Electrostatic discharge (ESD) can damage or destroy electronic components. All work on electronic assemblies should be performed at a static-safe work station. The following figure shows an example of a static-safe work station using two types of ESD protection:


- Conductive table-mat and wrist-strap combination.

Note

For the 86030A 50 GHz LCA system, the static strap is attached to the 86032A front panel grounding receptacle. [Refer to “Front Panel Features” on page 2-8.](#)

- Conductive floor-mat and heel-strap combination.

Maintenance
Electrostatic Discharge Information



Both types, when used together, provide a significant level of ESD protection. Of the two, only the table-mat and wrist-strap combination provides adequate ESD protection when used alone.

To ensure user safety, the static-safe accessories must provide at least $1\text{ M}\Omega$ of isolation from ground. Refer to [Table 2 on page 7-21](#) for information on ordering static-safe accessories.

WARNING

These techniques for a static-safe work station should not be used when working on circuitry with a voltage potential greater than 500 volts.

Reducing ESD Damage

The following suggestions may help reduce ESD damage that occurs during testing and servicing operations.

- Personnel should be grounded with a resistor-isolated wrist strap before removing any assembly from the unit.
- Be sure all instruments are properly earth-grounded to prevent a buildup of static charge.

Table 2. Static-Safe Accessories

Agilent Part Number	Description
9300-0797	Set includes: 3M static control mat 0.6 m × 1.2 m (2 ft. × 4 ft.) and 4.6 cm (15 ft.) ground wire. (The wrist-strap and wrist-strap cord are not included. They must be ordered separately.)
9300-0980	Wrist-strap cord 1.5 m (5 ft.)
9300-1383	Wrist-strap, color black, stainless steel, without cord, has four adjustable links and a 7 mm post-type connection.
9300-1169	ESD heel-strap (reusable 6 to 12 months).

Returning the System for Service

The instructions in this section show you how to properly return the instrument for repair or calibration. Always call the Agilent Instrument Support Center first to initiate service *before* returning your instrument to a service office. This ensures that the repair (or calibration) can be properly tracked and that your instrument will be returned to you as quickly as possible. Call this number regardless of where you are located. Refer to “[Agilent Technologies Service Offices](#)” on page 7-25 for a list of service offices.

Agilent Instrument Support Center (800) 403-0801

If the instrument is still under warranty or is covered by an Agilent maintenance contract, it will be repaired under the terms of the warranty or contract (the warranty is at the front of this manual). If the instrument is no longer under warranty or is not covered by an Agilent maintenance plan, Agilent Technologies will notify you of the cost of the repair after examining the unit.

When an instrument is returned to a Agilent service office for servicing, it must be adequately packaged and have a complete description of the failure symptoms attached. When describing the failure, please be as specific as possible about the nature of the problem. Include copies of additional failure information (such as the instrument failure settings, data related to instrument failure, and error messages) along with the instrument being returned.

Preparing the instrument for shipping

- 1 Write a complete description of the failure and attach it to the instrument. Include any specific performance details related to the problem. The following information should be returned with the instrument.
 - Type of service required.
 - Date instrument was returned for repair.
 - Description of the problem:
 - Whether problem is constant or intermittent.
 - Whether instrument is temperature-sensitive.
 - Whether instrument is vibration-sensitive.
 - Instrument settings required to reproduce the problem.
 - Performance data.
 - Company name and return address.
 - Name and phone number of technical contact person.
 - Model number of returned instrument.
 - Full serial number of returned instrument.
 - List of any accessories returned with instrument.
- 2 Cover all front or rear-panel connectors that were originally covered when you first received the instrument.

CAUTION

Cover electrical connectors to protect sensitive components from electrostatic damage. Cover optical connectors to protect them from damage due to physical contact or dust.

CAUTION

Instrument damage can result from using packaging materials other than the original materials. Never use styrene pellets as packaging material. They do not adequately cushion the instrument or prevent it from shifting in the carton. They may also cause instrument damage by generating static electricity.

- 3 Pack the instrument in the original shipping containers. Original materials are available through any Agilent Technologies office. Or, use the following guidelines:
 - Wrap the instrument in antistatic plastic to reduce the possibility of damage caused by electrostatic discharge.
 - For instruments weighing less than 54 kg (120 lb.), use a double-walled, corrugated cardboard carton of 159 kg (350 lb.) test strength.
 - The carton must be large enough to allow approximately 7 cm (3 inches) on

Returning the System for Service

all sides of the instrument for packing material, and strong enough to accommodate the weight of the instrument.

- Surround the equipment with approximately 7 cm (3 inches) of packing material, to protect the instrument and prevent it from moving in the carton. If packing foam is not available, the best alternative is S.D-240 Air Cap™ from Sealed Air Corporation (Commerce, California 90001). Air Cap looks like a plastic sheet filled with air bubbles. Use the pink (antistatic) Air Cap™ to reduce static electricity. Wrapping the instrument several times in this material will protect the instrument and prevent it from moving in the carton.
- 4 Seal the carton with strong nylon adhesive tape.
 - 5 Mark the carton “FRAGILE, HANDLE WITH CARE”.
 - 6 Retain copies of all shipping papers.

Agilent Technologies Service Offices

Before returning an instrument for service, call the Agilent Technologies Instrument Support Center at (800) 403-0801, visit the Test and Measurement Web Sites by Country page at <http://www.tm.agilent.com/tmo/country/English/index.html>, or call one of the numbers listed below.

Agilent Technologies Service Numbers

Austria	01/25125-7171
Belgium	32-2-778.37.71
Brazil	(11) 7297-8600
China	86 10 6261 3819
Denmark	45 99 12 88
Finland	358-10-855-2360
France	01.69.82.66.66
Germany	0180/524-6330
India	080-34 35788
Italy	+39 02 9212 2701
Ireland	01 615 8222
Japan	(81)-426-56-7832
Korea	82/2-3770-0419
Mexico	(5) 258-4826
Netherlands	020-547 6463
Norway	22 73 57 59
Russia	+7-095-797-3930
Spain	(34/91) 631 1213
Sweden	08-5064 8700
Switzerland	(01) 735 7200
United Kingdom	01 344 366666
United States and Canada	(800) 403-0801

After Repair

When you first received the 86030A LCA 50 GHz system, you also received a system calibration software disk as part of the shipment. The system software disk contains information that is unique to each 86032A test set. The 86030A system comes from the factory with this information loaded onto the system software disk. You will need to reinstall the system software disk for the following cases:

- If the 86032A test set has been returned to the factory for repair
- If the 86032A test set has been returned to the factory for calibration
- If the system controller (that is, personal computer) has been returned to the factory for repair

To perform the verification test, you will also need to reinstall the verification device data from the floppy disk that is included in the N1012A Verification Kit.

To install the system calibration files

- 1 Insert the 86032A test set calibration coefficients files disk into the floppy drive of the 86030A system computer.
- 2 From the Windows Desktop, double-click My Computer.
- 3 Double-click on the A: drive and then setup.bat.

Once the setup.bat file has been executed, the 86030A system is now ready for use.

To install the verification device data files

- 1 Insert the N1012A disk into the floppy drive of the 86030A system computer.
- 2 From the Windows Desktop, double-click My Computer.
- 3 Double-click on the A: drive and then setup.bat.

General Specifications 8-3
Electrical Specifications 8-4
Optical to Optical (O/O) Specifications 8-6
Optical to Electrical (O/E) Specifications 8-7
Electrical to Optical (E/O) Specifications 8-12
Characteristics 8-16
Optical to Electrical (O/E) Characteristics 8-18
Electrical to Optical (E/O) Characteristics 8-21
Regulatory Information 8-24
Declaration of Conformity 8-25

Specifications and Regulatory Information

Specifications and Regulatory Information

This chapter lists specifications and characteristics of the 86030A. Specifications apply over the temperature range +20°C to +30°C after the system's temperature has been stabilized after two hours of continuous operation. The specifications are valid only for a temperature drift of less than $\pm 3^\circ\text{C}$ from the user calibration temperature. A user calibration *must* be performed at least once every 8 hours.

- Specifications** *Specifications* described warranted performance.
- Characteristics** *Characteristics* provide useful, non warranted, information about the functions and performance of the system.
- Calibration cycle** Agilent Technologies warrants instrument specifications over the recommended calibration interval. To maintain specifications, periodic recalibrations are necessary. We recommend that the 86030A be calibrated at an Agilent Technologies service facility every 12 months.

General Specifications

Table 8-1. General System Specifications

Measurement	Specification
Specified Temperature Range	20 °C to 30 °C
Operating Temperature Range	5 °C to 40 °C
Storage Temperature	-40 °C to +75 °C
Power Dissipation	1940 VA maximum
Supply Requirements	
Nominal Frequency Range	47.5 to 66 Hz
Nominal Voltage	100, 120, 220, 240 Vac, ±10%
Fuse Type and Rating for 86032A test set	6.3A, 250V
System Weight	250 kg/592 lbs.
System Rack Size	
Height	1.6 meters
Width	600 mm
Depth	900 mm

Electrical Specifications

The electrical to electrical specifications are the same as for the 85107B with the following exceptions.

- The user does not have control of the RF power applied to the 8517B test set.
- In the Step mode, when the first point in the trace is in the 45 to 150 MHz range, the accuracy of the first point is significantly degraded.

In the Ramp mode, accuracy of all measurements in the 45 MHz to 150 MHz range will be degraded.

The full performance of the 85107B can be obtained by reconnecting the 50 GHz source directly to the 8517B test set (bypassing the 86032A) using the cable supplied with the 8510C accessories.

Refer to the 85107B System manual for a complete listing of the specifications.

Table 8-2. General Optical/Electrical Specifications

Measurement	Specification	Conditions
Modulation Frequency Range	0.150 - 50 GHz	
Optical Source Center Wavelength	1550 -1560 nm	DFB laser falls within these wavelength limits.
Optical Output Return Loss	> 30 dB	With factory new straight connectors. Improper connector care will degrade this specification.
Optical Input Return Loss	> 25 dB	With factory new straight connectors. Improper connector care will degrade this specification.

Table 8-2. General Optical/Electrical Specifications (Continued)

Measurement	Specification	Conditions
Average Optical Output Power: Modulator at minimum loss	> 3 dBm	Modulator set at minimum insertion loss.
Modulator at quadrature	> 0 dBm	Modulator set at quadrature. Quadrature is the average of the minimum and maximum transmission state of the modulator.
Available power at Laser output port	> 8 dBm	This port has a polarization maintaining fiber (PM F) connected.
Nominal RF modulation power setting for E/O mode	0 dBm	This is the default power that the system will use. This setting will assure that a 85107B receiver overload will not occur during the calibration process. Advanced users may increase the power level however, you will have to manually verify that receiver overload has not occurred.
Maximum available RF Modulation Power for E/O Mode	> 5 dBm	This is the power measured at the RF Output port of the 86032A test set. This value can be set manually from the 86030A program. From the Options menu, click Advanced, Customize, SRC Power E to O dBv and enter a new value. Note that you will need an electrical power meter to set this value as the 86030A software value is a relative number.
Maximum Operating Optical Input Power (to optical receiver input)	Do not exceed 4 mW (6 dBm)	Exceeding this value will cause measurement inaccuracies.
Maximum Optical Input Power to Optical Receiver (without damage)	Do not exceed 15 mW (11.8 dBm)	Power above this level can potentially damage the photodetector of the optical receiver.

Optical to Optical (O/O) Specifications

Specification conditions:

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- Greater than 20 dBc signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-3. Optical to Optical Noise Floor

Frequency Range (GHz)	Noise Floor (dBo) ^a
0.045 - 0.15	< - 18 (Characteristic)
0.15 - 0.2	< - 24
0.2 - 0.3	< - 27
0.3 - 0.5	< - 30
0.5 - 10	< - 33
10 - 20	< - 30
20 - 30	< - 27
30 - 40	< - 22
40 - 50	< - 18

^a dB down from the 0 dBo loss reference $10\log\left(\frac{\text{power}}{\text{optical thru-line power}}\right)$.

Optical to Electrical (O/E) Specifications

Relative Frequency Response

Relative frequency response refers to the amount of error that accumulates when you compare the response of two or more frequency points. This would often be used in calculating the – 3 dB roll-off point of an optical modulator. A large error term for this measurement is dependent on the amount of electrical port reflectivity on the O/E device under test. Thus, relative frequency response is specified as a function of electrical port reflectivity. The electrical reflectivity of any O/E device can be measured using the E/E mode on the 86030A. The following relative frequency response tables are given for several values of O/E device under test electrical port reflectivity. If you do not know the electrical reflectivity, then you must use [Table 8-6, “O/E Relative Frequency Response for the Electrical Port Reflection Coefficient < 1.0,” on page 8-9](#) as a conservative estimate. The electrical reflectivity of any O/E device can be measured using the E/E mode of the 86030A.

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- Greater than 20 dBe signal to noise ratio required for these specifications to be valid.

Specifications are valid only for Step mode operation.

Table 8-4. O/E Relative Frequency Response for the Electrical Port Reflection Coefficient < 0.25

Frequency Range (GHz)	Relative Frequency Response (dBe)	Relative Frequency Response (dBe) ^a
0.045 - 0.15	± 3.8 (Characteristic)	± 3.8 (Characteristic)
0.15 - 2	± 0.8	± 0.7
2 - 20	± 1.0	± 0.7
20 - 40	± 1.3	± 0.9
40 - 50	± 1.8	± 1.2

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. [Refer to “O/E measurement with 6 dB attenuator” on page 3-36.](#)

Table 8-5. O/E Relative Frequency Response for the Electrical Port Reflection Coefficient < 0.5

Frequency Range (GHz)	Relative Frequency Response (dBe)	Relative Frequency Response (dBe) ^a
0.045 - 0.15	± 3.8 (Characteristic)	± 3.8 (Characteristic)
0.15 - 2	± 0.9	± 0.7
2 - 20	± 1.4	± 0.8
20 - 40	± 1.7	± 1.0
40 - 50	± 2.3	± 1.3

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. [Refer to “O/E measurement with 6 dB attenuator” on page 3-36.](#)

Table 8-6. O/E Relative Frequency Response for the Electrical Port Reflection Coefficient < 1.0

Frequency Range (GHz)	Relative Frequency Response (dBe)	Relative Frequency Response (dBe) ^a
0.045 - 0.15	± 3.8 (Characteristic)	± 3.8 (Characteristic)
0.15 - 2	± 1.2	± 0.8
2 - 20	± 2.0	± 1.0
20 - 40	± 2.4	± 1.2
40 - 50	± 3.2	± 1.6

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. [Refer to "O/E measurement with 6 dB attenuator" on page 3-36.](#)

Relative Frequency Response with Response and Match User Calibration

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Any electrical port reflection coefficient
- Greater than 20 dB signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-7. O/E Relative Frequency Response for the Electrical Port Reflection Coefficient < 1.0 with Response and Match User Calibration

Frequency Range (GHz)	Relative Frequency Response (dBe)
0.045 - 0.15	±3.8 (Characteristic)
0.15 - 10	± 0.7
0.1 - 20	± 0.7
0.1 - 30	± 0.9
0.1 - 40	± 1.2

O/E Absolute Noise Floor

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- The internal O/E converter is disconnected from the 8517B input after the user calibration process so that it is not contributing to the noise floor rise. O/E converters with very large responsivities will cause a noise floor rise. This noise floor specification is valid only for O/E converters with responsivities less than 2.0 amps/watt.
- Specifications are valid only for Step mode operation.

Table 8-8. O/E Absolute Noise Floor

Frequency Range (GHz)	Noise Floor (dBe)^a
0.045 - 0.15	- 40 (Characteristic)
0.15 - 0.2	- 50
0.2 - 0.3	- 60
0.3 - 0.5	- 62
0.5 - 10	- 70
10 - 20	- 62
20 - 30	- 56
30 - 40	- 47
40 - 50	- 42

$$^a\text{dBe down from 1amp/watt} = 20\log\left(\frac{\text{DUT responsivity}}{1 \text{ amp/watt}}\right)$$

Electrical to Optical (E/O) Specifications

Relative frequency response refers to the amount of error that accumulates when you compare the response of two or more frequency points. This would often be used in calculating the – 3 dB roll-off point of an optical modulator. A large error term for this measurement is dependent on the amount of electrical port reflectivity on the E/O device under test. Thus, relative frequency response is specified as a function of electrical port reflectivity. The electrical reflectivity of any E/O device can be measured using the E/E mode on the 86030A. The following relative frequency response tables are given for several values of E/O device under test electrical port reflectivity. If you do not know the electrical reflectivity, then you must use [Table 8-11, “E/O Relative Frequency Response for the Electrical Port Reflection Coefficient < 1.0,” on page 8-14](#) as a conservative estimate. The electrical reflectivity of any E/O device can be measured using the E/E mode of the 86030A.

Specification Characteristics

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- 50 ohm termination on unused 8517B port
- Greater than 20 dB signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-9. E/O Relative Frequency Response for the Electrical Port Reflection Coefficient < 0.25

Frequency Range (GHz)	Relative Frequency Response (dBe)
0.045 - 0.15	±2.2 (Characteristic)
0.15 - 2	± 0.6
2 - 20	± 0.9
20 - 40	± 1.0
40 - 50	± 1.4

Table 8-10. E/O Relative Frequency Response for the Electrical Port Reflection Coefficient < 0.5

Frequency Range (GHz)	Relative Frequency Response (dBe)
0.045 - 0.15	±2.3 (Characteristic)
0.15 - 2	± 0.8
2 - 20	± 1.3
20 - 40	± 1.5
40 - 50	± 2.1

Specifications and Regulatory Information
Electrical to Optical (E/O) Specifications

Table 8-11. E/O Relative Frequency Response for the Electrical Port Reflection Coefficient < 1.0

Frequency Range (GHz)	Relative Frequency Response (dBe)
0.045 - 0.15	±2.8 (Characteristic)
0.15 - 2	± 1.3
2 - 20	± 2.1
20 - 40	± 2.5
40 - 50	± 3.4

E/O Absolute Noise Floor

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- Specifications are valid only for Step mode operation.

Table 8-12. Absolute Noise Floor

Frequency Range (GHz)	Noise Floor (dBe) ^a
0.045 - 0.15	- 50 (Characteristic)
0.15 - 0.2	- 55
0.2 - 0.3	- 57
0.3 - 0.5	- 60
0.5 - 10	- 61
10 - 20	- 58
20 - 30	- 55
30 - 40	- 53
40 - 50	- 50

^adBe down from 1 watt/amp = $20\log\left(\frac{DUT\ responsibility}{1\ watt\ amp}\right)$

Characteristics

Characteristics

Characteristics provide useful, non warranted, information about the functions and performance of the system.

Maximum Input Power into the 8510 Electrical Port

The following two tables indicate the maximum power the 8510 test port can tolerate before the system begins to overload and cause inaccurate measurements. For any reason, if an IF overload message appears on the 8510 display the input power must be reduced before continuing. Note that once an error message appears on the display, it does not go away until it is manually cleared using the 8510C Entry Off function. To check for an RF overload condition, refer to [“O/E RF Overload Detection Measurement”](#) on page 3-51.

Table 8-13. Maximum Input Power into the 8517B Test Ports

Frequency Range (GHz)	Maximum Power (dBm)
0.045 - 2.0	+ 18
2.0 - 20	+ 8
20 - 40	+ 4
40 - 50	- 3

Typical Performance

Table 8-14. Optical Modulation Power from the 86032A Source Output^a

Frequency Range (GHz)	Maximum Power (dBm)
0.045 - 0.84	0
0.84 - 20	- 3
20 - 40	- 5
40 - 50	- 10

^aTypical Performance (this is not a specification)

Optical to Electrical (O/E) Characteristics

O/E Absolute Frequency Response

The relative frequency response specifications gave information that is helpful in determining parameters such as the -3 dB roll off point of a device under test, however, it did not address the issue of how accurate each frequency point was in terms of absolute response. The absolute frequency response accuracy addresses the absolute error that is present in a responsivity measurement at any particular modulation frequency.

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- Greater than 20 dB signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-15. O/E Absolute Frequency Response Accuracy for the Electrical Port Reflection Coefficient < 0.25

Frequency Range (GHz)	Absolute Frequency Response (dBe)	Absolute Frequency Response (dBe) ^a
0.045 - 0.15	±3.8	±3.8
0.15 - 2	± 1.3	± 1.2
2 - 20	± 1.5	± 1.2
20 - 40	± 1.8	± 1.4
40 - 50	± 2.3	± 1.7

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. Refer to "O/E measurement with 6 dB attenuator" on page 3-36.

**Table 8-16. O/E Absolute Frequency Response Accuracy for the Electrical Port
 Reflection Coefficient < 0.5**

Frequency Range (GHz)	Absolute Frequency Response (dBe)	Absolute Frequency Response (dBe) ^a
0.045 - 0.15	±3.8	±3.8
0.15 - 2	± 1.4	± 1.2
2 - 20	± 1.9	± 1.3
20 - 40	± 2.2	± 1.5
40 - 50	± 2.8	± 1.8

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. [Refer to “O/E measurement with 6 dB attenuator” on page 3-36.](#)

**Table 8-17. O/E Absolute Frequency Response Accuracy for the Electrical Port
 Reflection Coefficient < 1.0**

Frequency Range (GHz)	Absolute Frequency Response (dBe)	Absolute Frequency Response (dBe) ^a
0.045 - 0.15	±3.8	±3.8
0.15 - 2	± 1.7	± 1.3
2 - 20	± 2.5	± 1.5
20 - 40	± 2.9	± 1.7
40 - 50	± 3.7	± 2.1

^a With a 6 dB attenuator connected to the electrical receiving port of the 8517B test set. [Refer to “O/E measurement with 6 dB attenuator” on page 3-36.](#)

Absolute Relative Frequency Response with Response and Match User Calibration

Specification Conditions

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Any electrical port reflection coefficient
- Greater than 20 dBe signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-18. O/E Absolute Frequency Response Accuracy for the Electrical Port Reflection Coefficient < 1.0 with Response and Match User Calibration

Frequency Range (GHz)	Absolute Frequency Response (dBe)
0.045 - 0.15	±3.8
0.15 - 10	± 1.2
0.1 - 20	± 1.2
0.1 - 30	± 1.4
0.1 - 40	± 1.7

Electrical to Optical (E/O) Characteristics

E/O Absolute Frequency Response

The relative frequency response specifications gave information that is helpful in determining parameters such as the -3 dB roll off point of a device under test, however, it did not address the issue of how accurate each frequency point was in terms of absolute response. The absolute frequency response accuracy addresses the absolute error that is present in a responsivity measurement at any particular modulation frequency.

Specification Characteristics

- Factory default laser power settings
- Factory default modulation power settings
- Setting of 512 averages on the 85107B
- Response and isolation calibration
- 50 ohm termination on unused 8517B port
- Greater than 20 dB signal to noise ratio required for these specifications to be valid.
- Specifications are valid only for Step mode operation.

Table 8-19. E/O Absolute Frequency Response for the Electrical Port Reflection Coefficient < 0.25

Frequency Range (GHz)	Absolute Frequency Response (dBe)
0.045 - 0.15	± 2.6
0.15 - 2	± 1.1
2 - 20	± 1.4
20 - 40	± 1.5
40 - 50	± 1.9

Specifications and Regulatory Information
Electrical to Optical (E/O) Characteristics

Table 8-20. E/O Absolute Frequency Response for the Electrical Port Reflection Coefficient < 0.5

Frequency Range (GHz)	Absolute Frequency Response (dBe)
0.045 - 0.15	±2.8
0.15 - 2	± 1.3
2 - 20	± 1.8
20 - 40	± 2.0
40 - 50	± 2.6

Table 8-21. E/O Absolute Frequency Response for the Electrical Port Reflection Coefficient < 1.0

Frequency Range (GHz)	Absolute Frequency Response (dBe)
0.045 - 0.15	±3.3
0.15 - 2	± 1.8
2 - 20	± 2.6
20 - 40	± 3.0
40 - 50	± 3.9

Test Set Monitoring Power Accuracy

The following characteristics relate to the accuracy of the test set monitoring capabilities. The test set monitoring functions are found under the Tools menu. Open the Modify Test Set dialog box to view the Current Laser Output Power, and Monitor Test Set dialog box to view the Optical Output Power and Optical Receiver Input Power.

Table 8-22. Test Set Monitoring Power Accuracy

Test Set Power Settings	Characteristics	Power Range
Current Laser Output Power	± 0.5 dB	0 dBm to 10 dBm
Optical Output Power	± 0.5 dB	- 10 dBm to 5 dBm
Optical Receiver Input Power	± 0.5 dB	- 10 dBm to 5 dBm


Regulatory Information

- This product is classified as Class I according to 21 CFR 1040.10 and Class I according to IEC 60825-1.
- This product complies with 21 CFR 1040.10 and 21 CFR 1040.11.
- This is to declare that this system is in conformance with the German Regulation on Noise Declaration for Machines (Laermangabe nach der Maschinenlaermverordnung -3.GSGV Deutschland).

Notice for Germany: Noise Declaration

Acoustic Noise Emission	Geraeuschemission
LpA < 70 dB	LpA < 70 dB
Operator position	am Arbeitsplatz
Normal position	normaler Betrieb
per ISO 7779	nach DIN 45635 t.19

Declaration of Conformity

DECLARATION OF CONFORMITY	
According to ISO/IEC Guide 22 and CEN/CENELEC EN 45014	
Manufacturer's Name:	Agilent Technologies, Inc.
Manufacturer's Address:	1400 Fountaingrove Parkway Santa Rosa, CA 95403-1799 USA
Declares that the product:	
Product Name:	Lightwave Component Analyzer System
Model Number:	86030A
Product Options:	This declaration covers all options of the above product.
Is in conformity with:	
Safety:	IEC 61010-1:1990 +A1:1992+A2:1995 / EN 61010-1:1994+A2:1995 CAN/CSA-C22.2 No. 1010.1-92 IEC 60825-1:1998 21CFR 1040.10 & 1040.11
EMC:	CISPR 11:1990/EN 55011:1991 Group 1, Class A IEC 61000-4-2:1995+A1:1998 / EN 61000-4-2:1995, 4 kV CD, 8 kV AD IEC 61000-4-3:1995 / EN 61000-4-3:1995, 3 V/m, 80-1000 MHz IEC 61000-4-4:1995 / EN 61000-4-4:1995, 0.5 kV sig. lines, 1 kV pow. lines IEC 61000-4-5:1995 / EN 61000-4-5:1995, 0.5 kV I-I, 1 kV I-e IEC 61000-4-6:1996 / EN 61000-4-6:1996, 3V 80% AM, power line IEC 61000-4-11:1994 / EN 61000-4-11:1994, 100 %, 20 ms
Supplementary Information:	
The product herewith complies with the requirements of the Low Voltage Directive 73/23/EEC and the EMC Directive 89/336/EEC and carries the CE-marking accordingly.	
	
Santa Rosa, CA, USA	25 Apr. 2000
Greg Pfeiffer/Quality Engineering Manager	
For further information, please contact your local Agilent Technologies sales office, agent or	

Index

Numerics

- 8510
 - address, 2-23
 - repair and service, 7-22
 - specifications, 8-2
 - split screen mode, 2-23
 - time date stamp, 2-23
 - 86030A
 - accessing, 1-11
 - cable configurations, 1-9
 - characteristics, 8-16
 - E/O specifications, 8-12
 - example measurements, 3-28
 - O/E specifications, 8-7
 - O/O specifications, 8-6
 - overview, 2-2
 - software, 2-12
 - specifications, 8-2
 - support and maintenance, 7-17
 - system overview, 2-2
 - temperature range, 8-2, 8-3
 - 86032A
 - block diagram, 5-3
 - diagnostic software, 7-7
 - modulator troubleshooting, 7-11
 - operation, 5-3
 - repair and service, 7-22
 - specifications, 8-2
 - system software, 7-26
 - theory of operation, 5-3
 - troubleshooting, 7-7
 - verification, 6-3
- ## A
- accessing the 86030A software, 1-11
 - accessories
 - cleaning tools, 2-40
 - system, 2-5
 - accurate measurements, 2-33
 - Advanced Settings, Options menu, 2-25
 - Agilent offices, 7-25
 - Agilent Technologies
 - Instrument Support Center, 7-22
 - sales and service, 7-25
 - support and maintenance, 7-17
 - web site, 7-25

- amplitude scaling calculations
 - E/O, 5-17
 - O/E, 5-16
 - O/O, 5-18
- assembling the monitor mount assembly, 1-6
- attaching
 - keyboard transmitter, installing, 1-8
 - keyboard tray, 1-6
 - monitor mount assembly, 1-6
- Auto Bias At Cal, 2-23

B

- bias interval, 2-23
- bias voltage, 2-20, 5-14
- block diagram, 86032A test set, 5-3

C

- cable configurations, 1-9
- calibration
 - E/O response and isolation, 3-23
 - E/O theory of, 5-11
 - electrical, 3-3
 - match, 3-39
 - New DUT, 3-22
 - O/E, 3-11
 - O/E match, 3-14
 - O/E response, 3-14
 - O/E, theory of operation, 5-9
 - O/O response and isolation, 3-8
 - optical (O/E), 3-3
 - optical (O/O), 3-3
 - procedures, 3-3
 - recommended cycle time, 8-2
 - response, 3-39
 - theory of, 5-6
- care of fiber optics, 2-7
- characteristics, 8-16
- checking laser conditions, 7-10
- cleaning
 - fiber-optic connections, 2-33, 2-41
 - non-lensed connectors, 2-41
- compressed dust remover, 2-41
- configuration options, 2-6
- configuring the system cables, 1-9
- connections
 - care manual, 2-42

Index

- care of, 2-33
- cleaning, 2-40
 - cleaning accessories, 2-40
 - electrical, 2-42
 - inspecting, 2-36
 - isopropyl alcohol, 2-40
- contacting Agilent, 7-22
- cotton swabs, 2-41
- Customize, Options menu, 2-23

D

- Declaration of Conformity, 8-25
- delay measurement, 3-47
- determining electrical length, 3-47
- deviation from linear phase of a lightwave receiver, 3-41
- diagnostic software, 7-7
- display scaling calculations, 5-16
- dust caps, 2-41

E

- E/O
 - display scaling calculations, 5-17
 - measurement calibration, 5-11
 - response and isolation calibration, 3-23
 - specifications, 8-12
- electrical
 - calibrations, 3-3
 - connector care, 2-42
 - delay values, determining, 3-47
 - measurement calibration, 5-14
 - mismatch, 3-39
 - mismatch ripple, 3-30
 - mismatch, correcting for, 3-14
 - reflectivity, 3-14
 - specifications, 8-4
- ESD
 - reducing damage caused by ESD, 2-46, 7-21
 - static-safe work station, 2-46, 7-21
- Excel
 - graphing, 2-15
 - saving data, 2-13
- external leveling, 2-26

F

- FDA laser safety, 2-30
- features
 - rear panel, 2-11
 - system, 2-2
- fiber optics
 - care of, 2-7
 - cleaning connections, 2-33
 - connectors, covering, 7-23
- File menu, 2-13
 - Graph Excel Data, 2-15
 - Save Excel Data, 2-13
 - Save text data, 2-13
- find us on the web, 7-25
- foam swabs, 2-41
- formatted data, viewing, 2-15
- front panel connections, 1-9
- fuse size and rating, 86032A, 8-3

G

- general specifications, 8-3
- GPIO
 - address of 8510C, 2-23
 - addresses of instruments, 7-6
 - interface, 7-6
- Graph Excel Data, 2-15

I

- IEC Publication 1010, i-iv
- input connector, 2-33
- inspecting connectors, 2-36
- installing
 - keyboard transmitter, 1-8
 - monitor mount assembly, 1-6
 - mouse transmitter, 1-8
 - system software, 7-26
- instrument GPIO addresses, 7-6
- internet web site, 7-25
- isopropyl alcohol, 2-41

K

- keyboard tray attachment, 1-6

L

- laser
 - classifications, 2-30
 - conditions, 7-10
 - key location, 2-9
 - remote shutdown, 2-11
 - safety, 2-30
 - warning, 2-31
- LCD monitor, attaching, 1-6
- lightwave test set
 - fuse, 8-3
 - modulator troubleshooting, 7-11, 7-16
 - operation, 5-3
 - verification, 6-3
 - verifying laser conditions, 7-10
- line fuse, 1-5

M

- magnitude response of a lightwave receiver, 3-41
- mains supply, 1-5
- match calibration, 3-39
- match calibration, new DUT, 3-22
- measurements
 - delay, 3-47
 - deviation from linear phase of a lightwave receiver, 3-41
 - electrical mismatch ripple, 3-29
 - magnitude response of a lightwave receiver, 3-41
 - O/E bandwidth, 2-47
 - overload detection, 3-51
 - photodetector, 2-47
- modulated optical power, 2-20
- modulator
 - bias interval, 2-23
 - bias setting, 2-28
 - bias voltage, 2-20, 2-28, 5-14
 - conditions, verification, 7-11
 - power curve, 5-14, 7-12
 - troubleshooting tips, 7-16
- monitor mount assembly, 1-6
- Monitor Test Set, Tools menu, 2-29
- mouse transmitter, installing, 1-8

N

- noise declaration, 8-24

O

- O/E
 - display scaling calculations, 5-16
 - match calibration, 3-14
 - measurement calibration, 5-9
 - response and isolation calibration, 3-11
 - response calibration, 3-14
 - RF overload detection, 3-48
 - specifications, 8-7
- O/O
 - display scaling calculations, 5-18
 - measurement calibration, theory of operation, 5-7
 - response and isolation bandwidth calibration, 3-8
 - specifications, 8-6
- operating temperature range, 8-2
- operation of 86032A test set, 5-3
- optical
 - calibrations, 3-3
 - connector care, 2-36
 - output power setting, 2-28
 - specifications, 8-6
 - theory of operation, 5-9
- Option menu, 2-20
 - Advanced Settings, 2-20
 - Auto Bias, 2-20
 - Auto-Bias at Cal, 2-20
 - Standard Settings, 2-20
 - System Verification, 2-20
- options, 86030A system, 2-6
- overload detection, O/E, 3-48
- overview
 - 86030A system, 2-2
 - server API, 4-24
 - software, 2-12

P

- packaging for shipment, 7-23
- phone numbers for Agilent Technologies, 7-25
- photodetector measurement, 2-47
- power curve of the modulator, 7-12
- powering up the system, 1-11

Index

- preparing the instrument for shipping, 7-23
- preparing the site for installation, 1-4
- product support, 7-17

Q

- quadrature
 - modulator bias, 2-28
 - power, 2-20
 - voltage, 2-20
- quick start measurement, 2-47

R

- ramp sweep, 2-23
- raw data, 2-15
- rear panel
 - connections, 1-9
 - features, 2-11
- recommended calibration cycle, 8-2
- reducing
 - electrical mismatch, 3-14, 3-39
 - mismatch ripple, 3-29
- regulatory information, 8-2, 8-24
- reinstalling system software, 7-26
- remote programing connector, 2-11
- repair of your system, 7-17
- return loss, 2-39
- returning for service, 7-22
- returning the system for service, 7-22

S

- sales and service offices, 7-25
- sales and service phone numbers, 7-25
- Save Data, File menu, 2-13
- saving
 - delay data, 2-13
 - Excel files, 2-13
 - formatted data, 2-13
 - log magnitude data, 2-13
 - phase data, 2-13
 - raw data, 2-13
- sending instrument to Agilent, 7-23
- server API, overview, 4-24
- service, 7-22
 - 8510, 7-22
 - returning for, 7-22

- sales and service offices, 7-25
- system, 7-17, 7-22
- setting
 - Advanced Settings dialog box, 2-25
 - bias interval, 2-23
 - external leveling, 2-26
 - modulator bias voltage, 2-28
 - optical output power, 2-28
 - Src power, 2-25
 - Standard dialog box, 2-23
- shipping preparation, 7-23
- site preparation for installation, 1-4
- software overview, 2-12
- specifications, 8-2
 - E/O, 8-12
 - electrical, 8-4
 - O/E, 8-7
 - O/O, 8-6
- Standard, 2-23
 - Average Factor, 2-23
 - Bias Interval, 2-23
 - GPIB address, 2-23
- starting the software, 1-11
- step sweep, 2-23
- support
 - and maintenance of the system, 7-17
 - on-site system repair, 7-17
 - phone numbers, 7-25
- swabs, 2-41
- sweep step, 2-23
- sweep type, 2-23
- System, 2-26
- system
 - accessing the software, 1-11
 - calibration theory of operation, 5-6
 - characteristics, 8-16
 - components, 2-5
 - configuration, 2-6
 - configurations, 1-9
 - dimensions, 1-4
 - E/O specifications, 8-12
 - GPIB addresses, 7-6
 - O/E specifications, 8-7
 - O/O specifications, 8-6
 - operation, 5-2
 - overview, 2-2
 - power consumption, 1-4
 - problems, 7-22

- repair, 7-17
- size, 8-3
- software disk, 7-26
- specifications, 8-6
- support and maintenance, 7-17
- temperature range, 8-2, 8-3
- verification, 6-3
- weight, 1-4, 8-3

T

- temperature range of operation, 8-3
- test set
 - modifications, 2-27
 - modulator troubleshooting, 7-11
 - operation, 5-3
 - troubleshooting, 7-7
- testing the system, 6-3
- theory of
 - electrical calibration, 5-14
 - electrical to optical calibration, 5-11
 - measurement calibration, 5-6
 - system operation, 5-2
- time date stamp, 2-23
- Tools menu
 - defined, 2-27
 - Modify Test Set, 2-27
 - Monitor Test Set, 2-27
- troubleshooting
 - software, 86032A, 7-7
 - the 86032A test set, 7-7
 - the modulator, 7-16
- turning on the system, 1-11

U

- URL for Agilent Technologies, 7-25

V

- verification kit, 2-5
- verification process, 6-3
- verifying, operation of the 86032A, 7-7
- viewing
 - delay data, 2-15
 - formatted data, 2-15
 - log magnitude, 2-15
 - modulator bias voltage, 2-28

- phase data, 2-15
- voltage selector, 1-5

W

- Web sites, 7-25
- weight of system, 8-3

