Agilent 81632A/3A/4A Power Sensor Module and Agilent 81635A Dual Power Sensor Module

User's Guide



Second Edition

This document contains proprietary information that is protected by copyright. All rights are reserved.

No part of this document may be photocopied, reproduced, or translated to another language without the prior written consent of Agilent Technologies Deutschland GmbH.

© Copyright 2000 by: Agilent Technologies Deutschland GmbH Herrenberger Str. 130 71034 Böblingen Germany

Subject Matter

The information in this document is subject to change without notice.

Agilent Technologies makes no warranty of any kind with regard to this printed material, including, but not limited to, the implied warranties of merchantability and fitness for a particular

Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Printing History

New editions are complete revisions of the guide reflecting alterations in the functionality of the instrument. Updates are occasionally made to the guide between editions. The date on the title page changes when an updated guide is published. To find out the current revision of the guide, or to purchase an updated guide, contact your Agilent Technologies representative.

Control Serial Number: First Edition applies directly to all instruments.

Warranty

This Agilent Technologies instrument product is warranted against defects in material and workmanship for a period of one year from date of shipment. During the warranty period, Agilent will, at its option, either repair or replace products that prove to be defective.

For warranty service or repair, this product must be returned to a service facility designated by Agilent. Buyer shall prepay shipping charges to Agilent and Agilent shall pay shipping charges to return the product to Buyer. However, Buyer shall pay all shipping charges, duties, and taxes for products returned to Agilent from another country.

Agilent warrants that its software and firmware designated by Agilent for use with an instrument will execute its programming instructions when properly installed on that instrument. Agilent does not warrant that the operation of the instrument, software, or firmware will be uninterrupted or error free.

Limitation of Warranty

The foregoing warranty shall not apply to defects resulting from improper or inadequate maintenance by Buyer, Buyer-supplied software or interfacing, unauthorized modification or misuse, operation outside of the environmental specifications for the product, or improper site preparation or maintenance

No other warranty is expressed or implied. Agilent Technologies specifically disclaims the implied warranties of Merchantability and Fitness for a Particular Purpose.

Exclusive Remedies

The remedies provided herein are Buyer's sole and exclusive remedies. Agilent Technologies shall not be liable for any direct, indirect, special, incidental, or consequential damages whether based on contract, tort, or any other legal theory.

Assistance

Product maintenance agreements and other customer assistance agreements are available for Agilent Technologies products. For any assistance contact your nearest Agilent Technologies Sales

Certification

Agilent Technologies Company certifies that this product met its published specifications at the time of shipment from the factory.

Agilent Technologies further certifies that its calibration measurements are traceable to the United States National Institute of Standards and Technology, NIST (formerly the United States National Bureau of Standards, NBS) to the extent allowed by the Institutes's calibration facility, and to the calibration facilities of other International Standards Organization members

ISO 9001 Certification

Produced to ISO 9001 international quality system standard as part of our objective of continually increasing customer satisfaction through improved process control.

Second Edition: 81635-90014 E0100 First Edition:

E1299: December 1999 Second Edition: E0100: January 2000

and Service Office.

Safety Considerations

The following general safety precautions must be observed during all phases of operation, service, and repair of this instrument. Failure to comply with these precautions or with specific warnings elsewhere in this manual violates safety standards of design, manufacture, and intended use of the instrument. Agilent Technologies Company assumes no liability for the customer's failure to comply with these requirements.

Before operation, review the instrument and manual, including the red safety page, for safety markings and instructions. You must follow these to ensure safe operation and to maintain the instrument in safe condition.

WARNING

The WARNING sign denotes a hazard. It calls attention to a procedure, practice or the like, which, if not correctly performed or adhered to, could result in injury or loss of life. Do not proceed beyond a WARNING sign until the indicated conditions are fully understood and met.

Safety Symbols



The apparatus will be marked with this symbol when it is necessary for the user to refer to the instruction manual in order to protect the apparatus against damage.

Initial Inspection

Inspect the shipping container for damage. If there is damage to the container or cushioning, keep them until you have checked the contents of the shipment for completeness and verified the instrument both mechanically and electrically.

The Performance Tests give procedures for checking the operation of the instrument. If the contents are incomplete, mechanical damage or defect is apparent, or if an instrument does not pass the operator's checks, notify the nearest Agilent Technologies Sales/Service Office.

WARNING

To avoid hazardous electrical shock, do not perform electrical tests when there are signs of shipping damage to any portion of the outer enclosure (covers, panels, etc.).

Line Power Requirements

The Agilent 81632A/3A/4A Power Sensor Module and Agilent 81635A Dual Power Sensor Module operate when installed in the Agilent 8163A Lightwave Multimeter, Agilent 8164A Lightwave Measurement System, and Agilent 8166A Lightwave Multichannel System.

Operating Environment

The safety information in the Agilent 8163A Lightwave Multimeter, Agilent 8164A Lightwave Measurement System, and Agilent 8166A Lightwave Multichannel System User's Guide summarizes the operating ranges for the Agilent 81632A/3A/4A Power Sensor Module and Agilent 81635A Dual Power Sensor Module. In order for these modules to meet specifications, the operating environment must be within the limits specified for the Agilent 8163A Lightwave Multimeter, Agilent 8164A Lightwave Measurement System, and Agilent 8166A Lightwave Multichannel System.

Storage and Shipment

This module can be stored or shipped at temperatures between -40°C and +70°C. Protect the module from temperature extremes that may cause condensation within it.

Contents

Safety Considerations	3		
Safety Symbols	3		
Initial Inspection	3		
Line Power Requirements	3		
Operating Environment	4		
Storage and Shipment	4		
Contents	7.300 TO 6000000	12 2004000 200 - 11 00 00 15 15 15	5
Accessories			ģ
Modules and Options	11		
Specifications			13
Definition of Terms	15		M9 E AND 11 179000
Averaging Time	15		
Linearity	15		
Linewidth	16		
Noise	16		
Power range	16		
Reference conditions	16		
Relative uncertainty (spectral ripple) due to interference	16		
Relative uncertainty due to polarization	17		
Return loss:	17		
Spectral width of optical source	17		
Total uncertainty	17		
Uncertainty at reference conditions	17		
Wavelength Range	17		
Power Sensor Specifications (Autorange Mode)	19		
Performance Tests			21
Equipment Required	23		
Test Record	24		
Test Failure	24		
Instrument Specification	24		
Performance Test	24		

Accuracy Test	25	
Test Setup	25	
Linearity Test	27	
Test Setup	27	
+10 dBm Range	28	
0 dBm Range	29	
-10 dBm Range	29	
Change Setup	30	
-20 dBm to -50 dBm Range	30	
Calculation	30	
Example: Measurement Results	30	
Calculations	31	
Noise Test	33	
Return Loss Test	33	
Relative Uncertainty due to Polarization (Optional Test)	34	
Relative Uncertainty due to Interference (Optional Test)	36	
Calculation Sheet for Linearity Measurement	54	
Classina Duran Jama		
Cleaning Procedure	4 MANUAL TO THE RESERVE OF THE RESER	55
The Cleaning Kit	57	
Isopropyl alcohol	57	
Cotton-swabs	57	
Soft-tissues	57	
Pipe-cleaner	58	
Compressed Air	58	
Other Cleaning Tools	58	
Microscope	58	
Ultrasonic bath	59	
Warm water and liquid soap	59	
Premoistened cleaning wipes	59	
Polymer film	59	
Infrared sensor card	59	
Lens Cleaning Paper	59	
Preserving Connectors	60	
Making Connections	60	
Dust Caps and Shutter Caps	60	
Immersion Oil and Other Index Matching Compounds	60	
Cleaning Instrument Housings	60	
Cleaning Procedures	61	
Cleaning Cable Connectors	61	
Preferred Procedure	61	
Procedure for Stubborn Dirt	61	
An Alternative Procedure	62	
Cleaning Connector Adapters	62	

Preferred Procedure	62
Procedure for Stubborn Dirt	62
Cleaning Connector Interfaces	62
Preferred Procedure	63
Procedure for Stubborn Dirt	63
Cleaning Bare Fiber Adapters	63
Preferred Procedure	63
Procedure for Stubborn Dirt	63
Cleaning Bare Fiber Ends	64
Cleaning Lenses	64
Preferred Procedure	64
Procedure for Stubborn Dirt	64
Cleaning Large Area Lenses and Mirrors	65
Preferred Procedure	65
Procedure for Stubborn Dirt	65
Alternative Procedure A	65
Alternative Procedure B	66
Cleaning Fixed Connector Interfaces	66
Cleaning Optical Glass Plates	66
Cleaning Physical Contact Interfaces	66
Preferred Procedure	67
Procedure for Stubborn Dirt	67
Cleaning Recessed Lens Interfaces	67
Preferred Procedure	67
Procedure for Stubborn Dirt	67
Cleaning Fragile Optical Devices	67
Preferred Procedure	68
Procedure for Stubborn Dirt	68
Alternative Procedure	68
Cleaning Metal Filters or Attenuator Gratings	68
Preferred Procedure	68
Procedure for Stubborn Dirt	68

Index

71

Accessories

The Agilent 81632A/3A/4A Power Sensor Module and the Agilent 81635A Dual Power Sensor Module are available in various configurations for the best possible match to the most common applications.

This chapter provides information on the available options and accessories.

Modules and Options




Figure 1 Recommended Connector Interfaces and Bare Fiber Adapters

Table 1 Connector Interfaces

Product Number	Connector InterfaceType				
81000AI	Diamond HMS-10				
81000FI	FC/PC/SPC				
81000GI	D4				
81000JI	SMA				
81000KI	SC/APC				

Table 1 Connector Interfaces

Product Number	Connector InterfaceType				
81000NI	FC/APC				
81000PI	E-2000				
81000SI	DIN 47526				
81000VI	ST				
81000WI	Biconic				

 Table 2
 Connector Interface and Bare Fiber Adapter Combinations

Product Number	Bare Fiber Adapter	Product Number	Connector Interface	
81000FB	Bare Fiber Adapter	81000FI	FC/PC/SPC	
81000KB	Bare Fiber Adapter	81000KI	SC/APC	
81000SB	Bare Fiber Adapter	81000SI	DIN 47526	
81000SB	Bare Fiber Adapter	81000VI	ST	

Specifications

Agilent 81632A/3A/4A Power Sensor Modules and the Agilent 81635A Dual Power Sensor Module are produced to the ISO 9001 international quality system standard as part of Agilent's commitment to continually increasing customer satisfaction through improved quality control.

Specifications describe the modules' and heads' warranted performance. Supplementary performance characteristics describe the modules' and heads' non-warranted typical performance.

Because of the modular nature of the instrument, these performance specifications apply to these modules and heads rather than the mainframe unit.

Definition of Terms

This section defines terms that are used both in this chapter and "Performance Tests" on page 21.

Generally, all specifications apply for the given environmental conditions and after warmup time.

Measurement principles are indicated. Alternative measurement principles of equal value are also acceptable.

Averaging Time

Time defining the period during which the power meter takes readings for averaging. At the end of the averaging time the average of the readings is available (display- or memory-update). Symbol T_{avg} .

Linearity

The linearity error is defined as the relative difference between the displayed power ratio, D_x/D_0 , and the actual (true) power ratio P_x/P_0 caused by changing the displayed power level from the reference level, D_0 , to an arbitrary displayed level, D_x . Symbol N.

if expressed in %

$$N = \left(\frac{D_x/D_0}{P_x/P_0} - 1\right)100$$

if expressed in dB

$$N_{dB} = 10\log\left(\frac{D_x/D_0}{P_x/P_0}\right)$$

Conditions: reference level 10 μ W, displayed power levels within the specified range, zero less than specified time prior to measurement.

Note 1: ideally E = 0 %, respectively 0 dB.

Note 2: the power-dependent nonlinearity, $N(P_x)$, can alternatively be expressed by the following formula:

$$N(P_x) = \frac{r(P_x) - r(P_0)}{r(P_0)}$$

where r(P) is the power-dependent responsivity (for a power meter, the responsivity is defined as the ratio of displayed power to actual input power).

Linewidth

FWHM spectral bandwidth. The 3 dB width of the optical spectrum, expressed in Hertz. Symbol: Δf .

Noise

The peak-to-peak change of displayed power level with zero input power level (dark).

Conditions: Zero prior to measurement, averaging time and observation time as specified, lowest power range selected and wavelength range as specified.

Measurement: the measurement result is obtained by:

 $Noise = P_{max} - P_{min}$

expressed as peak-to-peak within the given time span. Any offset is automatically excluded this way.

Power range

The power range is defined from the highest specified input power level to the smallest input power level that causes a noticable change of displayed power level.

Conditions: wavelength, averaging time as specified.

Reference conditions

The specified conditions during the spectral responsivity calibration, or conditions which are extrapolated from the conditions during calibration.

Conditions: power level, beam diameter or fiber type, numerical aperture, wavelength, spectral width, ambient temperature as specified, at the day of calibration. \rightarrow Noise and drift observed over a specified observation time, with a temperature change of not more than $\pm \Delta T$.

Relative uncertainty (spectral ripple) due to interference

Uncertainty of power reading when using a coherent source, due to a periodic change of the power meter's responsivity caused by optical interference¹ between reflective interfaces within the power meter's optical assembly.

Conditions: constant wavelength, constant power level, angled connector as specified, linewidth of source <100 MHz, temperature as specified.

Relative uncertainty due to polarization

Also termed polarization-dependent responsivity (PDR), the relative uncertainty due to polarization is the uncertainty of the displayed power level on the input polarization state, expressed as the difference between the highest and the lowest displayed power. Uncertainty figures are based upon a 95% confidence level.

Conditions: laser source with variable polarization state, generation of all possible polarization states (covering the entire Poincaré sphere), constant wavelength, constant power level, angled connector as specified, temperature as specified.

Return loss:

The ratio of the incident power to the reflected power expressed in dB. Symbol: *RL*.

$$RL = 10\log\left(\frac{P_{in}}{P_{back}}\right)$$

Conditions: the return loss excludes any reflections from the fiber end used as radiation source.

Spectral width of optical source

Full width at half maximum. The 3 dB width of the optical spectrum, expressed in nm. Symbol: *FWHM*.

Total uncertainty

The uncertainty for a specified set of operating conditions, including noise and drift.

Conditions: power level, beam diameter or fiber type, numerical aperture, wavelength, spectral width, ambient temperature, re-calibration period as specified. \rightarrow Noise and drift observed over a specified observation time, with a temperature change of not more than $\pm \Delta T$.

Uncertainty at reference conditions

The uncertainty for the specified set of reference conditions, including all uncertainties in the calibration chain from the national laboratory to the test meter.

Wavelength Range

The range of wavelengths for which the power meter is calibrated.

Note: Selectable wavelength setting of the power meter for useful power measurements (operating wavelength range).

Literature

[1] Fiber optic test and measurement, Hewlett Packard Professional Books, edited by Prentice Hall, ISBN 0-13-534330-5

Power Sensor Specifications (Autorange Mode)

Table 3 Power Sensor Specifications

	Agilent 81632A	Agilent 81635A	Agilent 81633A	Agilent 81634A	
Sensor Element	InGaAs InGaAs (dual)		InC	GaAs	
Wavelength Range	800 -	1650 nm	800 - 1700 nm		
Power Range	+10 to -80 dBm		+10 to -90dBm	+10 to -100 dBm	
Display Resolution	0.0001	dB/dBm, 0.01pW to 10	0 pW (depending on po	wer range)	
Applicable Fiber Type		M up to 62.5 μ m core $IA \le 0.24$		M up to 100 μm core [A ≤ 0.3	
Uncertainty (accuracy) at Reference Conditions ¹	<±3% (1200 nm to 1630 nm)		< ±2.5% (1000	nm to 1650 nm)	
Total Uncertainty ²	<±5% ⁸ (1200	nm to 1630 nm)	< ±4.5% (1000	nm to 1650 nm)	
Relative Uncertainty Due to Polarization ³	± 0.015 dB typical		± 0.005 dB		
Spectral Ripple (due to interference) 4	± 0.015 dB typical		± 0.005 dB		
Linearity (power) 5	CW +10 to -60 dB	m (1200 to 1630 nm)	CW +10 to -70 dBm	CW +10 to -90 dBm	
- at 23°C ±5°C	$< \pm 0.02 d$	$B \pm 20 \text{ pW}^9$	$< \pm 0.015 \text{ dB} \pm 2 \text{ pW}$	$<\pm 0.015 dB \pm 0.2 pW$	
- at operating temp. range	$< \pm 0.06 d$	$B \pm 20 \text{ pW}^9$	$< \pm 0.05 \text{ dB} \pm 2 \text{ pW}$	$< \pm 0.05 \text{ dB} \pm 0.5 \text{ pW}$	
Return Loss ⁷	>4	0 dB	>55 dB		
Noise (peak to peak) 5, 6	< 2	0 pW	< 2 pW	< 0.2 pW	
Averaging Time (minimal)	10	00 μs	100 μs		
Dimensions (H x W x D)		$75 \text{ mm} \times 32 \text{ mm} \times 335$	5 mm (2.8" × 1.3" × 13.	2")	
Weight		0	0.5 kg	200	
Recalibration Period	WOO M 000	2	years		
Operating Temperature	+10°C	to +40°C	0°C to +45°C		
Humidity		Non-c	ondensing		
Warm-up time		20 1	minutes		

Table 3 Power Sensor Specifications						
	Agilent 81632A	Agilent 81635A	Agilent 81633A	Agilent 81634A		
1 Reference Conditions				<i></i>		
• Power level 10 μW (-20 dBm), cor	ntinuous wave (CW)	•				
• Fiber 50 μm graded-index, NA=0.2	2					
• Ambient temperature 23°C ± 5°C						
• On day of calibration (add ± 0.3%	for ageing over one	year; add \pm 0.6% over	two years)			
• Spectral width of source < 10 nm (l	FWHM)					
Wavelength setting at Power Meter	must correspond to	source wavelength ± 0).4 nm			
2 Total uncertainty includes polarizati	on, interference, line	earity conditions:				
• Fiber $\leq 50 \mu\text{m}$, NA ≤ 0.2						
Only Agilent 81632A and Agilent 8	81635A: For fiber 6	2.5 μm graded-index (l	NA=0.24): add ± 2 %			
• Within one year of calibration, add	0.3% for second yes	ar				
Add ±1% for Biconic connector						
3 All states of polarization at constant	wavelength (1550 r	nm ± 30 nm) and consta	ant power, straight conn	ector, T=23°C±5 °C		
For angled connector (8°C) add 0.01 c	IB typ.			1E		
4 Conditions:				WI		
Wavelength 1550 nm ± 30 nm, fixed s	tate of polarization,	constant power, Tempe	erature 23°C ± 5°C			
Linewidth of source ≥ 100 MHz, angle	ed connector 8°.		W V 7 1999 (Lance			
5 At constant temperature $\Delta T = \pm 1^{\circ}C$		S. S				
6 Averaging time 1 s, $T = 23^{\circ}C \pm 5^{\circ}C$, observation time 3	300 s. Wavelength rang	e 1200 - 1630 nm.	8.198. W.S		
7 Conditions						
• Wavelengths 1310 nm ± 30 nm and	1 1550 nm ± 30 nm					
Standard single-mode fiber, angled	connector min 8°					
• T= 23°C ± 5 °C						

8 For wavelengths >1600 nm add ±0.06 %/nm

9 For input power >2 mW add ±0.02 dB

Performance Tests

The procedures in this section test the performance of the instrument. The complete specifications to which the Agilent 81632A/3A/4A Power Sensor Modules and the Agilent 81635A Dual Power Sensor Module are tested are given in "Specifications" on page 13. All tests can be performed without access to the interior of the instrument. The performance tests refer specifically to tests using the Diamond HMS-10/Agilent connector.

Equipment Required

Equipment required for the performance test is listed in the table below. Any equipment that satisfies the critical specifications of the equipment given in the table may be substituted for the recommended models.

Table 4 Required Equipment

Instrument/Accessory	Recommended Model	8163xA				Required	Alternative Models
		2A	5A	3A	4A	Characteristics	
Multimeter Mainframe	Agilent 8163A (2 each)	x	X	х	X		Agilent 8164A
CW Laser Module	Agilent 81656A	x	X	X	X		Agilent 81657A
CW Laser Module	HP 81554SM	x	X	X	X		Agilent 81657A
Power Meter Standard	HP 81533B Optical Head Interface Module with HP 81521B #C01 Working Standard Optical Head	x	X	X	х		
Power Sensor Module	HP 81532A	x	X	X	X		Agilent 81634A
Optical Attenuator	Agilent 8156A #221	x	X	X	X		
Optical Attenuator	Agilent 8156A #101	x	X	X	X		HP 8157A or HP 8158B #002
Backreflector Kit	Agilent 8156A #203	x	X	X	X		
Return Loss Module	HP 81534A	x	x	X	x		
Tunable Laser Source	Agilent 8164A and Agilent 81680A #022	-	=	0	0		HP 8168E/F #022
Polarization Controller	HP 11698A	-		0	0		
Wavelength Independed Coupler (3 dB)	Special Tool	_		0	0		
Best IF Adapter	Special Tool	-	#	0	O		
Singlemode Fiber	Agilent 81101AC (2 each)	x	x	x	x		
	Agilent 81102SC (1 each)	x	X	X	X		
	Agilent 81109AC (1 each)	x	X	X	X		
	Agilent 81113PC (3 each)	x	X	X	X		F
	Agilent 81113SC (1 each)	x	X	X	X		Ì
Connector Adapters	Agilent 81000AA (1 each)	x	X	X	X		
Connector Interfaces	Agilent 81000AI (5 each)	x	X	X	X		
	Agilent 81000FI (3 each)	x	X	X	x		
	Agilent 81000SI (5 each)	x	X	X	X		
Plastic Cap	PN 5040-9351	x	X	X	X	A.	
DIN Feedthrough	PN 1005-0255	x	X	x	X		

Legend:

- not applicable
- x necessary
- o optional

Test Record

Results of the performance test may be tabulated on the Test Record provided at the end of the test procedures. It is recommended that you fill out the Test Record and refer to it while doing the test. Since the test limits and setup information are printed on the Test Record for easy reference, the record can also be used as an abbreviated test procedure (if you are already familiar with the test procedures). The Test Record can also be used as a permanent record and may be reproduced without written permission from Hewlett-Packard.

Test Failure

If the Agilent 81632A/3A/4A/5A fails any performance test, return the instrument to the nearest Agilent TechnologiesSales/Service Office for repair.

Instrument Specification

Specifications are the performance characteristics of the instrument that is certified. These specifications, listed in "Specifications" on page 13, are the performance standards or limits against which the Agilent 81632A/3A/4A/5A can be tested. "Specifications" on page 13 also lists some supplemental characteristics of the Agilent 81632A/3A/4A/5A. Supplemental characteristics should be considered as additional information.

Any changes in the specifications due to manufacturing changes, design, or traceability to the National Institute of Standards and Technology (NIST), will be covered in a manual change supplement, or revised manual. Such specifications supercede any that were previously published.

Performance Test

The performance test given in this section includes the Accuracy Test, the Linearity Test, the Return Loss Test and the Noise Test. The performance test for the Agilent 81633A and Agilent 81634A also includes – as optional tests – the Relative Polarization Uncertainty and the Relative Interference Uncertainty Test. Perform each step in the order given, using the corresponding test equipment.

NOTE Make sure that all optical connections are dry and clean. DO NOT USE INDEX MATCHING OIL. For cleaning, use the cleaning instructions given in "Cleaning Procedure" on page 55.

Fix the optical cables that connect the laser source and Power Meter to the Agilent 8156A Attenuator. This ensures minimum cable movement during the tests.

Accuracy Test

NOTE

The linearity test must only be performed at either 1310 nm or 1550 nm. The accuracy test must be performed in the -20 dBm range at 10 μ W at both 1310 nm and 1550 nm.

Test Setup

- 1 Make sure that cable connector, detectors and adapters are clean.
- 2 Connect the equipment as shown in Figure 2. Instead of a HP 81554SM Laser Source you can also use a Agilent 81657A Laser Source. Ensure that the cables to and from the attenuator are fixed on the table and that both the optical head and the DUT are close together so that minimum cable movement is required when connecting the cable to the head or to the DUT.
- 3 Move to the Laser Source channel, move to the wavelength parameter, $[\lambda]$, press *Enter*, select the lower wavelength source, and press *Enter*.

4 If you are using a Agilent 81657A Laser Source ensure to initialize the Agilent 8156A Optical Attenuator with 30 dB attenuation.




Figure 2 Accuracy Test Setup

- 5 Turn the instruments on, enable the laser source and allow the instruments to warm up for at least 20 minutes.
- 6 Perform the following sub-procedure for both Power Meters:
 - a Move to the Power Meter channel.
 - **b** Move to the wavelength parameter, $[\lambda]$, press *Enter*, enter the wavelength of the laser source, and press *Enter*.
 - c Move to the calibration parameter, [CAL], press Enter, set the calibration parameter to zero, and press Enter.
 - **d** Move to the averaging time parameter, [AvgTime], press Enter, move to <500 ms>, and press Enter.
 - e Move to the power parameter, [P], press [Pwr unit], move to < Watt>, and press Enter.
- 7 Make sure the optical input of the Device Under Test (DUT), 8163xA, is not receiving any light by placing a plastic cap over the input. Move to the DUT Power Meter channel, press [Menu], move to <Zero>, press Enter.
- 8 Ensure, that the Agilent 8156A output is disabled. Move to the reference Power Meter channel, 81532A, press [Menu], move to <Zero>, press Enter.
- 9 Enable the Agilent 8156A output and change the attenuation until the reference Power Meter displays 10.00 μW.

- 10 Connect the attenuator output cable to the DUT Power Meter. Note the power value returned from the DUT, [P], from the display and note the result in the test record.
- 11 Move to the Laser Source channel, move to the wavelength parameter, $[\lambda]$, press *Enter*, select the longer wavelength source, and press *Enter*.
- 12 Repeat steps 4 to 10 at the second wavelength with the corresponding source.

Linearity Test




Figure 3 Measurement Setup for Power Linearity

NOTE

- Do not turn the laser off during the measurement!
- Clean all connectors carefully before you start with the measurement!

Test Setup

- 1 Make sure that cable connector, detectors and adapters are clean.
- 2 Make sure that you perform this test in a temperature-controlled environment with temperature fluctuations less than $\pm 1^{\circ}$ C.
- 3 Setup the equipment as shown in Figure 3. Disable both attenuators and enable the laser source, where the source wavelength is chosen to 1550 nm. If you are using the 81657A, move to the wavelength parameter, [λ], press *Enter*, select the longer wavelength source (1550 nm nominally), and press *Enter*.

- **4** Set the wavelength of both attenuators to the same wavelength as the laser source.
- 5 Perform the following sub-procedure for both Power Meters:
 - a Move to the Power Meter channel.
 - **b** Move to the wavelength parameter, $[\lambda]$, press *Enter*, enter the wavelength of the laser source, and press *Enter*.
 - c Move to the calibration parameter, [CAL], press Enter, set the calibration parameter to zero, and press Enter.
 - **d** Move to the averaging time parameter, [AvgTime], press Enter, move to <100 ms>, and press Enter.
 - e Move to the power parameter, [P], press [Pwr unit], move to <dBm>, and press Enter.
 - **f** Press the [Menu] softkey and move to *Number of digits*>, press *Enter*, move to *3*>, press *Enter* and press [Close].
- 6 Initialize the two attenuators as follows:
 - a Set the attenuation of the 8156A #221 with Monitor Output (referred to as Atty1) to 0 dB.
 - **b** Set the attenuation of the other 8156A (referred to as Atty2) to 35 dB.
- 7 Wait at least 15 minutes until the laser source is stabilized.
- 8 Perform the following sub-procedure for the reference Power Meter, 81532A:
 - a Press [Menu], move to <Range mode>, move to <Manual>, and press Enter.
 - **b** Move to <*Range*>, press *Enter*, move to <-40 dBm>, press *Enter*, and press [Close].
- **9** Perform the following sub-procedure for the DUT, 8163xA:
 - a Press [Menu], move to <Range mode>, move to <Manual>, and press Enter.
 - **b** Move to <*Range*>, press *Enter*, move to <*10 dBm*>, and press *Enter*.
 - c Zero both Power Meters. Move to <Zero all> and press Enter.
- 10 Enable both attenuators.
- 11 Adjust the attenuation of Atty2 in order to achieve -37.2 dBm on the reference Power Meter.

+10 dBm Range

- 12 Note both power readings as the first value in the test record, which is given at the end of the test descriptions (#1).
- **NOTE** Always include the three digits after the decimal point when you note a power reading.

- 13 Increase the attenuation of Atty1 until the power reading of the DUT shows about +2.8 dBm.
- 14 Note the InRange-values in the test record (#2)
- 15 Perform the following sub-procedure for the DUT, 8163xA:
 - a Press [Menu], move to <Range mode>, move to <Manual>, and press Enter.
 - **b** Move to <*Range*>, press *Enter*, move to <*0 dBm*>, and press *Enter*.
- **16** If necessary, adjust the attenuation of Atty2 in order to be on the upper limit of the -40 dBm range (i.e. -37.2 dBm).

0 dBm Range

- 17 Disable Atty1.
- **18** Zero both Power Meters. On the 8163A with two installed power meters, press [Menu], move to <*Zero all*>, and press *Enter*.
- 19 Enable Atty1.
- 20 Switch one range up to the +10dBm range.
- 21 Note both power readings (#3).
- 22 Switch down to the previous range (0dBm) and note the values again (#4).
- 23 Increase Atty1 by 10 dB and note the results in the test record (#5).
- **24** Move to the channel of the DUT, 8163xA, press [Menu], move to <*Range*>, press *Enter*, move to <*-10 dBm*>, and press *Enter*.
- 25 If necessary, adjust the attenuation of Atty1 in order to be on the upper limit of the range (i.e. -x7.y dBm).
- 26 Decrease the attenuation of Atty2 by 10 dB in order to be on the upper limit of the -40 dBm range.

-10 dBm Range

- 27 Disable Atty1.
- **28** Zero both Power Meters. On the 8163A with two installed power meters, press [Menu], move to <*Zero all*>, and press *Enter*.
- 29 Enable Atty1.
- 30 Switch one range up to the 0 dBm range and note the power readings (#6).
- 31 Switch down to the previous range (-10 dBm) and note the values again (#7).
- 32 Increase the attenuation of Atty1 by 10 dB and note the results in the test record (#8).
- 33 On the DUT switch one range down to the -20 dBm range.

Change Setup

34 Disable Atty1 and switch the output with the monitor output.

35 Set the attenuation of Atty1 to 15 dB and of Atty2 to 35 dB.

36 Enable Atty1 again.

37 Adjust the attenuation of both attenuators in the following order:

- Atty1: DUT Power Meter shows a reading of -17.2 dBm and
- Atty2: the REF Power Meter shows a reading of -37.2 dBm.

-20 dBm to -50 dBm Range

38 Disable Atty1.

39 Zero both Power Meters. On the 8163A with two installed power meters, press [Menu], move to *<*Zero all>, and press *Enter*.

40 Enable Atty1.

41 Switch one range up and note both power readings.

42 Switch one range down and note the power readings again.

43 Increase the attenuation of Atty1 by 10 dB and note the results in the test record.

44 On the DUT switch one range down. Adjust the attenuation of Atty1, if necessary, so that the power displayed by the DUT is at the upper limit of the range, that is, -x7.y dBm.

45 Decrease the attenuation of Atty2 by 10 dB in order to be on the upper limit of the -40 dBm range.

Repeat step 33 to 39 until the power reading of the DUT shows -57.x dBm.

Calculation

46 Calculate the non-linearity using the formulas given in the test record.

Example: Measurement Results

Information only			Your Enti	ries		
n	Atty1 / #221 [dB]	Any2/#100 [dB]	DUT Range [dBm]	REF Power [dBm]	DUT Pow- er [dBm]	Notes
1	0	24	10	-37,291	8,957	1. Value
2	6	24	10	-42,928	3,314	InRange
3	6	18	10	-37,299	3,317	RangeDisc / lower limit
4	6	18	0	-37,298	3,318	RangeDisc / upper limit
5	16	18	0	-47,280	-6,666	InRange

Information only				Your Entr	ies	
n	Atty1 / #221 [dB]	Atty2/#100 [dB]	DUT Range [dBm]	REF Power [dBm]	DUT Pow- er [dBm]	Notes
6	16	8	0	-37,301	-6,664	RangeDisc / lower limit
7	16	8	-10	-37,299	-6,662	RangeDisc / upper limit
8	26	8	-10	-47,294	-16,658	InRange
9	7,7	35,7	-10	-37,304	-17,321	RangeDisc / lower limit
10	7,7	35,7	-20	-37,302	-17,318	RangeDisc / upper limit
11	17,7	35,7	-20	-47,293	-27,309	InRange
12	17,7	25,7	-20	-37,285	-27,312	RangeDisc / lower limit
13	17,7	25,7	-30	-37,282	-27,309	RangeDisc / upper limit
14	27,7	25,7	-30	-47,280	-37,308	InRange
15	27,7	15,7	-30	-37,278	-37,306	RangeDisc / lower limit
16	27,7	15,7	-40	-37,276	-37,304	RangeDisc / upper limit
17	37,7	15,7	-40	-47,277	-47,306	InRange
18	37,7	5,7	-40	-37,274	-47,301	RangeDisc / lower limit
19	37,7	5,7	-50	-37,271	-47,298	RangeDisc / upper limit
20	47,7	5,7	-50	-47,270	-57,298	InRange

Calculations

	Conversion [dBm] → [mW]		Calculation	as given	Calculation as given		
n	Ref/R [mW]	DUT/D [mW]	Relation 1 / A $= R_{n+1}/R_n$	Relation 2 / B $= D_n/D_{n+1}$	Non-Linearity $= A_n * B_n (NL_{n\pm 1} + 1) - 1 $ [%]		
1	1,86612E-04	7,86448E+00	2,73049E-01	3,66708E+00	-0,02		
2	5,09542E-05	2,14462E+00					
3	1,86312E-04	2,14640E+00	9,99724E-01	9,99701E-01	-0,15		
4	1,86260E-04	2,14704E+00	1,00434E-01	9,96300E+00	-0,09		
5	1,87068E-05	2,15501E-01					
6	1,86256E-04	2,15561E-01	9,99540E-01	9,99471E-01	-0,16		
7	1,86170E-04	2,15675E-01	1,00157E-01	9,99079E+00	-0,06		
8	1,86462E-05	2,15874E-02					
9	1,86110E-04	1,85298E-02	9,99540E-01	9,99240E-01	-0,12		
10	1,86024E-04	1,85439E-02	Referenc	e Level	0,00		
11	1,86518E-05	1,85819E-03	9,97356E+00	1,00205E-01	-0,06		
12	1,86973E-04	1,85708E-03					

n	Conversion [dBm] → [mW]		Calculation as given		Calculation as given
	Ref/R [mW]	DUT/D [mW]	Relation 1 / A $= R_{n+1}/R_n$	Relation2 / B = D _n /D _{n+1}	Non-Linearity $= A_n * B_n (NL_{n\pm 1} + 1) - 1 $ [%]
13	1,86857E-04	1,85810E-03	1,00062E+00	1,00055E+00	0,06
14	1,87068E-05	1,85849E-04	9,98872E+00	1,00021E-01	-0,03
15	1,87245E-04	1,85935E-04			
16	1,87150E-04	1,86050E-04	1,00051E+00	1,00062E+00	0,08
17	1,87206E-05	1,85973E-05	9,99701E+00	9,99586E-02	0,01
18	1,87443E-04	1,86149E-05			
19	1,87335E-04	1,86264E-05	1,00058E+00	1,00062E+00	0,13
20	1,87495E-05	1,86312E-06	9,99148E+00	1,00025E-01	0,07

NOTE ①: The Nonlinearity is calculated recursively using n=11 as reference point. The formula is:

$$NL_{n} = \begin{cases} A_{n}/B_{n} \cdot (NL_{n+1} + 1) - 1 & \text{for } n < 10\\ A_{n}/B_{n} \cdot (NL_{n-1} + 1) - 1 & \text{for } n > 10 \end{cases}$$




Figure 4 Linearity Test

Noise Test

- 1 Insert the device under test, a 8163xA Power Sensor, into a slot of the 8163A mainframe. Make sure the optical input of the Device Under Test (DUT), 8163xA, is not receiving any light by placing a plastic cap over the input. Move to the DUT Power Meter channel, press [Menu], move to <Zero>, and press Enter.
- **2** Press *Appl*, move to *Stability*>, and press *Enter*. The Stability Setup Screen appears.
- 3 Ensure, that the correct channel is selected in the upcoming Module Selection box.
- 4 Press [Menu] to access the Logging application menu screen.
- 5 Move to <*Pwr unit*>, press *Enter*, move to <*W*>, and press *Enter*.
- 6 Move to <*AvgTime*>, press *Enter*, move to <*1 s*>, and press *Enter*.
- 7 Move to <*Range mode*>, press *Enter*, move to <*Auto*>, and press *Enter*, and press [Close].
- **8** Press the [Parameter] softkey, move to [*TotalTime*], press *Enter*, set the total time to 00:05:00, which is 5 minutes, and press *Enter*.
- 9 Press the [Measure] softkey to start the measurement.
- 10 After the stability application has finished, press the [Analysis] softkey, press the [more] softkey, and note $[\Delta P]$ as the noise value in the test record.

Return Loss Test

- 1 Connect the equipment as shown in Figure 5/①. Alternatively, you can use a clean and undamaged straight fiber end as a reference reflector.
- 2 Move to the fixed wavelength Laser Source channel, select [Menu] and set the <*Modulation src 15xx.xnm>* to <*Coherence Ctrl>*. Ensure, that you set the modulation of the upper wavelength source if you are using a Agilent 81657A Laser Source.
- 3 Set the attenuation of the Agilent 8156A optical attenuator to 10.0 dB at the wavelength given by the source module and enable the output of the attenuator.
- 4 Set the averaging time of the Return Loss Module to 1s by pressing *Param* and set the wavelength to the wavelength of the Laser Source.
- 5 Zero the Return Loss Module.
- **6** Select the reference parameter, R, by pressing *Param* and set this to 0.18 dB (in case of a straight fiber end as reflector, set the reference to 14.7 dB).
- 7 Enable the source output and press $Disp \rightarrow Ref$ for the Return Loss Module.
- 8 Select the termination parameter T by pressing *Param*.

- 9 Disconnect the Agilent 81102SC and the Agilent 8156A #203 patchcords from each other.
- 10 Press $Disp \rightarrow Ref$ for the Return Loss Module.
- 11 Ensure, that the termination parameter T at the Return Loss Module shows a reading of more than 50dB.
- 12 Connect the DIN-connector of the 81102SC patchcord to the sensor module as shown in Figure 5/②.




Figure 5 Return Loss Measurement Setup

13 Note the result as the return loss of the sensor module into the test record.

Relative Uncertainty due to Polarization (Optional Test)

NOTE The performance test "Relative Uncertainty due to Polarization" is optional, since the polarization is given with the production of the unit by mechanical and optical cavities and stays unchanged by normal use of the sensor module.

Below, you will find the test setup to verify the relative uncertainty due to polarization of the sensor module. Generally, during this measurement-procedure the tunable laser source is swept through a predefined wavelength range. After every wavelength step, a single PDL-measurement is made, where the polarization controller generates all different polarization states. The highest PDL

value is taken as the "relative uncertainty due to polarization". The low output power path of the coupler is used to monitor the power stability of the setup.




Figure 6 Measurement Setup for PDL Test

Relative Uncertainty due to Interference (Optional Test)

NOTE

The performance test "Relative Uncertainty due to Interference" is optional, since the interference is given with the production of the unit by mechanical and optical cavities and stays unchanged by normal use of the sensor module.

Below, you will find the test setup to verify the relative uncertainty due to interference of the sensor module. In order to perform the relative uncertainty due to interference test, it is mandatory to use two mainframes, since the time difference between measurement A und B for a specific wavelength point has to be at most 2 ms. Due to this short measurement interval, the performance test of the relative uncertainty due to interference can only be using computer control.




Figure 7 Setup for Relative Uncertainty due to Interference Measurement

Theoretically, both Power Meters are monitoring the power ratio over the variable wavelength in a predefined range as shown in Figure 8. Ensure that the tunable laser source is mode-hop free in the tested wavelength range.




Figure 8 Interference Ripple

Performance Test for the Agilent 81632A

Page 1 of 3			
Model	Agilent 81632A Sensor Module	Date _	5. 50- E8-H-C
Serial No.	7	Ambient Temperature _	°C
Options	0	Relative Humidity _	%
Firmware Rev.	19	Line Frequency _	Hz
Test Facility		Customer	Feb. St. 1886
Performed by		Report No	
Special Notes			
		St. 155, the 1986	A) Technology (1990)
		5-9 p. () 134-134-2	
	2 <u></u>		· · · · · · · · · · · · · · · · · · ·

Performance Test for the Agilent 81632A

Test Equipment Used

Page 2 of 3

	Description	Mo	odel No.	T	race No	C	al. Due Date
1a1	Lightwave Multimeter (Std.)	Ag	ilent 8163A			\(\frac{1}{2}\)	
1a2	Lightwave Multimeter (DUT)	Ag	ilent 8163A	conta			
1b	TLS Mainframe	Ag	ilent 8164A	-			
2a1	CW High Power Laser Source	Ag	ilent 81655A	8 200-01	we <u>17 2200 - </u>		
2a2	CW High Power Laser Source	Ag	ilent 81656A				
2b	CW Dual High Power Laser Source	Ag	ilent 81657A		- M	199	
3	CW Dual Laser Source	HP	81554SM		too to a second	_	
4a1	Opt. Head Interface Module	HP	81533B			(-2	
4a2	Optical Head, Reference	HP	81521B	-			
5	Sensor Module	HP	81532A				
6	Optical Attenuator	Agi	lent 8156A #221	85			2
7a	Optical Attenuator	Agi	Agilent 8156A #101			-	
7b	Optical Attenuator	HP	HP 8157A			-	
7c	Optical Attenuator	HP	8158B #002	-			
8	Return Loss Module	HP	81534A	_		7 <u>-2-4-44</u>	
9				10-10-		1944 - 1	
10		-		32		-	1000000
11		-		85	——————————————————————————————————————	-	
12				3 1720-1 3		-	
Access	ories	#	Product	#	Product	#	Product
Single	emode Fibers	2	81101AC	1	81102SC	1	81109AC
		3	81113PC	1	81113SC		
Conne	ector Interfaces	5	81000AI	3	81000FI	5	81000SI
Conne	ector Adapters	1	81000AA				
Backr	eflector Kit	1	8156A #203				

Performance Test for the Agilent 81632A

Page 3 of 3

Model Agilent 81632A Sensor Module			dule	Report No)	Date		
Test					Min.		Max.	Measurement
No.	Test Des	cription			Spec.	Result	Spec.	Uncertainty
I	Accurac	y Test				$[\mu W]$		
	measured (1310nm	d at)		ıt Power	9.64 μW Power		10.36 μW	
	measured (1550nm	d at)		ut Power	9.64 μW		10.36 μW	
II	Lineari	ty Test		For Calculation	s you may wai	nt to use the ap	propriate sheet	
	Range	P _{DUT} [dB	Bm]	P _{DUT} [dBm]		Loss [%]		
	+10	+9		<u></u>		-	<± 0.93 %	
	+10	+3				E	<± 0.46 %	
	0	+3		Six of the second		·	<± 0.46 %	
	0	-7		V-20-11-07-11-11-19		W	<± 0.46 %	
	-10	-7		5 0.00.00.00.00.00.00 7		Woman benefit in the W	<± 0.46 %	
	-10	-17		(<u>-</u>			<± 0.46 %	
	-20*	-17*		Reference		0.0	<± 0.46 %	
	-20	-27		2-1-2			<± 0.46 %	
	-30	-27				Parameter Committee	<± 0.46 %	
	-30	-37				19	<± 0.47 %	
	-40	-37		12-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		5 20,000,000,000,000,000,000,000,000,000,	<± 0.47 %	
	-40	-47		N		-	<± 0.56 %	
	-50	-47		1		8-8	<± 0.56 %	
	-50	-57				26	<± 1.46 %	
Ш	Noise To	est				[pW]		
						7-11-12-13-13-13-13-13-13-13-13-13-13-13-13-13-	< 20 pW	
IV	Return	Loss Test				[dB]		
					40 dB <			

Performance Test for the Agilent 81633A

Page 1 of 3			
Model	Agilent 81633A Sensor Module	Date	
Serial No.		Ambient Temperature	°C
Options		Relative Humidity	%
Firmware Rev.		Line Frequency	Hz
Test Facility		Customer	
Performed by		Report No	
Special Notes			44 (1)
		77 28 77 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	
			100 mg = 500
	8		

Performance Test for the Agilent 81633A

Test Equipment Used

Page 2 of 3

1 age 2	2 01 3							
	Description	Mo	del No.	Tr	ace No	Ca	l. Due Date	
1a1	Lightwave Multimeter (Std.)	Agi	lent 8163A	_			o de la constanta	
1a2	Lightwave Multimeter (DUT)	Agi	Agilent 8163A					
1b	TLS Mainframe	Agi	Agilent 8164A					
2a1	CW High Power Laser Source	Agi	lent 81655A					
2a2	CW High Power Laser Source	Agi	lent 81656A	<i>a</i>		76	***************************************	
2b	CW Dual High Power Laser Source	Agi	lent 81657A	_		2	100	
3	CW Dual Laser Source	HP	81554SM	-	 	100		
4a1	Opt. Head Interface Module	HP	81533B			-		
4a2	Optical Head, Reference	HP	81521B	_	The sales of the	- V - 5/6		
5	Sensor Module	HP	81532A	-		7) <u></u>		
6	Optical Attenuator	Agi	lent 8156A #221			2	- North State	
7a	Optical Attenuator	Agi	lent 8156A #101	22.10		19 <u>22</u>		
7b	Optical Attenuator	HP	8157A	-				
7c	Optical Attenuator	HP	8158B #002			8		
8	Return Loss Module	HP	81534A	-		0)		
9	,	:		_		10-		
10				-		8		
11						-		
12		1.2	32-11-34			1.72 1.733-1.03		
Acces	sories	#	Product	#	Product	#	Product	
Sing	lemode Fibers	2	81101AC	1	81102SC	1	81109AC	
		3	81113PC	1	81113SC			
Conr	nector Interfaces	5	81000AI	3	81000FI	5	81000SI	
Conr	nector Adapters	1	81000AA		3			
Back	creflector Kit	1	8156A #203					

Performance Test for the Agilent 81633A

Page 3 of 3

rage 3			2002 S	···				
Mode	l Agilent 8	1633A Senso	or Modu	ıle	Report No	•	Date	
Test No.	Test Des	cription			Min. Spec.	Result	Max. Spec.	Measurement Uncertainty
I	Accurac	y Test				$[\mu W]$		
	measured (1310nm	d at	nm Output 1	Power	9.69 μW	() 	10.31 μW	
	measured atnm (1550nm) Output Pov		Power	9.69 μW	[]	10.31 μW		
II	Linearit	y Test	F	or Calculations	you may wan	t to use the app	propriate sheet	
	Range	P _{DUT} [dBn	n] l	P _{DUT} [dBm]		Loss [%]		
	+10	+9				Q 2300A 3000T	<± 0.35 %	
	+10	+3					<± 0.35 %	
	0	+3	-	.			<± 0.35 %	
	0	-7	_			9	<± 0.35 %	
	-10	-7	_			Э	<± 0.35 %	
	-10	-17	_			3	<± 0.35 %	
	-20*	-17*	I	Reference		0.0	<± 0.35 %	
	-20	-27					<± 0.35 %	
	-30	-27	<u> </u>			4	<± 0.35 %	
	-30	-37	-			: [<± 0.35 %	
	-40	-37	-				<± 0.35 %	
	-40	-47	_			1	<± 0.36 %	
	-50	-47	-			, -1000	<± 0.36 %	
	-50	-57	_			-	<± 0.45 %	
Ш	Noise Te	st				[pW]		
						·	< 2 pW	
IV	Return I	Loss Test				[dB]		
					55 dB <			
(V)	Relative	Uncertainty	due to	Polarization		[dB]		
		m difference i - 1560 nm / (< 0.01 dB	
(VI)	Relative	Uncertainty	due to	Interference		[dB]		
		m difference i - 1560 nm / 2				S	< 0.01 dB	

Performance Test for the Agilent 81634A

Page 1 of 3			
Model	Agilent 81634A Sensor Module	Date	
Serial No.	B-1	Ambient Temperature	°C
Options		Relative Humidity	%
Firmware Rev.		Line Frequency	Hz
Test Facility		Customer	
Performed by		Report No	
Special Notes			
	Taxana and the same and the sam		A
	8		
	Saltonia estimata per alterna de la companya de la		5 / RVXX/y
			10 400
		- p. 15 x 15 000 24 x 4 1/2 x - 1 1/200	

Performance Test for the Agilent 81634A

Test Equipment Used

Page 2 of 3

8-							
	Description	Mod	del No.	Tr	ace No	Ca	l. Due Date
1a1	Lightwave Multimeter (Std.)	Agi	lent 8163A			- W	
1a2	Lightwave Multimeter (DUT)	Agi	lent 8163A	-	***************************************	-	
1b	TLS Mainframe	Agi	lent 8164A			· ·	****
2a1	CW High Power Laser Source	Agi	lent 81655A				
2a2	CW High Power Laser Source	Agi	lent 81656A	_			
2b	CW Dual High Power Laser Source	Agi	lent 81657A				
3	CW Dual Laser Source	HP	81554SM			-	
4a1	Opt. Head Interface Module	HP	81533B	-		9	
4a2	Optical Head, Reference	HP	81521B	2		_	
5	Sensor Module	HP	81532A	-	5 S S		
6	Optical Attenuator	Agi	lent 8156A #221	******	MICRORAL CONTRACTOR		
7a	Optical Attenuator	Agi	Agilent 8156A #101				- 10°
7b	Optical Attenuator	HP	HP 8157A			73 -	
7c	Optical Attenuator	HP	HP 8158B #002			10	
8	Return Loss Module	HP	81534A		*	8	
9	(A. C.	2 00 -3		-	Mini a section in the	1	
10		1 5-012-11				*	
11	-0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000 - 0000	8 1		20 - A		No.	s u sa santa s
12		La Company		6-7.		1	
Acces	sories	#	Product	#	Product	#	Product
Sing	lemode Fibers	2	81101AC	1	81102SC	1	81109AC
		3	81113PC	1	81113SC		
Con	nector Interfaces	5	81000AI	3	81000FI	5	81000SI
Con	nector Adapters	1	81000AA				
Back	reflector Kit	1	8156A #203				

Performance Test for the Agilent 81634A

Page 3 of 3

Model Agilent 81634A Sensor Module					Report No.		Date		
Test No.	Test Des	cription			Min. Spec.	Result	Max. Spec.	Measurement Uncertainty	
I	Accuracy Test					$[\mu W]$			
	measured (1310nm	d at		ut Power	9.69 μW	(10.31 μW		
	measured (1550nm	d at)		ut Power	9.69 μW		10.31 μW		
II	Linearit	y Test		For Calculation	s you may wa	int to use the ap	propriate sheet		
	Range	P _{DUT} [dł	Bm]	P _{DUT} [dBm]		Loss [%]			
	+10	+9				2 <u></u>	<± 0.35 %		
	+10	+3				0	<± 0.35 %		
	0	+3					<± 0.35 %		
	0	-7		2			<± 0.35 %		
	-10	-7					<± 0.35 %		
	-10	-17		104 11 - 12 10 10 10 10 10 10 10 10 10 10 10 10 10		West Control of the C	<± 0.35 %		
	-20*	-17*		Reference		0.0	<± 0.35 %		
	-20	-27				2 -11-11-11-11-11-11-11-11-11-11-11-11-11	<± 0.35 %		
	-30	-27				Ni 22	<± 0.35 %		
	-30	-37		 .		8 1122 - 1121 - 11	<± 0.35 %		
	-40	-37				Reserved Sections	<± 0.35 %		
	-40	-47				()	<± 0.35 %		
	-50	-47		Section Committee		¥ 	<± 0.35 %		
	-50	-57					<± 0.36 %		
Ш	Noise Te	st				[pW]			
							< 2 pW		
IV	Return I	Loss Test				[dB]			
					55 dB <				
(V)	Relative	Uncertaint	ty due	to Polarization		[dB]			
		n difference - 1560 nm				9 <u> </u>	< 0.01 dB		
(VI)	Relative	Uncertaint	ty due	to Interference		[dB]			
		n difference - 1560 nm					< 0.01 dB		

Performance Test for the Agilent 81635A

Page 1 of 3			
Model	Agilent 81635A Sensor Module	Date	77. (1860)
Serial No.		Ambient Temperature	°C
Options	2 -10-10-10-10-10-10-10-10-10-10-10-10-10-	Relative Humidity	%
Firmware Rev.	1	Line Frequency	Hz
Test Facility	19	Customer	
Performed by	·	Report No	
Special Notes			
	5		
		MARKET ST. S.	

Performance Test for the Agilent 81635A

Test Equipment Used

Page 2 of 3

	Description	Mode	el No.	Tra	ace No	Ca	l. Due Date
1a1	Lightwave Multimeter (Std.)	Agile	nt 8163A			p laneso	
1a2	Lightwave Multimeter (DUT)	Agile	nt 8163A	1 7			
1b	TLS Mainframe	Agile	nt 8164A	-			
2a1	CW High Power Laser Source	Agile	ent 81655A				***************************************
2a2	CW High Power Laser Source	Agile	nt 81656A	_		14 W	
2b	CW Dual High Power Laser Source	Agile	nt 81657A	81 <u>47</u>			
3	CW Dual Laser Source	HP 8	1554SM	(<u> </u>		85	2
4a1	Opt. Head Interface Module	HP 8	1533B	EN.	unicasa.	(<u></u>	2000
4a2	Optical Head, Reference	HP 8	1521B	(Tablishi)			
5	Sensor Module	HP 8	1532A	10-		()() (
6	Optical Attenuator	Agile	nt 8156A #221	19000		·	
7a	Optical Attenuator	Agile	nt 8156A #101			-	****
7b	Optical Attenuator	HP 8	157A	3 -110-	HILES HERRY	-	
7c	Optical Attenuator	HP 8	158B #002			=	
8	Return Loss Module	HP 8	1534A	9. 10	8700 FHB		
9			3500 F002 R004 F1 F724	_	A WIEL SAS	-	
10		A-1999	a a a a a a a a a a a a a a a a a a a	8 	·	-	
11					- 		
12			- Auritmanni II w	_		* 20-	
Acces	sories	#	Product	#	Product	#	Product
Sing	lemode Fibers	2	81101AC	1	81102SC	1	81109AC
		3	81113PC	1	81113SC		
Con	nector Interfaces	5	81000AI	3	81000FI	5	81000SI
Con	nector Adapters	1	81000AA				
Back	creflector Kit	1	8156A #203				

Performance Test for the Agilent 81635A

Page 3 of 3

Model Agilent 81632A Sensor Module			lule	Report No	10/1 - 20/100	Date		
Test					Min.		Max.	Measurement
No.	Test Desc	ription			Spec.	Result	Spec.	Uncertainty
I	Accuracy Test					[µW]		
	measured atnm (1310nm) Output Power		Power	9.64 μW	(1901-19-19-19-19-19-19-19-19-19-19-19-19-19	10.36 μW		
		measured at nm (1550nm) Output Power		. Power	9.64 μW		10.36 μW	
II	Linearity	Test		For Calculation	s you may war	nt to use the ap	propriate sheet	
	Range	P _{DUT} [d]	Bm]	P _{DUT} [dBm]		Loss [%]		
	+10	+9		3			<± 0.93 %	
	+10	+3		1			<± 0.46 %	
	0	+3		·			<± 0.46 %	
	0	-7					<± 0.46 %	
	-10	-7		CONTRACTOR OF THE PARTY OF THE			<± 0.46 %	
	-10	-17		200 - 201 - 2			<± 0.46 %	
	-20*	-17*		Reference		0.0	<± 0.46 %	
	-20	-27		-		-	<± 0.46 %	
	-30	-27		**********			<± 0.46 %	
	-30	-37					<± 0.47 %	
	-40	-37		2 -11-11-11-11-1			<± 0.47 %	
	-40	-47					<± 0.56 %	
	-50	-47					<± 0.56 %	
	-50	-57		s 1 			<± 1.46 %	
ш	Noise Tes	st				[pW]		
						S=	< 20 pW	
IV	Return I	oss Test				[dB]		
					40 dB <			

Calculation Sheet for Linearity Measurement

n	Conversion [dBm] → [mW]		Calculation as given		Calculation as given
	Ref / R	DUT/D	Relation1 / A	Relation2 / B	Non-Linearity
	[mW]	[mW]	$=R_{n+1}/R_n$	$= D_n/D_{n+1}$	$= A_n * B_n (NL_{n\pm 1} + 1) - 1 $ [%]
1					
2					
3					
4					
5					
6					
7					
8	11				
9					
10					
11					
12					
13					
14					
15					
16			12000		W. 1994
17					
18					
19					
20					

Cleaning Procedure

In general, whenever possible use physically contacting connectors, and dry connections. Clean the connectors, interfaces and bushings carefully each time after use.

WARNING

Make sure to disable all sources when you are cleaning any optical interfaces. Under no circumstances look into the end of an optical cable attached to the optical output when the device is operational.

The laser radiation is not visible to the human eye, but it can seriously damage your eyesight.

WARNING

To prevent electrical shock, disconnect the instrument from the mains before cleaning. Use a dry cloth or one slightly dampened with water to clean the external case parts. Do not attempt to clean internally.

The Cleaning Kit

A full cleaning kit contains the following items:

Isopropyl alcohol

This is usually available from pharmaceutical suppliers or chemists.

If possible, use alcohol supplied for medical purposes, rather than impure alcohol or alcohol with additives.

CAUTION

Do not use other solvents as some can damage plastic materials and claddings. For example, Acetone dissolves the adhesives used in fiber optic devices.

WARNING

Never drink this alcohol as this can lead to blindness or other serious damage to your health.

Cotton-swabs

Use swabs such as Q-tips or other cotton-swabs. These are typically available from local distributors of medical or hygiene products (such as supermarkets or pharmacies).

NOTE

If you are cleaning connector interfaces or adapters, the diameter of the cotton swab is important. Cotton swabs for babies normally have a smaller diameter.

CAUTION

Do not use foam swabs, as these can leave filmy deposits on the surface you are cleaning.

Store your cotton-swabs carefully and never reuse them. Dust and dirt from the air or from previous cleaning, can scratch or dirty your optical device.

Soft-tissues

These are available from most stores and distributors of medical and hygiene products (such as supermarkets or pharmacies).

Use multi-layer tissues made from non-recycled cellulose. These are more absorbent and softer than other types and they do not scratch the surface of your device.

CAUTION

Store your soft-tissues carefully and never reuse them, as dust and dirt from the air or from previous cleaning can scratch and dirty your optical device.

Pipe-cleaner

These are available from tobacco shops.

Ensure that the bristles of the pipe-cleaner are soft, so that they do not scratch your device during cleaning.

CAUTION

Store your pipe-cleaner carefully and never reuse them as dust and dirt from the air or from previous cleaning can scratch and dirty your optical device.

Compressed Air

This is available from laboratory suppliers.

It is essential that your compressed air is free of dust, water and oil. Only use clean, dry air. If you do not, it can lead to filmy deposits or scratches.

When using compressed air from a can,

- Hold the can upright. A slant can cause propellant to escape with the compressed air and dirty your optical device.
- Spray the first couple of seconds into the air, as the first stream of compressed air can contain condensation or propellant. Any condensation produces a filmy deposit.

If you are using compressed air from a can, you should select one with a CFC-free propellant, for the sake of the environment.

Other Cleaning Tools

To examine devices you also require:

Microscope

Select a microscope with a magnification range of between 50X and 300X. These should be available from photographic stores or laboratory suppliers.

Ensure that the light source of the microscope is flexible. This helps you to examine your device closely and from different angles.

A microscope allows you to determine the type of dirt on your device and its extent. Then you can choose the correct cleaning procedure and later to examine the results of cleaning. With a microscope you can also determine if your optical device is scratched.

Ultrasonic bath

These are typically available from photographic stores or laboratory suppliers.

An ultrasonic bath very gently removes greasy and other stubborn dirt from optical devices.

Only use an ultrasonic bath with isopropyl alcohol, as other solvents can damage or dirty your optical device.

Warm water and liquid soap

Use water only if you are sure that your optical device will not corrode or be damaged. Do not use hot water, as this can lead to mechanical stress that can damage your optical device. Ensure that your liquid soap has no abrasive properties or perfume in it, as these can scratch or damage your optical device. Do not use normal washing-up liquid, as it can leave behind an iridescent film.

Premoistened cleaning wipes

These are tissues that are moistened with isopropyl alcohol.

Polymer film

This is typically available from professional photographic stores or laboratory suppliers.

Polymer film is very gentle on optical surfaces and is particularly good for cleaning extremely sensitive devices such as mirrors.

Infrared sensor card

This is typically available from laboratory suppliers.

With this card you can qualitatively check the uniformity of your emitted laser light, because when the laser light is projected onto the sensor card it becomes visible.

Lens Cleaning Paper

Some lens cleaning papers and cleaning kits available, for example, in photographic stores are not suitable for cleaning fiber optic devices. To be sure, please ask the salesperson or the manufacturer.

Preserving Connectors

Listed below are some hints on how best to keep your connectors in the best possible condition.

Making Connections

Before you make any connection you must ensure that all cables and connectors are clean. If they are dirty, use the appropriate cleaning procedure.

When inserting the ferrule of a patchcord into a connector or an adapter, make sure that the fiber end does not touch the outside of the mating connector or adapter. Otherwise you will rub the fiber end against an unsuitable surface, producing scratches and dirt deposits on the surface of your fiber.

Dust Caps and Shutter Caps

Be careful when replacing dust caps after use. Do not press the bottom of the cap onto the fiber as any dust in the cap can scratch or dirty your fiber surface.

When you have finished cleaning, put the dust cap back on, or close the shutter cap if the equipment is not going to be used immediately.

Keep the caps on the equipment always when it is not in use.

All of Agilent Technologies's lightwave instruments and accessories are shipped with either laser shutter caps or dust caps. If you need additional or replacement dust caps, contact your nearest Agilent Technologies Sales/Service Office.

Immersion Oil and Other Index Matching Compounds

Where it is possible, do not use immersion oil or other index matching compounds with your device. They are liable to impair and dirty the surface of the device. In addition, the characteristics of your device can be changed and your measurement results affected.

Cleaning Instrument Housings

Use a dry and very soft cotton tissue to clean the instrument housing and the keypad. Do not open the instruments as there is a danger of electric shock, or electrostatic discharge. Opening the instrument can cause damage to sensitive components, and in addition your warranty will be voided.

Cleaning Procedures

If you are unsure about the correct cleaning procedure for your device or if you are unsure whether the procedure given here is suitable for your device, check with the manufacturer or sales distributor, or try the procedure on a dummy or test device first.

Cleaning Cable Connectors

Cleaning connectors is difficult as the core diameter of a singlemode fiber is only about 9 μ m. This generally means you cannot see streaks or scratches on the surface. To be certain of the condition of the surface of your connector and to check it after cleaning, you need a microscope.

In the case of scratches, or of dust that has been burnt onto the surface of the connector, you may have no option but to polish the connector. This depends on the degree of dirtiness, or the depth of the scratches. This is a difficult procedure and should only be performed by skilled personal, and as a last resort as it wears out your connector.

WARNING

Never look into the end of an optical cable that is connected to an active source.

To assess the projection of the emitted light beam you can use an infrared sensor card. Hold the card approximately 5 cm from the output of the connector. The invisible emitted light is project onto the card and becomes visible as a small circular spot.

Preferred Procedure

- 1 Clean the connector by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 2 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the connector:

- 1 Moisten a new cotton-swab with isopropyl alcohol.
- 2 Clean the connector by rubbing the cotton-swab over the surface using a small circular movement.
- 3 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 4 Blow away any remaining lint with compressed air.

An Alternative Procedure

The better, more gentle, but more expensive cleaning procedure is to use an ultrasonic bath with isopropyl alcohol.

- 1 Hold the tip of the connector in the bath for at least three minutes.
- 2 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 3 Blow away any remaining lint with compressed air.

Cleaning Connector Adapters

CAUTION

Some adapters have an anti-reflection coating on the back to reduce back reflection. This coating is extremely sensitive to solvents and mechanical abrasion. Extra care is needed when cleaning these adapters.

Preferred Procedure

- 1 Clean the adapter by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 2 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the adapter:

- 1 Moisten a new cotton-swab with isopropyl alcohol.
- 2 Clean the adapter by rubbing the cotton-swab over the surface using a small circular movement.
- 3 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 4 Blow away any remaining lint with compressed air.

Cleaning Connector Interfaces

CAUTION

Be careful when using pipe-cleaners, as the core and the bristles of the pipecleaner are hard and can damage the interface.

Do not use pipe-cleaners on optical head adapters, as the hard core of normal pipe cleaners can damage the bottom of an adapter.

Preferred Procedure

- 1 Clean the interface by pushing and pulling a new, dry pipe-cleaner into the opening. Rotate the pipe-cleaner slowly as you do this.
- 2 Then clean the interface by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 3 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the interface:

- 1 Moisten a new pipe-cleaner with isopropyl alcohol.
- 2 Clean the interface by pushing and pulling the pipe-cleaner into the opening. Rotate the pipe-cleaner slowly as you do this.
- 3 Moisten a new cotton-swab with isopropyl alcohol.
- 4 Clean the interface by rubbing the cotton-swab over the surface using a small circular movement.
- 5 Using a new, dry pipe-cleaner, and a new, dry cotton-swab remove the alcohol, any dissolved sediment and dust.
- 6 Blow away any remaining lint with compressed air.

Cleaning Bare Fiber Adapters

Bare fiber adapters are difficult to clean. Protect from dust unless they are in use.

CAUTION

Never use any kind of solvent when cleaning a bare fiber adapter as solvents can damage the foam inside some adapters.

They can deposit dissolved dirt in the groove, which can then dirty the surface of an inserted fiber.

Preferred Procedure

1 Blow away any dust or dirt with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the adapter:

CAUTION

Be careful when using pipe-cleaners, as the core and the bristles of the pipecleaner are hard and can damage the adapter.

1 Clean the adapter by pushing and pulling a new, dry pipe-cleaner into the opening. Rotate the pipe-cleaner slowly as you do this.

- 2 Clean the adapter by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 3 Blow away any remaining lint with compressed air.

Cleaning Bare Fiber Ends

Bare fiber ends are often used for splices or, together with other optical components, to create a parallel beam. The end of a fiber can often be scratched. You make a new cleave. To do this:

- 1 Strip off the cladding.
- 2 Take a new soft-tissue and moisten it with isopropyl alcohol.
- 3 Carefully clean the bare fiber with this tissue.
- 4 Make your cleave and immediately insert the fiber into your bare fiber adapter in order to protect the surface from dirt.

Cleaning Lenses

Some lenses have special coatings that are sensitive to solvents, grease, liquid and mechanical abrasion. Take extra care when cleaning lenses with these coatings.

Lens assemblies consisting of several lenses are not normally sealed. Therefore, use as little alcohol as possible, as it can get between the lenses and in doing so can change the properties of projection.

Preferred Procedure

- 1 Clean the lens by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 2 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the lens:

- 1 Moisten a new cotton-swab with isopropyl alcohol.
- 2 Clean the lens by rubbing the cotton-swab over the surface using a small circular movement.
- 3 Using a new, dry cotton-swab remove the alcohol, any dissolved sediment and dust
- 4 Blow away any remaining lint with compressed air.

Cleaning Large Area Lenses and Mirrors

CAUTION

Some mirrors, as those from a monochromator, are very soft and sensitive. Therefore, never touch them and do not use cleaning tools such as compressed air or polymer film.

Some lenses have special coatings that are sensitive to solvents, grease, liquid and mechanical abrasion. Take extra care when cleaning lenses with these coatings. Lens assemblies consisting of several lenses are not normally sealed. Therefore, use as little liquid as possible, as it can get between the lenses and in doing so can change the properties of projection.

Preferred Procedure

1 Blow away any dust or dirt with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the lens:

CAUTION

Only use water if you are sure that your device does not corrode.

Do not use hot water as this can lead to mechanical stress, which can damage your device.

Make sure that your liquid soap has no abrasive properties or perfume in it, because they can scratch and damage your device.

Do not use normal washing-up liquid as sometimes an iridescent film remains.

- 1 Moisten the lens or the mirror with water.
- 2 Put a little liquid soap on the surface and gently spread the liquid over the whole area.
- 3 Wash off the emulsion with water, being careful to remove it all, as any remaining streaks can impair measurement accuracy.
- 4 Take a new, dry soft-tissue and remove the water, by rubbing gently over the surface using a small circular movement.
- 5 Blow away remaining lint with compressed air.

Alternative Procedure A

To clean lenses that are extremely sensitive to mechanical stress or pressure you can also use an optical clean polymer film. This procedure is time-consuming, but you avoid scratching or destroying the surface.

- 1 Put the film on the surface and wait at least 30 minutes to make sure that the film has had enough time to dry.
- 2 Remove the film and any dirt with special adhesive tapes.

Alternative Procedure B

If your lens is sensitive to water then:

- 1 Moisten the lens or the mirror with isopropyl alcohol.
- 2 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 3 Blow away remaining lint with compressed air.

Cleaning Fixed Connector Interfaces

Generally, avoid cleaning this kind of interface, because it is difficult to remove any used alcohol or lint from the input of the optical block. Keep the dust caps on the interfaces unless it is in use.

If there is dust on the interface, try cleaning it using compressed air.

If there is fluid or greasy dirt on the interface then contact Agilent Technologies, so that trained personnel can open the instrument and do the cleaning. Never open the instrument to clean the optical block yourself, because the optical components can be easily scratched or misaligned.

Cleaning Optical Glass Plates

Some instruments, for example, the optical heads from Agilent Technologies have an optical glass plate to protect the sensor. Clean this glass plate in the same way as optical lenses (see "Cleaning Lenses" on page 64).

Cleaning Physical Contact Interfaces

Remove any connector interfaces from the optical output of the instrument before you start the cleaning procedure.

Cleaning interfaces is difficult as the core diameter of a singlemode fiber is only about 9 μ m. This generally means you cannot see streaks or scratches on the surface. To be certain of the degree of pollution on the surface of your interface and to check whether it has been removed after cleaning, you need a microscope.

WARNING

Never look into an optical output, because this can seriously damage your eye sight.

To assess the projection of the emitted light beam you can use an infrared sensor card. Hold the card approximately 5 cm from the interface. The invisible emitted light is project onto the card and becomes visible as a small circular spot.

Preferred Procedure

- 1 Clean the interface by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 2 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the interface:

- 1 Moisten a new cotton-swab with isopropyl alcohol.
- 2 Clean the interface by rubbing the cotton-swab over the surface using a small circular movement.
- 3 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 4 Blow away any remaining lint with compressed air.

Cleaning Recessed Lens Interfaces

Preferred Procedure

- 1 Blow away any dust or dirt with compressed air. If this is not sufficient, then
- 2 Clean the interface by rubbing a new, dry cotton-swab over the surface using a small circular movement.
- 3 Blow away any remaining lint with compressed air.

Procedure for Stubborn Dirt

Use this procedure particularly when there is greasy dirt on the interface, and using the procedure for light dirt is not sufficient. Using isopropyl alcohol should be your last choice for recessed lens interfaces because of the difficulty of cleaning out any dirt that is washed to the edge of the interface:

- 1 Moisten a new cotton-swab with isopropyl alcohol.
- 2 Clean the interface by rubbing the cotton-swab over the surface using a small circular movement.
- 3 Take a new, dry soft-tissue and remove the alcohol, dissolved sediment and dust, by rubbing gently over the surface using a small circular movement.
- 4 Blow away any remaining lint with compressed air.

Cleaning Fragile Optical Devices

Some optical devices, such as the Agilent 81000BR Reference Reflector, which has a gold plated surface, are very sensitive to mechanical stress or pressure. Do

not use cotton-swabs, soft-tissues or other mechanical cleaning tools, as these can scratch or destroy the surface.

Preferred Procedure

1 Blow away any dust or dirt with compressed air.

Procedure for Stubborn Dirt

To clean devices that are extremely sensitive to mechanical stress or pressure you can also use an optical clean polymer film. This procedure is time-consuming, but you avoid scratching or destroying the surface.

- 1 Put the film on the surface and wait at least 30 minutes to make sure that the film has had enough time to dry.
- 2 Remove the film and any dirt with special adhesive tapes.

Alternative Procedure

For these types of optical devices you can often use an ultrasonic bath with isopropyl alcohol. Only use the ultrasonic bath if you are sure that it won't cause any damage anything to the device.

- 1 Put the device into the bath for at least three minutes.
- 2 Blow away any remaining liquid with compressed air.

If there are any streaks or drying stains on the surface, repeat the cleaning procedure.

Cleaning Metal Filters or Attenuator Gratings

This kind of device is extremely fragile. A misalignment of the grating leads to inaccurate measurements. Never touch the surface of the metal filter or attenuator grating. Be very careful when using or cleaning these devices. Do not use cotton-swabs or soft-tissues, as there is the danger that you cannot remove the lint and that the device will be destroyed by becoming mechanically distorted.

Preferred Procedure

1 Use compressed air at a distance and with low pressure to remove any dust or lint.

Procedure for Stubborn Dirt

Do not use an ultrasonic bath as this can damage your device.

Use this procedure particularly when there is greasy dirt on the device:

- 1 Put the optical device into a bath of isopropyl alcohol, and wait at least 10 minutes.
- 2 Remove the fluid using compressed air at some distance and with low pressure. If there are any streaks or drying stains on the surface, repeat the whole cleaning procedure.

Index

A
Accessories 9
Accuracy Test 25
В
Bare Fiber Adapters 11
C
Cleaning Procedure 56
Connector Interfaces 11
L
Linearity Test 27
N
Noise Test 33
0
Optional features 11
P
Performance Tests 21
Agilent 81632A 39
Agilent 81633A 43
Agilent 81634A 47 Agilent 81635A 51
Power Sensor module
Performance tests 22
R
Relative Uncertainty due to Interference 36
Relative Uncertainty due to Polarization 34
Return Loss Test 33
S
Specifications 13