

P/N: MR01

Copyright

© 2015, FLIR Systems, Inc.

All rights reserved worldwide. Names and marks appearing herein are either registered trademarks or trademarks of FLIR Systems and/or its subsidiaries. All other trademarks, trade names or company names referenced herein are used for identification only and are the property of their respective owners.

Document identity

Publ. No.: MR01

Release:

Commit: 26727

Language:

Modified: 2015-06-12

Formatted: 2015-10-17

Website

<http://www.flir.com>

Customer support

<http://support.flir.com>

Disclaimer

Specifications subject to change without further notice. Camera models and accessories subject to regional market considerations. License procedures may apply. Products described herein may be subject to US Export Regulations. Please refer to exportquestions@flir.com with any questions.



Part number	MR01
Part description	Replaceable T/RH Probe for MR77
Replacement temperature/relative humidity probe for the FLIR MR77 moisture meter:	
<ul style="list-style-type: none"> • Metallic screw on connection. • Field replaceable. • Factory calibrated. • Protective cap. 	
Specifications	
Temperature range	-28 to +77°C (-18 to +170°F)
Temperature accuracy	±2°C (3.6°F)
Relative humidity range/accuracy at 20–30°C (68–86°F)	0–10 ±3 %, 10–90 ± 2.5%, 90–99 ±3%
Meter data	
Suitable main unit	MR77
Warranty	1 year
Meter physical data	
Weight:	19.8 g (0.04 lb.)
Dimensions (H × W × L)	2.5 cm × 2.5 cm × 4.4 cm (1" × 1" × 1.75")
Material	Plastic and metal
Color	Black
Shipping information	
Packaging type	Clear plastic bag
Packaging contents	MR01, protective cap enclosure
Packaging dimensions (H × W × L)	6.03 cm × 2.54 cm × 8.89 cm (2.375" × 1" × 3.5")



Replaceable T/RH Probe for MR77

P/N: MR01

© 2015, FLIR Systems, Inc.

#MR01; r. /26727;

Shipping information	
Packaging weight	19.8 g (0.04 lb.)
EAN-13	0793950370018
UPC-12	793950370018
Country of origin	China
Tariff code	9030908822

Technical support	
Website	http://support.flir.com
E-mail	TMsupport@flir.com
Phone	855-499-3662
Repairs	repair@flir.com