



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB331

Issue Date: 11-30-2012

Effective: SN: 05951212011683

Product Description:

Improvement of face plate/receptacle connection on FX-951

Part No:

FX951-66,FX951-66/P,B2973,B3256,B2982

Specification:

Part Changes		
Part Desc.	Old Part No.	New Part No.
Front Panel	B2973	B3732
Button Set	B2982	
Temp Ctrl PCB	B3256	



Comment:

The Hakko FX-951 has been changed internally to improve the connection strength at the face plate where the FM-2027 Connector plugs into the station receptacle. The change required a new design of the face plate, receptacle, and PCB. As a result of this change, the three parts are now combined with the button set into a single assembly.

The assembly is backward compatible with older Hakko FX-951 units that have serial numbers before the effective serial number listed on this bulletin.

There is no change to the performance or operating specifications of the product as a result of this change. This change does not affect the connection of the FM-2027 Connector.

Existing inventory of old part numbers will be used for repair of older units exclusively until exhausted at which time the new part number assembly will be used. All other requests should be for the new part number assembly effective immediately.

For more information, visit us online at www.HakkoUSA.com or call us at 1-800-88-HAKKO (42556).