Fluke Temperature accessories

Turn your digital multimeter into a thermometer



Other temperature accessories

80TK Thermocouple Module

- Converts type K thermocouple signals into mV output
- Connects to DMM via standard banana plugs
- · Switch selectable °C or °F
- Range: -50 °C to 1000 °C (-58°F to 1832°F)
- Includes 80PK-1 probe

80T-150UA Universal Solid State **Temperature Probe**

- · For measurement of air, surface and non-corrosive materials
- Measurement range: -50 °C to 150 °C (-58 °F to 302 °F)
- Output: 1 mV/°C or 1 mV/°F (switch selectable)
- Connects to DMM via standard banana


80PK-8, 80PK-10, Pipe Clamp **Temperature Probes**

Type K thermo-

- couples clamp securely onto pipes for fast temperature and superheat measurements
- Durable ribbon sensors
- 1 m (39 in) lead
- Measure from -29 °C to 149 °C
- 80PK-8 for 6.4 mm to 34.9 mm (0.25 in to 1.375 in)
- 80PK-10 for 32 mm to 64 mm (1.25 in to

Thermocouple Plug Kits

A kit of ten mini-plug connectors. One each of the following: Type J (black) Type K (yellow) Type T (blue)



A kit of seven mini-plug connectors. Type J (black), two

Type K (yellow), two Type E (purple), one Type T (blue), one Type R/S (green), one



80PK-18. **Pipe Clamp** Temperature **Probe Kit**

- Includes both 80PK-8 and 80PK-10 Type K clamps
- Provides full range of pipe measurement
- · Includes soft carrying case to conveniently keep both clamps handy for any situation

80CK-M and 80CJ-M Type K and J Male **Mini-Connectors**

- Isothermal screw terminal for K or J wire
- Suitable for up to 20 gauge thermocouple
- Color coded to industry standards (K-yellow, J-black)
- Two per package

80PJ-EXT, 80PK-EXT, 80PT-EXT

Thermocouple Wire Extension Kits

For extending and repairing type J, K or T thermocouple wires.

- Kit includes 3 m (9 ft) of thermocouple wire and 1 pair of male/female mini-connectors
- Maximum continuous exposure temperature: 260°C (500°F)
- 80PK-EXT is compatible with type K thermometers; 80PJ-EXT is designed for type J thermometers, and 80PT-EXT is designed for type T thermometers



Process tools accessories

- · Li-ion rechargeable battery; nominal 7.2 volt, 4400 mA hr
- Use with 750 Series Calibrators

BP7235

- NiMH rechargeable battery; nominal 7.2 volt, 3500 mA hr
- Use in 700 and 740 Series Calibrators

700LTP-1 Low Pressure Test Pump

Hand operated pressure pump designed to generate either vacuum to -13 psi/ -.90 bar or pressures to 100 psi/6.9 bar. Ideal for low pressure applications requiring accurate low pressure testing.

700ILF In-line Filter

The Fluke 700ILF can be used to isolate the calibrator from incidental contact with fluids. Particularly useful with the 718 calibrator to help keep moisture or oils from contaminating the on-board pump.

700PTP-1 Pneumatic **Test Pump**

The Fluke 700PTP is a handheld pressure pump designed to generate either vacuum to -11.6 psi/-0.8 bar or pressure to 600 psi/40 bar.

700HTP-2 Hydraulic **Test Pump**

The Fluke 700HTP is designed to generate pressures up to 10,000 psi/700 bar. Use the Fluke 700PRV adjustable relief valves to limit pressures from 1360 psi to 5450 psi.

700HTH-1 Hydraulic **Test Hose** The 700HTH is

a 10,000 psi, 700 bar test hose that connects to a calibration unit under test from a Fluke 700HTP hydraulic test pump.

FNPT

Fluke 700-IV **Current Shunt**

Conversion factor: 10 mV = 1 mAAccuracy (% of input, one-year): 0.025 % Input current: 0 mA to 55 mA Input resistance: 250 Ω nominal Output resistance: 10Ω nominal Accuracy specification applies from +18 °C and 28 °C to 50 °C Maximum input voltage: 30 V dc





