



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB377

Issue Date: 5-5-2016

Available: 5-5-2016

Product Description:

Replacement Heater Pipe for HAKKO FR-810

Part No:

B5045

Specification:

Removed one of the two bosses



Previous Specification	New Specification

Comments:

The HAKKO B5045 pipe for the HAKKO FR-810 hot air rework stations has changed to accommodate older generations of nozzles. The new pipe will work with the HAKKO N51 nozzles made for the HAKKO FR-810 and will no longer require the B5058 adaptor for nozzles from the HAKKO FR-801, FR-802, and FR-803B hot air units.

For more information please visit us at www.HakkoUSA.com

AHP14 Rev 2012-11

28920 Avenue Williams · Valencia · California 91355

Tel 661.294.0090 · Fax 661.294.0096 · www.HakkoUSA.com